

Douglas County Surveyor's Record of
Government Corners Renewed

T. 20 S. T. S. R. 7 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

33

$\frac{1}{4}$ Corner to Sections 32 and 33.
Found - Haines' "T" Iron at corner - Also real old, rotten squared stake,
could be original. - REN. #20

48" Fir N.73°E. (instead of S.17°E) 15.2 ft. Fir is down & badly
rotted, good scribing visible " $\frac{1}{4}$ SBT" - Would be facing cor. if tree was standing.
Remains of Cedar stump N.72°W. 6.6 ft. Not enough left to find scribing.
New BT's: 42" R. Cedar N.71°E. 23.0 ft. Mkd: $\frac{1}{4}$ S33 CS BT.
17" Hemlock N.78°W. 37.4 ft. Mkd: $\frac{1}{4}$ S32 CS BT.

Note - Orig. call on top of spur (was in error by approx. 10 chs. 51)
DID NOT SET BRASS CAP.

34

Section Corner to Sections 28 - 29 - 32 - 33.

Found - Haines' "T" Iron driven alongside remnants of corner tree,
which is down & partly decayed. - REN. #19

Live Hemlock, now 15", S.31°E. 3.3 ft. Has been previously
opened. Good scribing "W S33" visible on old face.

Maple, uprooted & down, N.70°E. 34.3 ft., shows good scar.

Hemlock, uprooted & down, N.58°W. 15.8 ft. buried under pile
of logs & tops. Cedar to S.W. not found.

33" D. Fir scribed by Haines, in wood, S.66°E. 27.0 ft.

40" D. Fir N.35°W. 50.7 ft. (instead of 27.7 ft.) bark scribed
DID NOT SET BRASS CAP by Haines.

New BT: 42" R. Cedar S.52°W. 40.8 ft. Mkd: T20S R7W S32 CS BT.

Corner lies approx. 50 ft. West of graveled logging road.

9/8/66 - CORNER O.K. - MISSED BY OXBOW FIRE - C.S. 54/22

35

Witness Corner $\frac{1}{4}$ Corner to Sections 21 and 28.

Found - Haines' "T" Iron about 3 ft. downhill from corner (in slide
area on upper side of logging road) - REN. #17

Dead Fir Snag N.2°W. 18.5 ft. Had been previously opened.

Good scribing "4S" plainly visible on old face.

Both Haines' BT's. alive & in good condition.

12" D. Fir S.69°W. 79.6 ft. scribing still visible. 57 & 75

18" D. Fir N.57 $\frac{1}{2}$ °E. 292.5 ft. scribing still visible.

I move Haines' "T" Iron back to true corner position.

Set - Wit. Cor. Iron Pipe with Brass Cap Mkd: County Surveyor's Office, 1962

T20S R7W W.C. $\frac{1}{4}$ S21 60 ft. E. to Cor. 60' W. of $\frac{1}{4}$ Corner.

Haines' S.W. BT., 13" D. Fir scribed " $\frac{1}{4}$ S28BT" bears S.25°W. 32.8 ft.

New BT's: 15" R. Cedar N.30°W. 18.8 ft. Mkd: W.C. $\frac{1}{4}$ S21 CS BT.

Corner lies on very steep East Slope. $\frac{1}{4}$ Corner approx. 40 ft. W. of
centerline of logging road.

36

Corner to Sections 32 and 33 only.

Found - Haines' "T" Iron & Cap, not recorded.

15" Fir Snag S.27°W. 12.5 ft., scribing visible "T21S R7W S5 BT".

No trace of N.E. or N.W. BT's.

DO NOT SET BRASS CAP

New BT's: 6" Hemlock N.57 $\frac{1}{2}$ °E. 45.7 ft. Mkd: S33 CS BT.

8" Hemlock N.58°W. 24.6 ft. Mkd: T20S R7W S32 CS BT.

Corner lies on steep N.W. slope approx. 500 ft. South of Road.

37

Corner to Sections 5 and 4 only, T21S-R7W.

Found - 70" Fir Snag S.37°W. 13.2 ft., faint bark scribing visible.

36" Cedar, uprooted, down & dead) S.34°E. 32.3 ft. Cut open &
found good scribing in "W".

No trace of Maple to N. E.

30" Hemlock N.24°W. 13.0 ft., old scribing visible in previously
opened scar "BT S33T20" looks like Orig., but no record.

24" Red Cedar N.84°W. 21.1 ft., recent scribing found.

Set - Brass Cap at Cor. Mkd: County Surveyor's T21S R7W
Office, 1962 S5/S4

New BT's: 5" D. Fir S.79°E. 19.3 ft. Mkd: S4 CS BT.

Rescribe 70" Fir Snag S.37°W. 13.2 ft. (in bark) "T21SR7W S5CSBT"

Haines' "T" Iron bears N.17°W. 4.0 ft. Corner is on level ground approx.
75 ft. East of Smith River Road.

Milo E. Godfrey
Vernon Tracey & C. Putnam
May 16, 1962
C. S. File No. 49/89

Milo E. Godfrey, Deputy
Mike Stone
October 17, 1962
C. S. File No. 49/89