

Douglas County Surveyor's Record of
Government Corners Renewed

T. 20 S. T. S. R. 7 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

74

Vernon "Ray" Tracy
Jack Heritage & V. Perron
C. S. File No. 54/22

1/4 Corner to Sections 20 and 21.
Found - C.S. Brass Cap in place, see Ren. #63.
Orig. BT's, as recorded in Ren. #63 in 1966. Renewal BT's. both gone due to logging. Steel fence post has been set by brass cap. Since there are no trees for several hundred feet, we mark stumps, as follows:
50" D. Fir Stump N.76°E. 25.2 ft. mkd. "1/4 S21 CS BT".
(Set 5/8"x 30" I. R. 20" deep in center of stump.)
50" Fir Stump N.76°W. 54.7 ft. mkd: "1/4 S20 CS BT".
(Set 5/8"x 30" I.R. 20" deep in center of stump.)
This corner lies approx. 80 ft. N. of creek, course S.60°W. & 150 ft. N. of log access road parallel to creek.

FD. OK 3/85
L. ROBERTS
M99-7
CS 63/18
5/6/68

V.R. Tracy
Ed. Monrean
C.S. File 54/22

Witness Corner to 1/4 Corner to Sections 21 and 28.
Found - No trace of Brass Cap set in 1962 by M.E.G., Ren. #35.
18", now 26" D. Fir, N.57 1/2°E. 292.5 ft., alive & O.K. Ren. #17.
14" D. Fir Stump S.25°W. 32.8 ft., Haines Button, Ren. #17.
30" D. Fir Stump N. 3° E. 7.0 ft., all scribe visible, good condition, Ren. #57.
At point 60 ft. west of true corner:
Set - Brass Cap Mkd: "County Surveyor's Office, 1972 T 20 S R 7 W
Wit. Cor. to 1/4 Cor. S 21 60 ft. E. to Corner"
S 28
No New BT's. Mkd.,
No trees within limits. True Corner not set as it falls in slide
FD. OK 10/95 BY EDWARDS; M122-71 area above road. 6/23/72

75

Gary Langlitz
P Earle
C 56/43
s /74

S 1/4 Corner for Sec. 34 only.
Found - "X" chiseled on large sandstone boulder.
1" x 1" T-iron bears north 1.1 ft. Ren. No. 50
Rec. 28", now 30" D. Fir bears N.77°W., 99.5 ft.
Show well-healed scar.
New BT - 30" D. Fir bears N.19°W., 99.6 ft. scribed "1/4 S34 CS BT"
2/5/74

76

Gary L. Langlitz County Surveyors Office

P. Earle
C.S. 56/43
Feb. 11, 1974

Sec. Corner for Secs. 4 and 3 only, T21-7.
Found - 1" x 1" T-iron with copper washer mkd. Wilford N. Haines 239, Survey Point Drain, Oregon. See Ren. No. 23 T21-7
12" red cedar, bears S.55°W., 31.3 ft. scribed "T21S R7W S4 CC BT" in open blaze.
14" Fir, now dead bears S.51°E., 22.8 ft. (rec. S.46°E., 22.8 ft.) with visible blaze.
OBT to the NW is now a shattered stump with blazed portion missing
Set - Brass cap alongside T-iron mkd. COUNTY SURVEYORS OFFICE 1974
T 20 S S4 | S3 CC T21S R7W
New BT's - No suitable trees near, I mark
14" Red cedar stump, bears S.11°E., 26.8 ft. scribed "CS BT"
Note - Corner lies at lower edge of old cat road. 2/12/74

77

Section Cor. for Secs. 33 and 34 only.
Found - Orig. 36" now 38" D. Fir with scribing "20S R7W S33" showing on previously opened blaze. Ren. No. 40
A tagged fir to the NE does not fit proper bearing & distance.
Set - Brass cap at record bearing & distance from OBT mkd.:
COUNTY SURVEYORS OFFICE 1974
T 20 S R 7 W S 33 | S 34 T21S

78

from which
Orig 36" now 38" D. Fir bears N.57°W N.32°W., 9.9 ft.
A 1" x 1" T-iron with copper washer attached mkd. Wilford N. Haines 239 Survey Point Drain, Oregon, bears S.25 1/2°W., 3.6 ft.
New BT's - An 8" Red cedar bears N.65 1/2°E., 11.8 ft. scribed "T20S R7W S34 CS BT"
A 6" Red cedar bears N.47°W., 22.0 ft. scribed "T20S R7W S33 CS BT"