

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 20 T. S. R 7 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

83

Daniel Baker
For: International
Paper Co.
Nov 1983
M - 44

Section corner for Secs. 16, 17, 20 and 21
Found - 1966 Douglas County brass cap properly mkd. Ren. #55
52" fir snag, N.12°E., 27.5 ft.
10" fir stub, N.15°E., 9.3 ft. ("BT"vis.)
New BT - 36" fir stump, S.38°E., 38.3 ft., set this survey.

11/10/83

84

Section corner for Sec. 31; and Sec. 6 only of T.21-7. (SW cor. S.31)
Found - Std. GLO 2 1/2" I.D. iron pipe projecting 8" above ground with
a 3 1/4" brass cap properly marked.
12" fir, down with blaze bears East 60 lks.
27" fir, down with blaze burnt out, N.38°E., 55 lks.
31" rotten fir stump bears N.55°E., 28.45 ft. burnt bad with
tree alongside.
New BTs - 8" D. fir bears N.43°W. 5.5 ft. scribed T20S R8W S BT.
6" D. fir bears N.39°E., 27.5 ft. scribed T20S R7W S31 BT.
Set - 5/8" x 30" rebar with yellow plastic 1 1/4" dia. cap makred
"Branch Eng. L.S. 1137" flush with the ground.

85

1/4 Corner for Sec. 31 only. (south)
Found - 70" fir laying 30 ft. down hill from root hole. Tree has burnt
blaze with no visible scribing.
Set - At record S.30°W., 23.1 ft. from root hole, I Set a 2 1/2" I.D.
alum. pipe protruding 6" above ground with 3 1/4" alum.
cap marked "T20S R7W 1/4 S31 1983 PLS 1137".
New BTs - 7" alder bears N.27°E., 11.1 ft. bark scribed 1/4 S 31 BT.
8" alder bears S.26°W., 34.3 ft. scribed 1/4 S6 BT.

86

Section corner for Secs. 31 and 32 only.
Found - T-Iron with cap marked "Survey marker Haines Drain, OR Ren. #21
36" fir stump bears N.35°E., 9.0 ft. with no scribing.
Burnt out stump with no visible markings bears S.81°W., 27.7 ft.
Set - Std. I.P. Co. 2 1/2" I.D. alum. pipe protruding 6" above ground
with 3 1/4" alum. pipe marked "T20S R7W S31 S32 T21S R7W S6
1983 PLS 1137.
New BT - 36" D. fir bears S.16°W., 54.7 ft. scribed T21S R7W S6 BT.
Set - 1/2" x 6 ft. rebar 30" in ground with BT sign attached bears
N.63°W., 10.8 ft.
5/8" x 30" rebar with 1 1/4" yellow plastic cap marked "Branch
Eng. LS 1137" in top of BT stump bears N.35°E., 9.0 ft.

87

Section corner for Secs. 5 and 6 only of T.21-7.
Found - "T"-Iron, no record, with cap marked "Survey Marker W. Haines
Drain, OR"
Set - At the same point and with the "T" iron inside, set 2 1/2" alum.
pipe protruding 6" above ground with std. I.P. Co. 3 1/4"
alum. cap marked T20S R7W S32 S6 T21S R7W 1983 PLS 1137.
New BTs - 16" D. fir bears N.3°E., 33.7 ft. scribed T20S R7W S32 BT.
17" chinquapin bears S.32°W., 5.8 ft. scribed T21S R7W S6 BT.
18" D. fir bears S.25°E., 43.6 ft. scribed T21S R7W S5 BT.

88

Standard Section Corner between Sections 32 & 33, of T. 19-7.
Found - 2" I.P. w/GLO B.C. "1949".
BTs - 23" fir stump bears S.17°W., 27.3-ft. (S.15°W., 41-lks) Orig. BT.
55" fir stump bears N.29°W., 10.5-ft. (N.26°W., 14-lks) Orig. BT.
New BTs - 8" fir bears N.53°W., 25.4-ft. scribed: T19S R7W S32 BT.
7" fir bears N.2°W., 12.4-ft. scribed: T19S R7W S32 BT.
No suitable tree in northeast quadrant. 2/84

Donald L. Branch, L.S. 1137
Branch Engineering, Springfield
For: International Paper Co.
November 1983
M 95 - 66

iel W. Baker,
PLS #1978
For: International
Paper Co.
M 96 - 41, &
C.S. 58/289