

Douglas County Surveyor's Record of
Government Corners Renewed

T 20 S T. S. R 8 W R.W.W.M.

KOKE-CHAPMAN CO., EURENE, ORE. 21881

Les Roberts
International Paper Co.
Dec. 30, 1987 M 103 - 63

18

East 1/4 Corner section 12 Only.
Found - A 1954 G.L.O. Brass Cap, bent to the West. Properly stamped.
BT's - A 16" fir stump bears S63°E, 10.2'(scar visible), 1884 BT.
rec. S65°E. 8.6'.
54" fir stump, bears S52°W, 6.2' (no marks). 1954 BT rec.
S52°W, 4.6'.
44" fir stump, bears N51°W, 46.4' (scribe vis.) 1954 BT rec
N51½°W, 46.2'.
New BT - 8" fir bears N14°W, 10.0 ft. (scribed/painted red.)
"R.R." spike in top of 54" fir stump. Stump bears
S3°W, 5.3 ft. from corner.
Set metal fence post , with survey attention sign wired to., beside
cap. Painted all BT's red. Corner lies on West slope about 60'
East of small draw.

North East Corner Section 12.
Found - A 1954 brass cap set loosely in the ground about 15'
down the hill from original position. Re-set brass
cap from found Bt's. Brass cap disturbed by logging activity.
A 30" fir stump bears N50E, 25.1' (no marks)
1884 BT rec. N47°E, 25.1 ft.
52" fir stump bears N 36½°W, 43.0 ft. (scribe vis.)
1954 BT. rec. N36½°W, 42.2 ft.
58" fir snag bears S87½°W, 24.4 ft. (scribe vis.)
1954 BT rec. S87½°W, 24.4 ft.
Set aluminum fence post, with survey attention sign wired to,
beside brass cap, Painted all BT's red. Corner lies on North
slope about 250 ft. South of North Sister Creek.

19

Les Roberts LS 1039
For: ?
May 5, 1989
C.S. 63/85

1/4 Corner for Sections 7 and 18
Found - 1954 GLO brass cap laying on cut-bank of new dirt logging
road. Both 1954 BTs have been destroyed.
Set - Reset 1954 GLO brass cap from M 103-36 traverse points.
Brass cap buried 6" below surface of dirt road. Buried purple
magnetic marker under pipe.
New BTs - 30" hemlock, N.29°E., 88.2 ft. (scribed/painted red)
32" fir, S.50°E., 48.6 ft. (scribed/painted red)
Distances are measured to 6" spike driven into center of tree.
5/5/89

20

Les Roberts LS 1039
For: I.P.
Jan. 1993
M 116 - 53
C.S. 63/149

1/4 Corner for sections 10 & 15.
Found - 1954 GLO brass cap set firmly in the ground.
End.BTs- 60" downed Cedar, S.22°W., 47.0' (scar vis.) Rec. S.22°W., 46.9'.
(1954 BT)
66" Cedar, N.56°E., 24.6' (scar vis.) Rec. N.57°E., 23.8'.
(1954 BT)
New BT- 14" Fir, S.23°E., 35.2' scribed and painted red.
Note - Corner lies on N.W. slope about 30' east on North Sister Creek.
1/18/93

21

1/4 Corner for sections 14 & 15.
Found - 1954 GLO brass cap set firmly in the ground, also found 6'
steel fence post beside brass cap.
No 1954 bearing trees found.
New BTs- 8" Fir, S.66°W., 48.6'. Scribed and painted red.
10" Fir, S.33°E., 8.4'. Scribed and painted red.
Note - Corner lies on S.E. slope about 50' west of creek.
Creek bears north-south.
1/21/93

22