

Douglas County Surveyor's Record of
Government Corners Renewed

T. 20 S. T. S. R. 9 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97001

Vernon "Ray" Tracy
Jack Heritage & V. Perron
July, 1968
C. S. File No. 53/66

(continued)

Set - Brass Cap at Cor. Mkd: County Surveyor's T 20 S R9W $\frac{S 6}{S 7}$ R10W
(Dep. old Pipe Alongside) Office, 1968
Note - This corner lies approx. 600 ft. W. of ridge, course N. & S. and
on N. side of ravine 15 ft. inlogged off unit.

7/10/68

Witness Cor. to $\frac{1}{4}$ Corner to Sections 17 and 16. 11
Found - GLO Brass Cap, nearly out of ground due to slide & Co. Surv. BT.,
as recorded in Ren. #6.
6" Hemlock N. 82° E. 11.1 ft., down & dead.
8" Hemlock S. 23 $\frac{1}{2}$ ° E. 41.3 ft., scribe visible, we add "WC".
At True Corner Set 5/8" x 30" I.R. & move Brass Cap S. 30 ft. to
point for witness corner & add "30 ft. N. to Cor." to Brass Cap.
New BT's: 6" Hemlock N. 84° E. 28.1 ft. mkd. "W C $\frac{1}{4}$ S16 BT".
8" Hemlock S. 67° E. 21.2 ft. mkd. "W C $\frac{1}{4}$ S16 CS BT".
1953 Fir Stump of BT about to slide out. Witness Corner now lies in
brush 10 ft. E. of top of cut bank on E. side of road about 50' above road.
7/10/68

S 197 '68

$\frac{1}{4}$ Corner Sections 26 & 25 12
Found - 1954 Cad. Brass cap out of place as determined from BT's as follows:
Orig. now 62" Fir N. 83° E 29.7' Sawed Stump--burned no scribe visible.
Orig. now 50" Fir N. 51° W. 13.7 " Sawed stump--1954 Rescribe visible.
1954 8" Hemlock S. 76° E. 7.3 " Now shattered stump. Scribe visible.
S.W. Hemlock down & out of place/
Reset - Brass cap at Cor. point & set steel fence post along side.
Mkd. new B.T.
12" Cedar N. 79° W. 98.5 " Mkd. S26 CS BT
No trees close to East. This cor. lies 30 ft. East of cold water Creek
Access Road. 5-15-69

RE-RENEWED, SEE CORNER NO. #52

Vernon "Ray" Tracy
Jack Heritage & Vernon Perron
6-19-69
C. S. File No. 53/66

Section Corner to Sections 4 & 3, T 19S, 20S R 9W 13
Found - 1921 G.L.O. I.P. & Brass Cap Broken--No trace O.B.T.S. We
measure from Sec. Cor. 33 & 34 of T 19S R 9W to locate pipe. Record
Dist. is 335.3. We make it 332.0 Ft. on bearing of N. 86° E. S 8.86° W
at Cor. point in place of old pipe
Set - 1" I.P. & Brass Cap Mkd: County Surveyors T 19S R 9W T 20S R 9W
Office, 1969 C. C. S4/ S3
& Mkd. new B.T.
48" D. Fir (stump) S. 27° E 45.6 Ft. Mkd. CC S3 CS BT
No other trees or stumps available. This cor. lies on very steep
S. W. Slope 6-19-69

Section Corner To Sections 33 & 34 Only 14
Found - 1921 G.L.O. Brass Cap on broken concrete filled I.P.
in place. T 19S S33/S34 R9W
30" Now 36" Fir N. 84° W. 23.8 Ft. Record S4
N. 31° W --Dead shows good scar. No trace of N. E.
B. T. Found.
Set - 1" I.P. & Brass Cap Mkd: County Surveyors T 19S
Office, 1969 S 33 / 34 R 9W
New B. T.
10" Maple N. 45° W 32.6 Ft. Mkd. T 19S R9W S33 CS Bt
No other trees close to N. E. This Cor. lies on very steep Southerly
slope on E. W. Cutting line. Clear cut to South. June 19, 1969

John M. Powell
Frank Jones & W. Penley
C.S. File No. 53/66

$\frac{1}{4}$ Corner to Sec. 31, T20-9W and Sec. 6, T21-9W. 15
Found - GLO Brass Cap, properly set in 1953. Cap in Fence Row North 203.3 ft.
25" Cedar, now 36", S. 86° W. 91.7 ft.
1 $\frac{1}{2}$ " Iron Pipe in bed rock bears N. 86° E. 351.8 ft. - No trace N.E. BT.
New BT: 19" Cedar N. 73° E. 255.2 ft. mkd: " $\frac{1}{4}$ S31 CS BT".
Reblzd. & Rescrbd: 36" Cedar S. 86° W. 91.7 ft. mkd: " $\frac{1}{4}$ S6 CS BT".
9/19/69

FOCK
ES WARD
2/23 1116-61