

Douglas County Surveyor's Record of
Government Corners Renewed

T. 20 S. T. S. R. 9 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21887

Section Corner to $\begin{matrix} T\ 20\ S \\ S\ 36\ S\ 31 \\ R10W\ S\ 1\ R9W \end{matrix}$

16

Found - GLO Brass Cap properly marked in 1951
16", now 27" Cedar, N.66 $\frac{1}{2}$ °E. 17.2 ft., shows good scar. -REN.#1
16", now 19" Cedar, N.57°W. 34.3 ft., scribe visible, "S".
New BT: 24" Maple S.24°E. 29.8 ft. mkd: "T21S R10W S1 CS BT".
Also tagged other Bearing Trees.

FD 9/1/83
R. 5510175
M 95-12

John M. Powell
F. Jones & W. Penley
Sept. 1969 C. S. File No. 53/66

~~Section Corner to Sections 1 and 12 only, T21-9W
Found - GLO Brass Cap properly mkd. in 1919 T21S R10W S 1 TWP 1919 S 12 RANGE~~

WLONG
RANGE

~~New BT: 17" D. Fir N.59 $\frac{1}{2}$ °E. 40.0 ft. mkd: T21S R9W S 6 CS BT.
Note - I renewed this corner because of new to be built. S. W. Tree
is on top of ridge and will probably be taken out. Sta. 72+30.~~

Section Corner to Secs. 31 & 32, T20-9 and Secs 5 & 6, T21-9W. 17
Found - Unmarked Pipe Cap & also GLO Brass Cap marked in 1953,
34" Cedar, now stob, S.85 $\frac{1}{2}$ °W. 58.1 ft., scribe visible.
33" D. Fir, now stump, S.83°E. 77.2 ft.
11", now 13" Maple, N.2°E. 103.0 ft., partial scribe visible, 67

New BT's: 14" Maple N. 7° E. 22.3 ft. mkd: T20S R9W S32 CS BT.
12" Maple N.46°W. 22.6 ft. mkd: T20S R9W S31 CS BT.
15" D. Fir S. 23°E. 23.8 ft. mkd: T21S R9W S 5 CS BT.
16" Maple S.50°W. 21.7 ft. mkd: T21S R9W S 6 CS BT.
This corner is in E - W Fence Line.

RE-RENEWED
CORNER
MAY 1970

9/29/69

North $\frac{1}{4}$ Corner Section 4 only, T20-9W. 18
Found Corner established in 1921 by Collier, which is:
a cement filled pipe set in 1921 by G.L.O., from which:
40" Fir bears S. 2° W. 12.4 ft., evidence of face.
Set - 2"x 30" Iron Pipe with Brass Cap Mkd: T 20 S R 9 W

Set pipe alongside corner.
Set fence post with signs \pm 5 ft. S., facing E. 1970 650
April '70

Tom O. McCullough
For. U.S. Forest Serv.
April 1970
C.S. 55/148
John M. Powell
J. Heritage
May 1971
C.S. File No. 53/66

South $\frac{1}{4}$ Corner Section 34 only, T20-9W 19
Found - GLO Brass Cap, date 1953, properly marked.
20" D. Fir, now stump, N.49 $\frac{1}{2}$ °E. 33.0 ft. Shows good scar.
Set - Steel fence post along side Brass Cap.
New BT's: 14" Hemlock S.85°W. 69.7 ft. scribed C.S. BT
30" Cedar S.44 $\frac{1}{2}$ °E. 77.4 ft. scribed C.S. BT.
To the north of this corner is clear cut.
Northwest BT buried by logging show.

MARCH 71

Center 1/4 Corner Section 12. 20
Set - 5/8" Iron Rod.
Location Sign on 30" Cedar which bears N.60°E. 12.5 feet.
7/8/72

Hintz, Richard
J.
M 46-57
For: B.L.M.
Jan 1972

$\frac{1}{4}$ Corner for Section 10 only. (West $\frac{1}{4}$) 21
Found - Badly rusted iron pipe with concrete core firmly set in
ground, brass cap missing.
Orig. 9" now 18" Alder bears N.80°E., 5.9 ft. well healed and
in good condition/
Orig. 8" Alder, now 16", bears S.22°E., 25.1 ft. well healed
and in good condition.

Set - Brass cap alongside remains of original monument mkd.:
COUNTY SURVEYORS T 20 S R 9 W
OFFICE $\frac{1}{4}$
1974 S 10
2/13/74

Gary Langlit
P. Earle
C.S. 56/43
2/13/74

200 25