

Douglas County Surveyor's Record of
Government Corners Renewed

T. 20 T. S. 9 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

22

1/4 Corner for Secs. 17 and 20
 Found - U.S. GLO Brass cap, 1953, properly marked, with a steel fence post alongside.
 BT's - 60" now 54" D. Fir stump bears S.76° W., 27.7 ft., scribing partially visible at edge of lower blaze. Note (This stump has had the bark removed, been treated with a liquid preservative and covered with sheet metal.)
 The NE BT, marked in 1953, has fallen and slid downhill out of position. The main portion of the tree has been removed in recent logging. Scribing is partially visible near base of root wad.
 New Bearing Object - A boat spike, driven in the top of a 58" D. Fir stump, bears N.64° W., 33.1 ft.
 Note - This corner lies on steep slope near the bottom of and approx. 150' north of a ravine in a recently logged area. 3/15/74

Gary Langlitz
 Surveyors office
 P. E. Le
 C.S. 6/49
 March 15, 1974

Gary L Langlitz, Surveyors office
 John Nordling
 Feb. 2, 1975
 C.S. 57/17

23

1/4 Corner for 3 and 4.
 Found - Badly rusted 1" I.P. with brass cap attached. 1921 GLO cap properly marked.
 From which:
 An orig. 40" now 52" D. Fir bears S.35° E., 23.1 ft. alive and well healed.
 An orig. 40" now 52" D. Fir bears N.84° W., 21.8 ft. alive and well healed.
 Note: The brass cap and uppermost 4 in. of the orig. monument were inadvertently broken off during the setting of a new monument at the corner. The remaining portion of the orig. monument, a badly rusted 1" I.P. filled with concrete was placed alongside the new monument.
 Set - At the corner point we set a 1"x30" I.P with brass cap attached mkd:
 COUNTY SURVEYOR T 20 S
 OFFICE S 4 S 3
 1975 1/4
 R9W 2/4/75

L.E. Monrean
 P.L. E
 D.L.S.
 C.S. 57/39
 11/4/75

24

1/4 Corner for 31 and 30
 Found-U.S. GLO Brass cap, 1953, properly marked;
 BT's -A fir, 54", diam. bears N25° W., 34.3 ft. shows good blaze. Other bearing trees not found.
 Renewal;
 50" Diam. fir bears S21 1/2° W., 81.4 ft. scribed "1/4 S31 CS BT"
 Note: Corner lies approx. N82° E 3/8 mile from last landing on road #20-10-29.1. Corner is approx 180 ft. east of ridge running S5° E., & approx 60 ft lower than ridge top. 11/4/75

File 2193
 by Ward
 M 116-61

25

Witness Corner to
 Closing Corner Sec. 1 T21-10 Sec. 6 ~~T21-10~~ only
 Found-A Cedar 40" now 52" in Dia. bears S42° E, 44.5 ft. (rec 46.2 ft) blazed .
 A Cedar 45" now 55" in Dia. bears N38° W, 21.8 ft, scribed "WCC T21S R9&10 W"
 Maple bearing tree not found, bearing and distance recorded fall in Large growth of Maples in slide area.
 Set Brass Cap at W.C. to C C stamped
 T20S R9W
 CC S31
 COUNTY SURVEYOR'S OFFICE
 1975
 S1 S6
 R 10 WR 9W
 T21 S
 Note: Corner lies near so. Bank of Smith River, Nearly directly across from fence running north & south at east end of Fawn Creek Park 11/5/75

175 (11/5/75)

26

L.E. Monrean
 P.L. Earle
 J.H. Cook
 1/20/76
 C.S. 59/2

Closing Corner to Sec. 4 & 5 REN # 13
 Found-38 (Rec. 48) inch dia. fir stump. Stump is rotted, partial scribing visible "CC S 3 BT" Stump bears S27° E., 45.6 ft.
 Brass cap not found T 19S R9W
 Set-Brass cap at closing corner stamped S 34
 S 4 S 3
 C.C.
 T20S R9W
 Set spike in 43" Dia. Fir stump. Spike bears S39° W, 118.4 ft, spike stamped "B.O.". There are no suitable trees for scribing in the southerly quadrants
 Corner falls in a steep slide area. Mag. Dec. 1/20/76

+ + 3-77