

Douglas County Surveyor's Record of
Government Corners Renewed

T 20 T. S. R 9 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21981

L.E. Monrean, Deputy, Doug. Co. Surveyors Office
Randall Smith - Stephen Flause
March 22, 1984
C.S. 62/16

51

1/4 Corner for Sections 23 and 26.
Found - 1954 U.S. GLO brass cap on 1" I.P., protruding 6" above ground
Cap properly marked.
A 63" fir, now a 54" stump 3 ft. high with burnt single blaze and
partial scribing visible, bears N.71°W., 16.0 ft. (1954
record, N.68 1/2°W., 15.8 ft.)
36" fir, now a 30" stump 4 ft. high with burnt single blaze and
scribing visible "4S 26 BT" bears S.15°E., 22.6 ft. (1954 rec.
S.16°E., 23.1 ft.)
New BTs - 5" D. fir double blazed and scribed "1/4 S23 CS BT" bears
N.8 1/2°E., 21.6 ft.
4" D. fir double blazed and scribed "1/4 S26 CS BT" bears
S.79 1/2°W., 23.3 ft.
Note: See also L.D. Roberts LS #1039, survey, M 96 - 20 for condition
report.
Corner lies on steep west slope of a north-south ridge covered with 10-15
year old growth.

2/84
52

1/4 Corner for Secs. 25 and 26
Found - 1954 U.S. GLO properly marked brass cap on 1" I.P. protruding
6" above ground.
36" fir, now a 48" stump 5 ft. high with a burnt single blaze,
bears N.49°W., 16.1 ft. (Rec. N.51°W., 13.2 ft.) Orig. BT.
42" fir now a 57" stump 5 ft. high with a burnt single blaze
bears N.83°E., 30.6 ft. (Rec. 29.7 ft.) Orig. BT.
8" hemlock now a 1 ft. high shattered stump with rotted out blaze
bears S.73 1/2°E., 7.6 ft. (1954 BT.)
A 17" cedar now a 17" diam. 2 ft. high stump with a well headed
double blaze bears N.79°W., 98.5 ft. Ren. #12
New BTs - 5" D. fir double blazed & scribed "1/4 S26 CS BT" bears S.5 °W.,
18.3 ft.
6" D. fir double blazed and scribed "1/4 S25 CS BT" bears
N.30°E., 34.7 ft.
Note: See also L.D. Roberts LS #1039 survey, M96 - 20, for condition
report.
This corner lies along gentle southeast slope covered with 10-15 year old
reproduction.

3/84

1/4 Corner for Sections 35 and 36
No evidence found of brass cap or BTs set by GLO in 1954. Corner
falls in steep and narrow creek bottom. Creek has been torn up by old
logging.
Set - 2" x 36" alum. pipe and cap by proportionate measure. Buried
purple magnetic marker under cap. Cap stamped T20S R9W 1/4 Cor
S35 + S36 1984 P.L.S. 1039.
Set - 2" x 36" alum. pipe and cap for witness corner. W.C. bears
N.2°01'02" E., 30.0 ft. from 1/4 cor. Buried purple mag-
netic marker under 36" alum. pipe. Cap stamped "T20S
R9W W.C. S35 + S36 1984 P.L.S. 1039".
New BT - 8" alder, N.54°E., 20.0 ft. Bark scribed/painted brass washer
Set metal fence post beside brass cap. Wired survey monument sign to
fence post. Corner lies 8 ft. south of 2 ft. creek in steep narrow canyon.

53

South 1/4 Corner for Sec. 35 only.
CORNER REPORT ONLY.
Found - 1954 GLO brass cap, properly marked, set firmly in ground.
1954 BTs gone.
17" maple stump, N.58°W., 26.6 ft. (no marks) (1966 rec. N.58 1/4°
W., 25.7 ft.
63" fir stump bears N.62°E., 78.5 ft. (scribe vis.) 1966 BT. Rec.
N.62°E., 79.2 ft.
42" cedar snag, S.35°W., 25.6 ft. (no marks) International Paper
Location tag nail to snag. No Record.
Set - Metal fence post beside brass cap. Wired survey attention sign
to fence post.
Corner lies on top of narrow ridge. Ridge runs N.45°E. and S.45°W. Corner
is in stand of 15-20 year old reproduction.

RE-RENEWED CORNER NO. # 56

Les Roberts PLS #1039
For: International Paper Company
March, 1984
M 96 - 26 - C.S. 58/280