

**Douglas County Surveyor's Record of
Government Corners Renewed**

T. 20 T. S. R 9 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 91881

Robert Ward Jr
L S 1091
For: Siuslaw Nat Forest
June 1991
M 113 - 37 A & B

Section Corner for Sections 31 & 32 only. 64
A
Fnd. - 1921 G L O. brass cap attached to a badly rusted iron pipe.
17" Fir bears N.21°E., 20 4 ft. (healed face)
Set - U.S F S. alum corner monument stamped "T19S R9W S31 S32 T20S R9W S6
L.S. 1091 1991"
New BTs-23" Fir bears S34°E., 29.1 ft. (scribed "T20S R9W S6 BT")
15" Maple bears S.16°W., 7.9 ft. (bark scribed "T20S R9WS6 BT")
25" maple bears N 73°W , 26.1 ft (bark scribed "T19S R9WS31 BT")
8/12/91

Robert Ward, Jr
For: International
Paper Co.
2/93
M 116 - 61

C 1/4 Corner Section 31 65
A
Set- 3 1/4" Dia. Aluminum cap on a 3/4" x 36" RLS 1091
aluminum rod. Marked: C1/4 * S 31
New BTs-31" Hemlock S46°E 44.9'. 1993
32" Hemlock N2°W 23.1'.
32" Hemlock N32°W 50.7'.
44" Hemlock N86°W 21.4'.
Note- All BT's blazed and scribed "C 1/4 S 31 BT" 2/93

1/4 Corner for Sections 31 and 32. 66
A
Fnd: 2 1/2" BLM Brass cap with the following accessories,
33" Fir N58°W 14.8'.
21" fir stump N29°E 5.7'.
New BTs-30" Fir N5°E , 35'. Blazed and scribed "1/4 S32 BT"
2/93

Section corner for Sections 31 & 32 T. 20 S. R. 9 W Ren. No. 17 67A
and Sections 5 & 6 T. 21 S. R. 9 W.
Fnd- 2 1/2 BLM Brass cap with the following accessories:
17" Maple N 8°E, 22.1'
11" Maple N 42°W, 22.4'
17" Maple S 47°W, 21.1'
Fir BT is uprooted. (Ren. No. 17)
New BT- 20" Alder S 30°E 30.8'. Barkscribed "T21S R9W S5 BT" 2/93

Les Roberts
For: International
Paper Co.
March 1993
CS 63/149
M 116 - 60

West 1/4 Corner Section 30, T. 20 S. R 8 W. only. 68
Found- 1950 G.L.O. Brass cap set firmly in the ground and marked "W.C. S 1/2
S30". True corner bears N 1° 27'E, 7.26'. At true corner I find
a 14" rotted fir stub, no marks visible.
New Accessories -
8" Fir, N 76°E, 5.4' (Scribed "W.C. 1/2 S B.T.")
8" Fir, S 03°W, 9.1' (Scribed "W.C. 1/2 S B.T.")
72" aluminum post, with land survey monument sign attached to,
beside brass cap. Painted all bearing trees red.
Note - Also found 2 bearing trees for true 1/2 corner.
14" Fir Stump, S 85°E, 14.5' (No marks), 1883 BT. Rec. S 85 1/2°E 13.9'
18" Fir Stump, N 33°E, 23.9' (Scar vis.), 1950 BT. Rec. N 33°E
25.7'. 3/93

East 1/4 Corner Section 25 only 69
Found - 22" Fir, N 85°W, 15.8' (Scar vis), 1954 BT. Record N 85 3/4°W,
15.8'.
28" Fir, S 12°W, 6.6' (Scar Vis), 1954 BT. Record S 13°W, 6.6
See also Vol. 43 Pg 16710 for B.L.M. renewal.
Set - 72" aluminum post, with land monument survey sign atted to,
beside brass cap.
Note - Corner lies on West slope about 50' South of the N.W. corner
of Section 30. 3/93

N.W. Corner Section 30 T. 20 S. R. 8 W. only 70
Found - 1950 G.L.O. Brass Cap set firmly in the ground.
20" Fir, S 58°E, 16.5' (scar vis.), 1950 BT. Record S 58°E, 16.5'.
39" Fir, N 47°E, 19.8' (scar vis.), 1950 BT. Record N 47 1/2°E, 19.8'.
See also Vol. 43, Pg 16711 for B.L.M. Renewal.
Set - 72" aluminum post, with land monument survey sign attached to, beside
brass cap. Painted all bearing trees red.
Note - Corner lies on West slope about 200' South of creek. Creek flows
West. 3/93