

Douglas County Surveyor's Record of
Government Corners Renewed

20 T. S. 10 R. W. W. M.

Eppstein
County Surveyor
J. A. Dailey
Claude Dailey
Emery Dailey
Witness
July 24, 1926
Ren. Cor. Vol. 1
Pg. 7

CORNER OF SECTION 32-33-5-4.
Iron pipe with Copper Cap Standard U. S. corner Marked thus:
P. 203.
R. 10W.
S. 32E 3.33
S. 51S. 4
E. 213.
New Bearings Trees:
14" Alder S. 88° W. 8.6 links
15" Fir W. 45° 30' W. 44 links
12" Fir N. 30 E. 36 links
12" Alder S. 5 W. 6.0 links

RE-RENEWED, SEE CORNER NO. #71

1

Jan. 25, 1929
Frank Cole
Will Dailey
T. I. Eppstein
County Surveyor
Witness
Ren. Cor. Vol. 1
Pg. 7

COR. SECS. 31-36-1-6 TOWNSHIP COR. ON T. 20 & 21 S: R. 10 & 11 W.
Set corner from old witness tree in Sec. 31 Maple, setting
x 4" Galv. Iron pipe, Marked new trees as follows: 25
Fir 4" Brs. S. 77° 15' E. 65 links;
Maple 10" Brs. S. 27W. 17 links;
Maple 20" Brs. N. 14° W. 23 links.
No trees near in Sec. 31.

RE-RENEWED, SEE CORNER NO. #25

2

July 12, 1929
T. Berberso
W. Knefke
E. A. J. Eppstein
County Surveyor
Witness
Ren. Cor. Vol. 1
Pg. 7

COR. BET. SECS. 5-6
Set 4" x 36" Fir limb for corner from Maple Witness Tree
Marked new R. 7.
18" Maple N. 21.8 E. 8 ft.
28" Fir S. 13E. 25 ft.

RE-RENEWED, SEE CORNER NO. #44

3

Arthur Poyer D. C. S.
Jno. Wroe. Witness
Henry Wroe
Dec. 12, 1929
Ren. Cor. Vol. 1
Pg. 7
C.S. 16/32

CORNER BET. SECS. 17 & 20.
Set 3" pipe for corner on true line & midway between the
section corner 1/2 mile to East & West. from which
A Fir 36" dia, bears N. 83 1/2° E. 261.5 feet on bank of N. Fork
Smith-river.
Barked blazed & scribed 1/2 S. 17 E. 203. R. 10W. S. S. E. T.
Alder 24" dia., bears S. 32° W. 100.5 feet.
Marked 1/2 S. 20 T. 203. R. 10W. S. S. E. T.
About 54' N. of this corner there is a 3" pipe set at the point
that looks like the original corner. from which the stump of
18" Maple Brs. N. 70° E. 15 ft. & the snag 4' high of a 50"
I Maple bears S. 40° W. 10 feet. In 1874 Byars ran the W 1/2
of the line bet. 17 & 20 & set the 1/2 Cor. between 17 & 20
without running the full mile, about 4 yrs. later Thiel continue
tinned running 1/2 mile. W. from Byars corner. This corner above
looks like the corner. The 50" maple shows the round for the
blaze but was burned out inside the blaze, from this corner
is a 3" iron pipe the above B. T. shows as follows:
36" fir S. 81E. 175 ft.
24" Alder S. 46° W. 198 ft.
See letter Feb. 7., 1940, from Jos. A. Gonong.
Dist. Cadastral Engr and notation of opinion by
Dist. Atty. in V. 16, E. 58. Arthur Poyer 2/8/40

RE-RENEWED, SEE CORNER NO. 30

4

Section corner to secs. 19, 20, 29 and 30.
No trace of original corner was found; corner set by double proportionate
measurement.
Set a 4 x 4 post at point for corner,
from which:
32 inch Fir bears N15W 19.5 feet.
16 inch Hem bears N64E 15.5 feet.
24 inch Fir bears S82E 24.0 feet.
32 inch Fir bears S59W 41.5 feet.

RE-RENEWED, SEE CORNER NO. #79

5

Roy C. Gibson
June, 1957
C. S. File No. 42/275.
Ren. Cor. Vol. 1
Pg. 7

Section corner to secs. 20, 21, 28 and 29.
Found original B. T. - bears N34E 75 lks.
Set post at corner,
from which:
20 inch Alder bears S36W 35.4 feet.
14 inch Maple bears N34W 27.4 feet.
42 inch Fir bears N35E 46.4 feet.
12 inch Maple bears S82E 11.7 feet.

RE-RENEWED, SEE CORNER NO. 40

6

5/8/68 - FOUND BUT NOT ENOUGH EVIDENCE
TO RENEW - See C.S. 53/66 V.R.T.

Douglas County Surveyor's Record of
Government Corners Renewed

20 T. S. 10 R. W. W. M.

Section corner to secs. 28, 29, 32 and 33.
No trace of original corner was found. Corner set by double proportional measurement.

At corner point made an X on East face of 4 foot sandstone outcrop,
from which:

- 38 inch Fir bears N45 $\frac{1}{2}$ W 35.8 feet.
- 14 inch Maple bears N88E 48.6 feet.
- 6 inch Fir bears S21W 4.2 feet.

RENEWED, SEE CORNER NO. 39 7

Roy C. Gibson
June, 1957.
C. S. File No. 42/275.

$\frac{1}{4}$ corner to secs. 29 and 32.
No trace of original corner was found. Corner set by proportional measurement.

Set a post,
from which:

- 40 inch Fir bears N17W 37.0 feet.
- 8 inch Maple bears S43E 14.8 feet.

RENEWED, SEE CORNER NO. 33 8

$\frac{1}{4}$ corner to secs. 21 and 28.
No trace of original corner was found. Corner set by proportional measurement.

Set a post,
from which:

- 14 inch Maple bears S76E 7.4 feet.
- 18 inch bears N60W 38.6 feet.

NOT FOUND - FEB. 1970 - V.R.T.
C.S. 53/66
RENEWED, SEE CORNER NO. 41 9

Section Corner common to Secs. 25, 30, 31, & 36. (REGS. 11 & 10) 10

Found - 3 Orig. BT's. as follows:

- A Maple 24" in diam. bears N.29°W. 25.0 ft. (old face at base of tree. New face approx. 4 ft. above the ground line. Has been re-scribed in unrecorded survey.
- A Maple stump 24" in diam. bears S.35°W. 39.6 ft. (remains of tree & old face still visible.)
- A Maple 22" in diam. bears N.45°E. approx. 55.0 ft. (uprooted & down). -

SEE REN #1 T20-11

New BT.: A Fir 60" in diam. bears S.18°W. 70.3 ft. (Scribed) 38

Set 5/8" re-enforcing rod for the corner & Post. Set distances from BT'S. as called for. The orig. bearings did not check. - Cor. Fo. 5/1964 - M 28-19

NOT ABLE TO RENEW - 4/1968 V.R.T. ?
C.S. 53/66

Clifford A. Stephens
For Coos Head Timber Co.
Filed April, 1958
C. S. File No. 42/362
Map File M 10 - 3

$\frac{1}{4}$ Section Corner to Sections 30 & 31. 11

By proportion I set the $\frac{1}{4}$ Corner 2618.88 ft. West of the Northeast corner of Sec. 31. The West $\frac{1}{2}$ of the section receiving 2646.20 ft. to close in on the Range line.

For the $\frac{1}{4}$ Corner I set $\frac{1}{2}$ " Iron Pipe & Post from which:

- A Cedar 8" in diam. bears N.13°W. 14.0 ft.
- A Fir 12" in diam. bears S.34°W. 12.0 ft.

RENEWED, SEE CORNER NO. #111
See also M 99-51 for Cor. FD.

Cl. Corner to Sec. 6, T20-10W. & Sec. 1, T20-11W. 12

Set - Iron Pipe with Brass Cap Mkd: RS239 C.C. Sec. 1, T20S R11W
Sec. 6, T20S R10W

Scribed New BT's: 14" Fir S. 46° E. 34.5 ft.
30" Fir S. 24° W. 65.7 ft.

W. 1/16 to Sec. 6, T20-10W. & Sec. 31, T19-10W. 13

Set - Iron Pipe with Brass Cap Mkd: RS239 S 1/16 S 31 T19-10W
S 6 T20-10W

New BT's: 24" Fir N.12° E. 23.7 ft.
28" Fir S. 76° E. 31.0 ft.

$\frac{1}{4}$ Cor. to Sec. 6, T20-10W. & Sec. 31, T19-10W. 14

Set - Iron Pipe with Brass Cap Mkd: RS 239 $\frac{1}{4}$ S 31 T19S R10W
S 6 T20S R10W

New BT's: 22" Fir South 4.1 ft.) Scribed
24" Fir N. 15° W. 36.5 ft.)

Sec. Cor. - Secs. 5 & 6, T20-10W. & Secs. 31 & 32, T19-10W. 15

Set - Iron Pipe with Brass Cap Mkd: RS239 S 31 S 32 T19S R10W
S 6 S 5

(con't. next page)

Wilford N. Haines
For - U.S.F.S. - U.S. Plywood - Int. Paper
November 1965
Map File M 31 - 6

Douglas County Surveyor's Record of
Government Corners Renewed

T. 20 S. T. S. R. 10 W. R. W. W. M.

HOKE-CHAPMAN CO., EUGENE, ORE. 21881

Wilford N. Haines
For-U.S.F.S.-U.S.Plywood &
International Paper
Nov. 1965
Map File M 31 - 6

(continued)

Scribed New BT's: 40" Fir N. 3° W. 27.0 ft.
14" Fir N. 59° E. 21.5 ft.
30" Fir S. 6° E. 25.5 ft.
40" Fir S. 72° W. 59.6 ft.

West 1/16 Sec. 5, T20-10W. & Sec. 32, T19-10W. 16

Set - Iron Pipe with Brass Cap Mkd: RS239 W 1/16 S 32 T19S R10W
Scribed New BT's: 40" Fir S. 70° W. 19.7 ft. S 5 T20S R10W
18" Fir N. 5° E. 39.8 ft.

1/4 Corner to Sec. 5, T20-10W. & Sec. 32, T19-10W. #118 17

Set - Iron Pipe with Brass Cap Mkd: RS 239 S 32 T19-10W
Scribed New BT's: 33" Fir S. 72° W. 19.3 ft. S 5 T20-10W
28" Fir N. 61° E. 31.3 ft.

Sec. Corner to Sections 7 - 8 - 17 - 18. 18

Found - 5" Fir S. 40° W. 76 lks., now stub about 2 ft. high,
scribed W" BT, plain.

Set - 1" x 1" x 36" T. Iron

There is two unrecorded BT's., both Firs, These scribed trees
here in 1941 when I first visited this corner.

Section Corner to Sections 7 - 8 - 17 - 18. 19

Found - Haines' "T" Iron, see Ren. #18, set at corner from one Orig. BT.
Orig. 5" Fir, now badly decayed stump with "WBT" scribe S.40°W. 50.2 ft.
Unrecorded BT's. as follows:

20" D. Fir Snag S.35°W. 54.0 ft., bark scribed "T20 R10W S17". *Fd. by:*

23" D. Fir Snag S.73°W. 46.3 ft., bark scribed "BT S7 T20S R10W". *HINTZ 4/83*

Set - Brass Cap at Cor. Mkd: County Surveyor's T 20 S R 10 W
(Reset "T" Iron alongside) Office S 7 S 8
1968 S 18 S 17 *SEE M 90-42 #98*

New BT's: 26" Maple N.81°E. 7.0 ft. mkd. T20S R10W S8 CS BT.

24" Maple S.22°E. 57.7 ft. mkd. T20S R10W S17 CS BT.

No other suitable trees available.

This corner lies on steep easterly slope approx. 50 ft. W. of small ravine.

Section Corner to Sections 8 - 9 - 16 - 17. 20

Found - 1951 G.L.O. Brass Cap, properly mkd., out of ground. *Fd. by:*

38", now 40" Fir, alive, N.35 3/4°E. 33.3 ft., healed blaze. *HINTZ 4/83*

18", now 18" Fir, alive, badly injured on blaze sde. S.25°E. 10.6 ft. *M 90-42*

16", now 18" Fir, alive, S.20°W. 8.6 ft., healed blaze.

22" Fir, now stump, N.32°W. 20.8 ft., scribe visible on unhealed blz.

Reset Brass Cap at Corner Point.

New BT's: 9" D. Fir S. 63° E. 20.4 ft. mkd. T20S R10W S16 CS BT.

No other trees available in Sec. 8.

This corner lies on steep southerly slope approx. 60 ft. S. of ridge top.

Section Corner to Sections 29 - 30 - 31 - 32. 21

Found - 1951 G.L.O. Brass Cap, properly mkd., out of ground.

12", now 15" Cedar, alive, S.49°W. 7.9 ft., scribe visible on
nearly healed blaze.

N.W. BT. has slid downhill, now stump. S.E. BT. now stump in
proper position. M. BT. turned out.

Reset Brass Cap at Corner Point.

New BT's: 10" D. Fir North 53.2 ft. mkd. T20S R10W S29 CS BT.

10" Maple S.67°E. 28.8 ft. mkd. T20S R10W S32 CS BT.

No trees available in Sec. 30. This corner lies on very steep southerly slope

Vernon "Ray" Tracy
Jack Heritage & V. Perron
April, 1968
C. S. File No. 53/66

RE-REVIEWED SEE CORNER NO. #118
RE-REVIEWED SEE CORNER NO. #98
MICROFILM TO HERE 10/67
RE-REVIEWED SEE CORNER NO. #98
SEE M 90-42 #98

**Douglas County Surveyor's Record of
Government Corners Renewed**

T. 20-S. T. S. R. 10-W. R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

22

Section Corner: Secs. 19 & 30, T20-10W. and Secs. 24 & 25, T20-11W.
Found - Orig. 40", now 48" Fir, badly decayed stub, N.76°E. 9.2 ft.,
no scribe found.
Orig. 12", now 38" Fir, alive, S.3°E. 69.3 ft., old scar, opened prev.,
about 8" to false face.
Orig. 7", now 34" Fir, alive, S.61½°W. 29.0 ft., opened & find, "T20"
scribe & reverse under 70+ rings.
Orig. 8", now 40" Fir, alive, N.2°W. 70.6 ft. We do not open.
Set - Brass Cap at Cor. Mkd: County Surveyor's R T20S R
Office 11 S 24 S 19 10
1968 W S 25 S 30 W

New BT's: 7" D. Fir S.83°W. 21.7 ft. mkd. T20S R11W S25 CS BT.
12" D. Fir N.29°W. 27.8 ft. mkd. T20S R11W S24 CS BT.
14" Maple N.4°E. 24.6 ft. mkd. T20S R10W S19 CS BT.
14" Maple S.62°E. 26.5 ft. mkd. T20S R10W S30 CS BT.
Corner lies 30 ft. east of spur, sloping North.

FD OK 6/86
D. BAKER
M102-12

23

Section Corner to Sections 16 - 17 - 20 - 21.
Found - 1951 G.L.O. Brass Cap, Gone.
66" Fir, alive, N.52°45'E. 132.0 ft., bark scribe (See C.S.16/58)
Orig. 32" Alder, alive, N.17°W. 26.4 ft., blaze decayed out.
30" Fir N.58½°E. 130.0 ft., alive & good condition.
30" Fir, S.69¼°E. 75.1 ft., alive & good condition.
All other 1951 BT's. down. T20S R10W
Set - Brass Cap at Cor. Mkd: County Surveyor's S 17 S 16
Office, 1968 S 20 S 21

No tree close for new bearing trees.
This corner lies in head of ravine on N.E. slope, very steep & brushy.

FD. by:
HINTZ
APR. 1983
M 90-42

Vernon "Ray" Tracy
Jack Heritage & V. Perron
March & April, 1968
C. S. File No. 53/66

24

Section Corner to Sections 17 - 18 - 19 - 20.
Found - 3/4" I. Pipe & BT's. as follows, recorded C.S.16/58.
17", now 19" Hemlock stump, N.69¼°E. 36.0 ft., scribe visible.
20", now 30" Hemlock stump, S.31°E. 4.2 ft., scribe visible.
All other BT's. down or gone. No trace of originals.
Set - Brass Cap at Cor. Mkd: County Surveyor's T20S R10W
(Deposit old pipe alongside) Office S 18 S 17 #105
1968 S 19 S 20

New BT's: 6" D. Fir S.48°W. 28.4 ft. mkd. T20S R10W S19 CS BT.
4" Hemlock N.48°W. 10.0 ft. mkd. S18 CS BT.
8" Alder N.84°E. 43.6 ft. mkd. T20S R10W S17 CS BT.
No trees suitable to S.E. This corner lies on moderate westerly slope.

FD. by:
HINTZ
4/83
M 90-42

Township Corner: T20S.-T21S.-R.10W.-R.11W.
Found - 3/4" I. Pipe & BT's. as shown in Ren. #2, T20-10W.
20", now 28" Maple, alive, N.14°W. 15.2 ft., shows good scar.
We do not open.
4", now 20" Fir, alive, S.77¼°E. 42.9 ft. faint scar.
Rescribe: "T21S R10W S6 CS BT"
Set - Brass Cap at Cor. Mkd: County Surveyor's T20S 19 S 36 S 31 10
(Deposit old pipe alongside) Office, 1968 T21S W S 1 S 6 W

New BT: 15" D. Fir N.80°E. 83.6 ft. mkd. T20S R10W S31 CS BT.
This corner lies on very steep south slope approx. 300 ft. N. of
Smith River Road.

FD OK PER STUNTZNER
M109-13 OCT 1989 25

1/4 Corner to Sections 18 and 19.
Found - Orig. 12", now 26" Maple, alive, N.45°E. 26.4 ft., open
& shows scribe on badly decayed blaze.
Rescribe: "1/4 S18 CS BT". T20S R10W
Set - Brass Cap at Cor. Mkd: County Surveyor's 1/4 S 18
Office, 1968 S 19

New BT: 30" Maple S.10°E. 11.9 ft. mkd. "1/4 S19 CS BT".
Note - No trace of Corner Tree or other Orig. BT's.
This corner lies on S.W. slope about 150 ft. E. of
Johnson Creek.

26

RE-RENEWED SEE CORNER NO. #102

Douglas County Surveyor's Record of
Government Corners Renewed

T. 20 S. T. S. R. 10 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Section Corner to Sections 13 and 24, T20-11W. 27
 Found - Unrecorded 1 1/4" I. Pipe at corner point.
 Orig. 36", now 48" Fir, alive, S. 81° W. 26.0 ft., shows "T S24", bark scribe in poor condition. Rescribe: "T20S R11W S24 CS BT".
 Orig. 15", now 30" Fir, alive, N. 74° W. 8.6 ft., shows good scar. Dont open. No trace original corner tree or other orig. BT's.
 Set - Brass Cap at Cor. Mkd: County Surveyor's R T 20 S R
 (Reset Old Pipe Office 11W S 13 10W
 Alongside) 1968 S 24
 New BT: 15" Cedar N. 56° W. 15.6 ft. mkd: T20S R11W S13 CS BT.
 Note - This corner lies on steep E. slope about 100 ft. above creek, course N. and 99.3 ft. N. 3 1/2° E. of CC. Secs. 18 & 19, T20-10W.

RE-RENEWED, SEE CORNER NO # 63

Closing Corner to Sections 18 and 19, T20-10W. 28
 Found - 1/2" I. Pipe on N-S line, not at point for C.C., unrecorded.
 (I.P. bears N. 85° E. 6.2 ft.)
 Orig. 6", now 18" Maple, alive, N. 85° E. 39.6 ft., Open & find frag. scribe on decayed axe blaze. Rescribe: "CC S18 CS BT".
 Orig. 6", now 14" Chittam, now decayed stub, hollow center, S. 76° E. 26.4 ft., no scribe. No trace other Orig. BT.
 Set - Brass Cap at C. Cor. Mkd: County Surveyor's R T 20 S R
 Office 11 S 18 10
 1968 W S 19 W
 New BT: 28" Maple S. 21° E. 41.7 ft. mkd. T20S R10W S19 CC CS BT.
 Note - This corner lies 99.3 ft. S. 3 1/2° W. of Sec. Cor. 13 & 24, T20-11W. Creek course N. about 125 ft. E. of Cl. Corner.
 4/12/68

FD. OK 4/18/7
R. HINTZ
M 104-9

East 1/4 Corner to Section 1, T20S-R10W. 29
 Found - 1" I.P. filled with cement at corner point with BrassCap (1951) broken off.
 Orig. 36", now 40" Fir, alive, S. 66° W. 16.5 ft., shows good scar. We do not open.
 6" Yew S. 86 1/2° W. 38.9 ft., alive, scribe visible on partially healed blaze. (1951 BT)
 Set - Brass Cap at Cor. Mkd: County Surveyor's R T 20 S R
 (Deposit old pipe Office 10 1/4 S 1 9
 alongside) 1968 W 1/4 S 1 W
 Note - This corner lies on very steep N. slope approx. 50 ft. south of small creek, course N.W.

1/4 Corner to Sections 17 and 20. 30
 Found - BT's. as recorded in Ren. #4, C.S. File 16/58 by Boyer.
 36", now 48" Fir, alive, S. 81° E. 175.0 ft., scribed "1/4 S17 T20S R10W CS BT"
 No trace any corner pipes or other bearing trees.
 At orig. cor. point, See letters by Boyer & Ganong, Feb. 1940, C.S. 16/58.
 Set - Brass Cap at Cor. Mkd: County Surveyor's T 20 S R 10 W
 (Set 6 ft. steel fence Office 1/4 S 17
 post alongside B.C.) 1968 S 20
 New BT: 9" Ash N. 30° E. 354.0 ft. mkd. "1/4 S17 CS BT".
 No other trees available on west side of river.
 Note - Boyer's BT. is on east side of river. Also point of Boyer's BT proportioned 1/4 corner bears S. 57° W. 103.3 ft. Corner falls in E. G. Dunn's field approx. 90 ft. west of N. Fork of Smith River.
 1993-0072A/B
4-1-93

Fd. by:
HINTZ 1983
Apr. 1983
M 90-42

North 1/4 Corner to Section 2 only, T21-10W. 31
 Found - No trace of Brass Cap. - 1951 BT's. as follows:
 60", now 60" D. Fir, S. 6° E. 63.4 ft., alive, blaze pitched over & healing
 20", now 26" Hemlock, alive, S. 47° W. 36.3 ft., scrb. mks. vis. on heald. blz
 Set - Brass Cap at Cor. Mkd: County Surveyor's T 20 S R10W 1/4
 (6' steel fence post Office, 1968 T 21 S R10W 1/4 S 2
 alongside Brass Cap)
 Note - The 1/4 corner of Sec. 35, T20-10W bears N. 87 3/4° W. 13.9ft.
 This corner lies on edge of new logging road, course N. 30° W. - S. 30° E.
 May 8, 1968

Vernon "Ray" Tracy
Jack Heritage & V. Perron
April, 1968
C. S. File No. 53/66

C. S.
File
No.
54/1

Douglas County Surveyor's Record of
Government Corners Renewed

T. 20 S. T. S. R. 10 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

South $\frac{1}{4}$ Corner to Section 35 only, T20-10W. 32
 Found - No trace of Brass Cap, but 1951 BT's., as follows:
 20", now 24" Hemlock, alive, N. $45\frac{1}{4}^\circ$ E. 45.5 ft., scribe
 marks visible on nearly healed blaze.
 24", now 26" Hemlock, alive, N. $54\frac{1}{4}^\circ$ W. 92.4 ft., scribe
 marks visible on partially healed blaze.
 Set - Brass Cap at Cor. Mkd: County Surveyor's T20S R10W $\frac{1}{4}$ S 35
 (Set 6' Steel fence post Office, 1968 T21S R10W $\frac{1}{4}$ S 35
 alongside B.C.)
 Note - The $\frac{1}{4}$ corner of Sec. 2, T21-10W bears S. $87\frac{3}{4}^\circ$ E. 13.9 ft.
 and 14 ft. west of new logging road, course N. 30° W. - S. 30° E.
5/8/68

C. S.
File
No.
54/1

$\frac{1}{4}$ Corner to Sections 29 and 32, T21-10W. 33
 Found - 3"x3"x48" squared Post & BT's. as Rec. in Ren. #8 by
 Roy Gibson in 1957 by proportional measurement.
 40", now 42" Fir Sawed Stump, N. 17° W. 37.0 ft. scribed.
 8", now 10" Maple, alive, leaning badly, S. 43° E. 14.8 ft.,
 scribe visible.
 Set - Brass Cap at Gibson's Corner Point Mkd: T 20 S R 10 W
 County Surveyor's $\frac{1}{4}$ S 29
 Office, 1968 $\frac{1}{4}$ S 32
 New BT's: 6" Hemlock N. 18° W. 19.2 ft. mkd. $\frac{1}{4}$ S29 CS BT.
 4" Hemlock S. 9° E. 30.8 ft. mkd. $\frac{1}{4}$ S32 CS BT.
 Note - This corner lies on spur sloping N.W. approx. 300 ft. E. of creek,
 course N. W. in dense brush.

Vernon "Ray" Tracy
Jack Heritage & V. Perron
May, 1968
C. S. File No. 53/66

Closing Corner for Sections 7 and 18, T20-10W. 34
 Found - 24"x20"x10" S. S. mkd: "CC +" & 2 notches on N. edge and
 4 notches on south edge, firmly set
 and in place.
 Orig. 18", now 46" Fir, alive, S. 10° E. 10.6 ft., shows good scar.
 We Rescribe: "T20S R10W S18 CC CS BT".
 Orig. 10", now 28" Fir, alive, N. 36° W. 29.0 ft., shows faint scar.
 We Rescribe: "CC CS BT".
 Set - Brass Cap in place of rock & Mkd: County R T 20 S R
 Surveyors 11 CC $\frac{S}{S}$ $\frac{7}{18}$ 10
 Office, '68 W W
 New BT: 8" Hemlock N. 45° E. 39.2 ft. mkd. T20S R10W S 7 CC CS BT.
 Note - This corner lies on top of spur ridge, sloping N., approx.
 495 ft. south of corner of secs. 12 & 13, T20-11W., see below.

★ SEE
C.S. 62/19
4/2/84

Witness Cor. to Sections 12 and 13, T20-11W. 35
 Found - Orig. 18", now 26" Fir Corner Tree, now dead Snag, leaning
 badly with very poor bark scribe.
 Orig. 30", now 60" Fir, alive, S. $71\frac{1}{2}^\circ$ E. 9.9 ft., shows fair
 bark scribing.
 Orig. 30", now 64" Cedar, alive, S. $34\frac{1}{2}^\circ$ W. 41.6 ft., shows faint
 scar. We do not open.
 Orig. 12", now 16" Cedar, 5' high stub, N. 82° W. 14.5 ft., blazes
 rotted out, no scribing found.
 Set - Wit. Corner 10 ft. west of True Corner mkd:
 County Surveyor's R T 20 S R
 Office Wit. Cor. 10' 11 S 12 | 10
 1968 E. to Cor. W S 13 | W
 New BT: 40" Cedar N. 26° W. 18.5 ft. mkd. WC T20S R11W S12 CS BT.
 64" Cedar S. $29\frac{1}{2}^\circ$ W. 35.9 ft. mkd. W.C. T20S R11W S13 CS BT.
 (Orig. BT.)
 Note - This corner lies on steep northerly slope, approx. 100 ft. E.
 & 150 ft. S. of creek, course N.E. & approx. 495 ft. N. of
 of C.C. Sections 7 & 18, T20-10W, see above.

Douglas County Surveyor's Record of
Government Corners Renewed

T. 20 S. T. S. R. 10 W. R.W.W.M.

KOIKE-CHAPMAN CO., EUGENE, ORE. 21681

John M. Powell & Crew
C.S. File 53/66

Tom O. McCullough
For: U.S. Forest Service
Feb., 1970
C.S. File No. 55/142

Tom O. McCullough
For: U. S. Forest Service
April, 1970
C.S. File No. 55/148

SEPT. 68

50-9/83
R. Spurr
4/95-12

Closing Corner to Sections 6 and 7, T20-9W. 36
Found - Concrete filled I. Pipe but Brass Cap broken off.
Orig. 30", now 34" Cedar, alive, N. 37° E. 34.3 ft., shows good scar.
We Rescribe "T20S R9W S6 CC CS BT".
Orig. 40" Cedar, now 42" sawed stump, S. 82½° E. 61.4 ft., scribe
visible on unhealed blaze.
No other trees to SE or suitable trees close NE or W.
Corner Pipe was under logging debris which we remove to set Brass Cap:
Set - Brass Cap at Cor. Mkd: County Surveyor's T20S R9W CC $\begin{matrix} S & 6 \\ S & 7 \end{matrix}$ R10W
(Dep. old pipe alongside) Office, 1968
Note - This corner lies about 600' W. of ridge, course N & S and
on N. side of ravine 15 ft. in logged off unit.

7/10/68

Section Corner Thus: $\begin{matrix} T & 20 & S \\ R10W & \begin{matrix} S & 36 \\ S & 1 \end{matrix} & \begin{matrix} S & 31 \\ S & 7 \end{matrix} & R9W & T21S \end{matrix}$

Found - GLO Brass Cap properly marked in 1951.
16", now 27" Cedar, N. 66½° E. 17.2 ft., shows good scar. *REN. #1-T20-9*
16", now 19" Cedar, N. 57° W. 34.3 ft., scribe visible "S".
New BT: 24" Maple S. 24° E. 29.8 ft. mkd: "T21S R10W=S 1 CS BT".
Also tagged other bearing trees. 9/30/69

Section Corner Common to Secs. 30 & 31, T20-10W and 38
Secs. 25 & 36, T20-11W. *Refer to Ren. #112*
Found - 1½" Pipe from which: Refer to Ren. #10.
24" Maple Stump bears N. 32° W. 25.0 ft. (Orig.)
Face chopped out, evidence of old chop marks & face, with tag.
50" Fir bears S. 18° W. 20.3 ft., scribed S36 CS, with tag.
Set - 2"x30" Iron Pipe with Brass cap mkd: $\begin{matrix} R & T & 20 & S & R \\ 11 & 25 & 30 & 10 \\ W & 36 & 31 & W \end{matrix}$
from which: $\begin{matrix} 4" & Chittewood & bears & N. 72^\circ E. & 27.6 & ft. & 1970 \\ & scribed & R10 & S31 & BT, & with & tag. & 650 \\ 6" & Cedar & bears & N. 20^\circ W. & 47.3 & ft. & scribed \\ & R11 & S25 & BT, & with & tag. \end{matrix}$
Set 2 fence posts with signs + 5 ft. west facing south.
+ 5 ft. north facing east.

Section Corner to Sections 28 - 29 - 32 - 33. 39
Corner established in 1878, re-established by Gibson in June, 1957,
by double proportional measurements, See *Ren. #7*.
Found - an "X" 8" high on east face of 4' sandstone outcrop,
scribed by Gibson in 1957, from which:
44" Fir bears N. 45½° W. 35.8 ft., visible scribing, with tag.
14" Maple bears N. 88° E. 48.6 ft., scribing visible, with tag.
6" Fir bears S. 21° W. 4.2 ft., face healed, with tag, windthrown.
Set - 2"x30" Iron Pipe with Brass Cap Mkd: $\begin{matrix} T & 20 & S & R & 10 & W \\ WC & 4.4 & ft. & east & of & true & corner. & WC & \begin{matrix} 29 & 28 \\ 32 & 33 \end{matrix} \end{matrix}$
from which: $\begin{matrix} 11" & Fir & bears & N. 32^\circ W. & 23.2 & ft. & scribed & S29 & BT. & 1970 \\ 11" & Fir & bears & S. 89\frac{1}{2}^\circ W. & 16.1 & ft. & scribed & S32 & BT & 650 \\ & & & & & & with & tag. \end{matrix}$
Set 2 fence posts with signs + 5' W. facing S. & 5' S. facing W.

Section Corner to Sections 20 - 21 - 28 - 29. 40
Found - ¾" I.P. set by Gibson in 1957, See *Ren. #6*, from which:
Orig. 48" Fir bears N. 35° E. 46.4 ft., scribing visible, with tag,
has been chopped out. *out.*
20" Alder bears S. 36° W. 35.4 ft scribing vis., with tag, has been chopped
Set = 2"x30" I.P. with Brass Cap Mkd: $\begin{matrix} T20S & R10W & \begin{matrix} 20 & 21 \\ 29 & 28 \end{matrix} \\ 650 & 1970 \end{matrix}$
from which: $\begin{matrix} 12" & Maple & bears & N. 68^\circ W. & 26.2 & ft. & scribed & S20 & BT, & with & tag. \\ 12" & Hemlock & bears & S. 1^\circ E. & 54.5 & ft. & scribed & S28 & BT, & with & tag. \end{matrix}$
Set - 2 fence posts with signs: + 5 ft. W. facing S. & 5 ft. S. facing W.

Douglas County Surveyor's Record of
Government Corners Renewed

T. 20 S. T. S. R. 10 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

1/4 Corner to Sections 28 and 21. 41
Set - 3/4" Iron Pipe, from which: SEE REN. No. 9
18" Maple, now down with visible scribing, N.60°W.
The S. E. BT is now gone. 38.6 feet.
Scribed: 12" Maple S. 6 1/2° E. 37.4 feet.
14" Maple N. 70 1/2° W. 44.5 feet.

Sept. 1, '70

Stuntzner,
Ronald E.
For. U.S.
Plywood
M 42 - 2
C.S. 55/163

MARCH 77

1/4 Corner to Sections 7 and 8. 42
No evidence of original corner found.
At the properly proportioned position I placed a 2" x 36" galv. I. P.,
flanged at the bottom and capped with a bronze disk welded on top.
The monument projects 6" above ground. I filled in around the
pipe monument with stone and packed earth.
I stamped the disk

SEE
M 90-42

~~RENEWED GOVERNMENT CORNER NO. #95~~

S6/S5
1971
4185

I established new bearing trees as follows. Each bearing tree has a
scribed face and a U.S.F.S. bearing tree sign breast high and facing
the monument.
Set: A 10" Spruce bears S. 69° E. 26.60 feet.
A 10" Maple bears S. 30° W. 59.43 feet.

Rev. 10/12/71

Section corner to Sections 6 - 5 - 7 - 8 43
No evidence of original corner found.
At the properly proportioned position I placed a 2" x 36" galvanized
iron pipe, flanged at the bottom and capped with a bronze disk
welded on top. The monument projects 6" above ground. I filled
in around the pipe monument with stone and packed earth.
I stamped the disk:

SEE NEW NOTES

T20S R10W
S6/S5
S7/S8
1971
4185

I established new bearing trees as follows. Each bearing tree has a
scribed face and a U.S.F.S. bearing tree sign high and facing the
monument.
Set: an 18" maple bears S 46° W 47.55 feet.
a 26" maple bears S 26° E 43.06 feet.
a 4" alder bears N 17° E 27.56 feet.
a 32" hemlock bears N 19° W 59.10 feet.

James W. Prochman
For U.S. Forest Service
May, 1971
C.S. File 55/201
Map File M 43 - 56

1/4 Corner to Sections 6 and 5. 44
No evidence of original corner found. Ren. #3
At the properly proportioned position I placed a 2" x 36" galv. I.P.
flanged at the bottom and capped with a bronze disk welded on top.
The monument projects 6" above ground. I filled in around the
pipe monument with stone and packed earth.
I stamped the disk:

~~RENEWED GOVERNMENT CORNER NO. #117~~

S6/S5
1971
4185

I established new bearing trees as follows. Each bearing tree has a
scribed face and a U.S.F.S. bearing tree sign breast high and facing
the monument.
Set: a 28" maple bears N. 15° E. 30 feet.
a 32" Hemlock bears N. 44° W. 80.86 feet.

Rev. 10/12/71

POSSIBLE SITKA SHOWS - PER DICK HAMILIN
4/17/77

Douglas County Surveyor's Record of
Government Corners Renewed

20 T. S. 10 R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 21891

$\frac{1}{4}$ Corner to Section 1 only. T 20S R11W. 45
No evidence of original corner found.
At the properly proportioned position I placed a 2" x 36" galv. I. P.,
flanged at the bottom and capped with a bronze disk welded on top.
The monument projects 6" above ground. I filled in around the pipe
monument with stone and packed earth.
I stamped the disk: $\frac{1}{4}$ S1
1971
4185

I established new bearing trees as follows. Each bearing tree has a
scribed face and a U.S.F.S. bearing tree sign breast high and facing the
monument.
Set: a 16" fir bears N 82° W 31.00 feet.
an 18" fir bears N 57° W 42.18 feet.

$\frac{1}{4}$ Corner to Section 6 only. 46
Original corner never established.
At the properly proportioned position I placed a 2" x 36" galvanized
iron pipe, flanged at the bottom and capped with a bronze disk
welded on top. The monument projects 6" above ground. I filled
in around the pipe monument with stone and packed earth.
I stamped the disk: $\frac{1}{4}$ S6
1971
4185

I established new bearing trees as follows. Each bearing tree has a
scribed face and a U.S.F.S. bearing tree sign breast high and facing
the monument.
Set: a 28" fir bears N 40° E 24.1 feet.
a 20" fir bears N 24° E 34.6 feet.

Section Corner to Sections 1 and 12 only. T 20S R 11W. 47
Found: Original maple B.T. in NE quadrant (Good face but scribing was
destroyed in 1894). Found fir B.T. now 30" windfall with faint
face on bottom. Corner agrees very well with " canon " call
0.25 chains North.
Note: In 1894 all markings relating to R10W were destroyed making
corner common to Sections 1 and 12 only.
From the original maple B.T. in NE quadrant I placed a 2" x 36" galvanized
iron pipe, flanged at bottom and capped with a bronze disk welded
on top. The monument projects 6" above ground. I filled in around
the pipe monument with stone and packed earth.
Set: a 24" fir bears N 30° W 75.29 feet.
an 18" fir bears S 3° W 23.93 feet.
I stamped the disk: T20S T20S
S1 R10W
S12
R11W S6
1971
4185

Closing Corner to Sections 6 and 7. 48
No evidence of original corner found.
At the properly proportioned position I placed a 2" x 36" galv. I. P.,
flanged at the bottom and capped with a bronze disk welded on top.
The monument projects 6" above ground. I filled in around the pipe
monument with stone and packed earth.
I stamped the disk: S12 T20S
S6 cc
S7 R10W
1971
4185

I established new bearing trees as follows. Each tree has a scribed face
and a U.S.F.S. bearing tree sign breast high and facing the monument.
Set: a 16" fir bears N 60° E 72.25 feet.
an 18" fir bears S 49° E 47.59 feet.

James W. Prochnau
For U. S. Forest Service
May, 1971
C.S. File 55/201
Map File M 43 - 56

FD OK
9/18/84
CO. Surveyor's office
c.s. 62/21

RE-RENEWED, SEE CORNER NO # 84

Douglas County Surveyor's Record of
Government Corners Renewed

20 T. S. 10 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

1/4 Corner to Section 12 only. T20S R11W

49

No evidence or original corner found.

At the properly proportioned position I placed a 2" x 36" galv. I.P., flanged at the bottom and capped with a bronze disk welded on top. The monument projects 6" above ground. I filled in around the pipe monument with stone and packed earth.

I stamped the disk: _____

1/4 S12
1971
4185

I established new bearing trees as follows. Each bearing tree has a scribed face and a U.S.F.S. bearing tree sign breast high and facing the monument.

Set: a 32" fir bears S 66° W 33.90 feet.
a 20" fir bears N 73° W 29.10 feet.

1/4 Corner to Section 7 only.

Original Corner never established.

At the properly proportioned position I placed a 2" x 36" galv. I.P., flanged at the bottom and capped with a bronze disk welded on top. The monument projects 6" above ground. I filled in around the pipe monument with stone and packed earth.

I stamped the disk: _____

1/4 S7
1971
4185

I established new bearing trees as follows. Each bearing tree has a scribed face and a U.S.F.S. bearing tree sign breast high and facing the monument.

Set: a 22" fir bears N 29° E 49.4 feet.
a 14" fir bears N 78° E 75.54 feet.

1/4 corner to Sections 6 and 7.

No evidence of original corner found.

At the properly proportioned position I placed a 2" x 36" galv. I.P., flanged at the bottom and capped with a bronze disk welded on top. The monument projects 6" above ground. I filled in around the pipe monument with stone and packed earth.

I stamped the disk: _____

1/4 S6
S7
1971
4185

I established new bearing trees as follows. Each tree has a scribed face and a U.S.F.S. bearing tree sign breast high and facing the monument.

Set: a 18" fir stump bears N 72° E 28.23 feet.
a 26" fir stump bears S 52° E. 13.4 feet.

Rev. 10/12/71

1/4 Corner to Sections 5 and 8.

52

No evidence of original corner found.

At the properly proportioned position I placed a 2" x 36" galv. I.P., flanged at the bottom and capped with a bronze disk welded on top. The monument projects 6" above ground. I filled in around the pipe monument with stone and packed earth.

I stamped the disk: _____

1/4 S5
S8
1971
4185

I established new bearing trees as follows. Each bearing tree has a scribed face and a U.S.F.S. bearing tree sign breast high and facing the monument.

Set: a 6" fir bears N 36° W 90.7 feet.
a 12" fir bears S.78° W 92.5 feet.

Rev. 10/12/71

#93 50

#91 51

#122

SEE
M 90-42

RE-RENEWED, SEE CORNER NO.

James W. Trochman
For U.S. Forest Service
May, 1971
C.S. File 55/201
Map File M 43- 56

Douglas County Surveyor's Record of
Government Corners Renewed

T. 20 S. T. S. R. 10 W. R.W.W.M.

ROSE-CHAPMAN CO., EUGENE, ORE. - 21001

U. S. Forest Service
By James W. Prochnau
Oct. 12, 1971
C. S. File 55/201 Map M 43- 56

Section Corner to Sections 5 - 6 - 7 - 8.

Orig. Surv. record states: Set post for corner from which:
A fir 48" diam bears S.65°W. 76 lks. dist.
A maple 4" diam. bears N.69½°E. 33 lks. dist.
A fir 48" diam bears N.42°W 1.11 lks. (Corr. later to 111 lks.) dist.
A fir 16" diam. bears S.68°E. 1.03 lks. (Corr. later to 102 lks.) dist.
Found the N.W.(Sec.6) BT. with "X" and \equiv chopped in face. Now a bucked root
wad which has slid about 450 ft. downhill. This BT. while still green was
identified by Richard Hanlin during Doug. Co. timber appraisal as recorded
in Doug.Co.Surv. office. Noted X \equiv & faint bark scribe. Found U.S.Ply.tag
set by Walter Camp on 11/22/65 on 48" Fir stump location corner N.76½°E.
39.0 ft. Mr. Camp states that he set corner & his tag from a Forest Service
tag on nearby maple, that he was shown this tag by Mr. Mel Holmes, adjacent
land owner & verified tag with Forest Serv. personnel at Gardiner Ranger
Station as being the tag referencing the corner used to run a 1953 transit
survey to establish property lines in 1953. Mr. Holmes states that before
sliding out the Sec. 6 BT. was in a proper position relating to the corner
as ref. by Mr. Camp. I found evidence of a large fir sliding out from the
proper position of the Sec. 6 BT., in relation to the Walter Camp tag.

Considering the above evidence, I located the corner from the record on
said tag set by W. Camp on 11/22/65. At this position, I placed a 2"x36"
galv. Iron Pipe, flanged at the bottom & capped with a bronze disk welded
on top. The monument projects 6" aboveground. I filled in around the
pipe monument with stone & packed earth. The monument was set a post
set by Camp referenced by his tag.

T 20 S R 10 W
S 6 S 5
S 7 S 8
1971
4185

I stamped the disk-----

I established new BT's., as follows. Each BT. has a scribed face &
a U.S.F.S. BT. sign breast high & facing the monument.
BT's.Set: A 30" fir stump bears S. 74° E. 59.60 feet.
A 60" fir stump bears S. 80° W. 40.78 feet.
A 6" alder bears N. 54° W. 10.80 feet
A 24" Spruce bears N. 54° E. 118.38 feet.

PROCHNAU'S FIRST
CORNER - REV. #43

Jan 1972

Gary Langlitz
P. Earle
County Surveyor's
office
C.S. 56/49
3/19/74

1/4 corner for sections 10 and 11.

Found - 1952 U.S. GLO brass cap properly mkd. mounted on an iron pipe.
BT's - 10" now 20" Hemlock stump bears S.40°E., 31.7 ft. showing
a well healed blaze.

A 40" fir stump, bears S.12°W., 35.0 ft. showing a well
healed blaze.

Set - A steel fencepost with survey marker sign attached alongside the
brass cap.

New Bearing Object - A boat spike driven in the top of a 60" D.Fir stump,
directly above its root collar, marked with a "10" bears
N.76°W., 26.7 ft.

This corner lies on a steep north slope nearly at the bottom of a canyon
in a clearcut unit.

Jan 1975

Gar E. Commons
P. Earle
Surveyors office
Jan. 16, 1975
C.S. 57/17

1/4 Corner for Secs. 30 and 29.

Found - 60" D.Fir snag, is now a stump, extremely rotted on outside.
32" Hemlock N.42°E., 34 ft. (rec. N.43°E., 32.0 ft.) is now a 34"
stump. We opened scribe and found "CS" on portion of tree removed
by fallers. We opened and found "BT" (we attached this to top of
stump). The first record I could find of this BT was in the field
notes of railroad creek survey by Roy C. Gibson for E.K. Wood Lbr.
in 1957. He found BT and stated it was not orig. Knife scribed 25
years old.

Set - A railroad spike with "X" marked on head in center of 60" D. Fir.
New BT's - A 6" Hemlock, bears N.56°E., 40.6 ft. scribed "1/4 S30 CS BT."
A 12" Hemlock, bears N.57°W., 81.6 ft. scribed "1/4 S30 CS BT."

1/16/75

C.S. 42/275

53

54

55

Douglas County Surveyor's Record of
Government Corners Renewed

20 T. S. 10 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Sec.35 and 36 T20-10 and Sec.2 T21-10 Section corner between 35 & 36 only **56**
Found: U.S GLO Brass cap(1951) properly marked:
The 1892 bearing trees noted during the 1951 resurvey are both down.
We find them to be in their record positions.
BT's - A 31" D Fir bears West 30.2 ft., scribed "T20S R10W S35 CS BT" on a double blaze.
A 25" Hemlock bears N37°W., 31.9 ft., scribed "T20S R10W S35 CS BT" on a double blaze.
Note: The NE Corner of Sec. 2, T21S R10W A Brass cap, bears S89°15'E., 86.5 ft. This corner is located on top of a ridge at the SW corner of a clear-cut unit. Compass Declination Setting: 20° East. 11/12/75

Gary L Langlitz
Clell E Goodv
A Vic. Cangie
M. Lenora Lad
CS 57/39
11/12/75

Sec. 36 T20-10 and Sec.2 and 1 T21-10 Section corner between 1 & 2 only **57**
Found: U.S. GLO Brass cap leaning to south after apparent bulldozer damage properly marked.
BT's - no identifiable trace of the S E 1919 Bt. The rotting remains of the SW 1919 BT are in their record position with reference to the 1951 resurvey. This tree is now down and any identifying marks are buried. The southeast BT marked in 1951 is down, bearing S42 3/4°E., 23.1 ft., with scribing visible on an unhealed blaze.
We reset the Brass cap and the remains of the 1919 Iron post in the proper position and add the following markings to the brass cap. "CS 1975"
New BT's- a 28" Hemlock bears S53°E., 41.7 ft., scribed " T21S R10W S1 CS BT" on a double blaze.
a 17" D. Fir bears S22°W., 35.2ft, scribed "T21S R10W S2 CS BT" on a double blaze.
Note: The SW cor. sec.36 T20S R10W, a brass cap bears N89°15'W., 86.5 ft. This corner is located on a ridgetop near the SW Corner of a clearcut unit. 11/12/75

JAN 76

Center 1/4 for Section 36
Set - Iron Rod Post
From which:
Steel fence post set by BLM bears S.18°E., 21.95 ft.
6" Chittum, bears S.24°15'W., 26.9 ft.
12" Hemlock, bears N.74°23'W., 56.1 ft.
8/25/76

58
F.D. 10/84
R. STUTEMER
M 97-80
(Also fd. 1975
B.L.M. UNRECORDED
INFO.)

Forrest J. Ha s
For: Internat ional
Paper Co.
August 25, 1976
M 61 - 31

Section corner for 2, 1, 11 and 12. **59**
Found - 1952 monument not found. (several trees are down and have rolled over this area).
Found a squared wooden post at section corner (not of record).
An 8" Hemlock now a badly decayed stump bears N.31 3/4°E., 17.8 ft. Face is nearly rotted out, fragmentary scribe marks visible near edge of blaze.
A 40" Cedar now 48" bears S.13 3/4°W., 27.1 ft. Tree marked "T20S R10W S11 BT" on open blaze.
A 8" Hemlock now 9", bears N.33°W., 39.3 ft. (Rec. N.35 1/4°W., 38.0 ft.) Tree has partially healed single blaze.
SE 40" Fir is gone.
Set - Brass cap at section corner marked "Douglas Co. Surveyor"
T 20 S R 10 W
S 2 | S 1
S11 | S12
1977

Larry E. Monrean
Rod Kimberling
Doug. Co. Surv
Office
April 6, 1977
C.S. 59/31

Place wooden post along south edge of cap.
New BT's- A Maple, 13", bears S.44°E., 29.1 ft. Tree double blazed and scribed "S12 CS BT".
An Alder, 15", bears N.68 1/2°E., 25.0 ft. Tree double blazed and scribed "T20S R10W S1 CS BT".

N E corner Govt. Lot 8, Sec. 5 **60**
Found - unrecorded 3/4" I. P. at the NE corner Lot 8.
BT's - I witness this lot corner by marking the following bearing trees:
26" Fir bears N.63°E., 3.4 ft. (S 4 BT)
12" Fir bears N.3°W., 19.2 ft. (S 5 BT)
Note: The Northeast corner of Sec. 5 bears N. 0°46'13" W. (True), 456.29 ft.

Richard J. Hintz
For: Ford Investors
Aug. 13, 1977
C.S. 58/121

JAN 78

BOOK BY Clyde MURKINS
FOR: I.P. D. CRAVEN 5/94 M120-13

4/6/77

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 20 T. S. R 10 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORG. 21981

Ernesto R. Alvarado
U.S.F.S.
Deputy, Doug. Co.
Surveyors Office
Witness: Jill O'Neil
April 15, 1978
C.S. 59/46

1/4 Corner for Section 1 only, T20-11
Found - 2 1/2" brass cap in good condition, 4" below the road surface marked T20S R11W S1 only 4/185. Ren. #45
Uprooted D. Fir stump bears N.84°W., 33.10 ft.
22" D. Fir bears N.52°W., 43.04 ft. scribe marks visible.
New BT - 18" D. Fir bears S.70°W., 31.32 ft. double faced scribed 1/4 S1, upperblaze and CS BT lower blaze.
Note: Go south on USFS Road #1909 about 3.6 miles to the Siuslaw National Forest boundary sign on the left side of the road. The corner lies in the center of the road.

RE-RENEWED, SEE CORNER NO. #83

61

4/15/78

Richard J. Hintz
PLS 497
For: International Paper
4/78 M 69-78

Center 1/4 Corner for Section 4.
Set - 5/8" Iron Rod
BT's - 30" Fir stump bears N.4°00'E., 27.4 ft. scribed.
40" Fir bears N.85°00'W., 16.8 ft. scribed.

RE-RENEWED, SEE CORNER NO. #67

62

4/78

P. Fox, Engineer
#3282
For: U.S. Forest Serv.
Sept. 28, 1977
C.S. 60/11

*FD OK 4/87
R. HINTZ
M104-9*

Section corner for 13 and 24 only, T.20-11.
Found - 1968 Douglas County brass cap in mound of rock on steep rocky hillside. Ren. #27
48" Fir stump with tag bears S.81°W., 9.9 ft.
30" Fir stump with tag bears N.74°W., 8.6 ft.
15" Cedar stump with tag bears N.50°W., 16.6 ft.
Drilled hole in rock ledge to receive the iron pipe and a recess was made for the brass cap and then cemented in place.
No new accessories.

9/28/77

63

Forrest Hales
For: International Paper
April 1979
M 76 - 55

1/4 Corner for Secs. 31 and 32. *FD OK 2/92 BY STUNTZNER M114-80
FD OK 2/94 BY DOUGLE C.S. 63/130-4*
Set - 1 1/2" Pipe post with Brass cap in road ditch.
BT's - 16" D. Fir bears N.19°20'E., 59.8 ft.
5" Pond. Pine bears N.76°W., 84.4 ft.
14" D. Fir bears S.25°50'W., 169.1 ft.
1 Iron axle post bears S.1°03'W., 65.29 ft.

FD OK 1/96 P. Halar M123-37

64

Section corner for Secs. 31 and 32.; and Secs. 5 and 6 of T21-10.
Set - 1 1/2" x 36" Pipe post with brass cap
BT's - 28" D. Fir bears S.42°30'E., 84.4 ft.
16" R. Cedar bears N.7°W., 28.6 ft.

RE-RENEWED, SEE CORNER NO. #85

65

Center 1/4 Corner for Sec. 32.
Set - 1 1/2" x 36" Pipe post with brass cap.
BT's - 32" Hemlock bears N.32°30'E., 6.0 ft.
36" R. Cedar bears S.11°W., 19.4 ft.

April 1979

66

Ernesto R. Alvarado
U.S. Forest Service
Deputy - Doug. Co. Surveyor
Greg Martin - Witness
March 20, 1980
C.S. 61/6

Center 1/4 Corner for Sec. 4
Found - 1/2" machine axle with gear at top (no record)
36" D. Fir stump bears N.2°E., dist. 28.39 ft. open face scribing visible: 1/4 BT. (Rec. 30", N.4°E., 27.4 ft.) Ren. #62
57" D. Fir bears N.87°W., dist. 16.84 ft. partially healed face, scribing: 1/4 BT. (Rec. N.85°W., 16.8 ft.) Ren. #62
Set - 2" Douglas County Surveyor brass cap on 1" steel pipe mkd. T20S R10W C 1/4 S4 1980
1/2" re-bar is inside 1" steel pipe, and gear is deposited alongside.
New Accessories:
New bearings and distances to found BT's.
36" D. Fir stump bears N.4°E., dist. 28.5 ft.
57" D. Fir bears N.85°30'W., dist. 16.8 ft.

Attention signs and boundary signs on metal fence posts placed west and north of corner. Location: Take Burma Rd. to I.P. Rd. #20-10-4.1 Location Poster on edge of rd. approx. 0.1 mile from junction with rd. #20-10-3.3 Corner bears N.10°W., dist. 150 ft. from poster and lies on north lobe in clear cut.

3/20/80

67

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 20 S T. S. R 10 W R.W.W.M.

ROCKE-CHAPMAN CO., EUGENE, ORE. 21981

68

Frank M. Pumphrey
LS# 1677
For: International
Paper Co.
Aug. 1980
M 85 - 37

*FNO. OK 12/90
M 111-47 A-F
FO. OK 2/92
STOUTNER
M 114-80*

1/4 Corner to Secs. 31, T.20S. R.10W.; and Sec. 36, T.20S. R.11W.
Set - 5/8" x 30" Rebar with alum. cap mkd. "1/4 Sec. 36 31".
Set 4" below surface.
B.O.'s- 3/4" Iron pipe bears N.82°11'30"E., 298.22 ft.
3/4" Iron pipe bears S.55°46'56"E., 287.06 ft.
Fence post with 16P nail in top of post bears N.56°E., 33. t.
Fence post with 16P nail in top of post bears S.33°E., 36. t.
Fence posts are tagged. Corner lies in middle of field.

9/80

Richard Hintz
For: International
Paper Co.
July 1980
M 74 - 3

1/4 Corner to Secs. 8 and 17
Set - By apportionment - 5/8" Iron Rod.
BT's - 20" Hemlock bears N.43 15'E., 37.6 ft. scribed.
18" Hemlock bears N.24 30'W., 11.8 ft. scribed.
Note - Found corner from County Surveyor's file map # M 35 - 80
bears N.45 13'E., 17.79 ft.

69

Richard J. Hintz
For: Internat. Paper
February, 1982
M 91 - 24

Witness Corner to 1/4 cor. common to Sec. 33, & Sec.4, of T.21-10.
Set - 1-1/4" x 36" I.P. with B.C. stamped "P.L.S. 497", 2.0-ft.
south of corner position, which is in a field ditch.
New BTs- 32" fir bears N.65°45'E., 265.5-ft. (scribed).
68" maple bears S.57°30'W., 320.5-ft. (to face). 2/82

70

Sec. cor. common to Secs. 32, & 33, and Secs. 4, & 5 of T.21-10.
Found - Iron Pipe with U.S.G.L.O. B.C. dated 1918, & a plow share.
New BT - 14" alder bears S.70°W., 4.7-ft. (scribed). 2/82

RE-RENEWED, SEE CORNER NO. #72 71
(SEE REN. #1)

Gregory Quibell
Deputy, Douglas Co.
Surveyors Office
Randy Smith, witness
March 22, 1982
C.S. 61/30

Sec. corner common to Secs. 32 and 33; and Secs. 4 and 5 of T.21-10
Found - 2" I.P. filled with concrete firmly set protruding 6" out of
ground. The top 10" of said I.P. has brass cap attached and
is broken off and lying on ground. Cap is an unrecorded GLO
cap stamped "General Land Office Survey" T20S R10W SE2 S33
S 5 S 4 T21S 1918. See C.S. Renewal #'s 1 and 71.
Also found unrecorded 20" x 5" plow shear along side iron pipe.
14" alder with possible well healed blaze and newly bark scribed
"S 5 BT", bears S.63°W., 4.7 ft. (Rec. 5.7 ft.) bark scribing
per Ren. #71.
15" now 20" fir stump with scribed "BT" visible bears N.32°E.,
28.2 ft. (rec. N.45°30'E., 29.0 ft.)
12" now 15" fir snag approx. 40 ft. tall with well healed blaze
bears N.30°E., 23.8 ft.
12" alder is gone as is any orig. evidence. (Ren. #1)
Set - At the location of the 2" I.P. filled with conc. I set a 1" x 30"
I.P. with brass cap attached marked "Douglas Co. Surveyor"
T20S S32 S33 S5 S4 R10W T21S 1982.
I buried both parts of found GLO I.P. and brass cap along
with plow shear alongside new brass cap.
New BT's- 16" fir scribed "T20S R10W S33 CS BT" in double blaze bears
N.2°E., 83.8 ft.
7" fir scribed "T21S R10W S4 CS BT" in double blaze bears S.1°E
16.2 ft.
24" cedar scribed "T21S R10W S5 CS BT" in double blaze bears
S.71°W., 32.9 ft.

3/22/8

73

W. Carey Weatherly
For: International
Paper Company
Aug. 1982
C.S. 58/276

1/4 Corner for Secs. 9 and 10
Found - No evidence of 1952 BLM monuemnt.
30" D. fir BT, marked by BLM in 1952 now a 36" D. fir stump with
IPCo tag reading N.87°W., 44.6 ft.
14" maple BT, marked by BLM in 1952 gone.
78" D. fir stump with IPCo tag reading S.45°W., 37.7 ft. (no rec.)
Set - 1 3/8" galv. iron pipe with brass cap marked "Sec. 9/10, T20S
R10W 1982 LS 1667"
From which:
36" D. fir stump, with IPCo tag, bears S.87°E., 44.6 ft.
78" D. fir stump, with IPCo tag, bears N.45°E., 37.7 ft.
18" maple stump, with IPCo tag, bears S.84 1/4°W., 56.1 ft.

8/82

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 20 T. S. R 10 R. W. W. M.

ROCKE-CHAPMAN CO., EUGENE, ORE. 21001

W. Carey Weatherly
For: International
Pa Company
Aug 1982
C.S. 8/276

74

Section corner for Secs. 9, 10, 16 and 15.
Found - 1 1/2" galv. iron pipe with 1952 BLM brass cap in good condition.
36" D. fir BT (BLM 1952) now a 36" stump with IPCo tag reading
S.77°W., 6.0 ft.
56" D. fir BT, face evident (BLM 1952) now a 56" stump with
IPCo tag reading N.28°W., 9.4 ft.
28" hemlock BT (BLM 1952) now a 34" stump with IPCo tag reading
N.75 1/4°E., 45.4 ft.
20" alder BT (BLM 1952) now a 20" stump.
44" D. fir stump with IPCo tag reading N.51°W., 57.0 ft.
Set - IPCo tag on 20" alder stump BT, reads S.33°E., 23.8 ft.
8/82

es Roberts #1039
For: Int. Paper Co.
Oct. 8, 1982
M 90 - 28

75

1/4 Corner common to Sec. 25, and Sec. 30, of T. 20-9.
Found - 1951 GLO B.C.
BTs - 12" fir stump, bears S.26°W., 9.3-ft. (no marks) 1951 BT.
18" fir bears S.36°E., 20.9-ft. (scar visible) 1951 BT.
New BT - 23" fir bears N.24°W., 40.8-ft. (scribed). 10/82

Richard J. Hintz
P.L.S. #497
For International Paper Co.
October, 1982
M 93 - 26

76

Section corner for Secs. 27, 28, 33, & 34
Found - U.S. G.L.O. 1951 I.P./B.C.
BTs - 22" fir stump bears S.4°30'E., 264.8-ft. (1951 BTs)
30" fir uproot bears S11°W., 255-ft.
New BT - 28" fir bears S.2°30'W., 250.6-ft. (scribed). 12/82

77

North 1/4 corner of Sec. 33.
Set - 1-1/4" x 36" I.P. with B.C. stamped P.L.S. 497. #106
New BTs - 68" fir bears S.2°00'W., 19.5-ft. (to face).
24" fir bears N.17°15'W., 5.6-ft. (to face). (both BTs scribed) 12/82

78

Center 1/4 corner of Sec. 33.
Set - 1-1/4" x 36" I.P. with B.C. stamped P.L.S. 497.
New BTs - 16" maple bears S.36°30'E., 114.7-ft. (scribed).
28" alder bears N.63°30'W., 30.6-ft. (scribed). 12/82

79

Sec. Corner common to Secs. 19, 20, 29, & 30. Ren. #5. #114
Fd. - 4 x 4 post & 4 BT stumps per M 1-56 & CS 42/275
Set - Replace post with 1-1/4" x 36" Iron Pipe with Brass Cap
marked: PLS 497. 4/83

Richard J. Hintz
P.L.S. #497
For: International Paper Co.
April 1983
M 90 - 42

80

1/4 Corner common to Secs. 20, & 21.
Set - 1-1/4" x 36" I.P. w/ B.C. mkd: PLS 497.
New BTs - 14" maple bears S.60°00'E., 7.0-ft. to face. (both scribed)
64" fir bears N.62°00'W., 101.4-ft. to face. 4/83

81

W.C. for 1/4 Corner common to Secs. 20, & 29.
Set - 1-1/4" x 36" I.P. w/ B.C. mkd: PLS 497.
New BTs - 22" maple bears N.44°00'E., 44.0-ft. (scribed).
42" fir bears S.50°00'W., 53.9-ft. (bark scribed).
Note - 1/4 cor. position falls 6.0-ft., N.89°01'08"W from W.C.
and in creek bed at base of a 15' rock bluff. 4/83

82

Center 1/4 Sec. Corner of Sec. 20.
Set - 1-1/4" x 36" I.P. w/ B.C. mkd: PLS 497.
New BTs - 26" fir bears N.73°00'E., 29.2-ft. (both scribed).
28" fir bears S.55°00'E., 22.5-ft. 4/83

Donald Peel
For: Davidson
Industries
May 6, 1983
M 94 - 64
C.S. 58/274

83

1/4 Corner for Section 1 only, T.20-11
Set - U.S.F.S. alum. monument buried 4" below surface of Rd. No. 4811.
23" fir, N.42°W., 52.7 ft. (Prochnau BT) See Renewals #45 & 61
18" fir, N.88°W., 32.2 ft. (Prochnau BT)
Note: 1/4 Corner set by J. Prochnau in 1971 bears N.13°36'00"W., 11.77 ft
5/6/83

Douglas County Surveyor's Record of
Government Corners Renewed

T 20 T. S. R 10 R.W.W.M.

MOORE-CHAPMAN CO., EUGENE, ORE. 21881

84

Donald Peel For:
Davidson Industries
May 6, 1983
M 94 - 64
C.S. 58/274

Closing corner for Sections 6 and 7 only. (west side)
Found - 10"x7"x7" stone mkd CC with 1 notch, in circle of stones
approx. 4 ft. in diam.
Set - U.S.F.S. alum. monument in mound of stone.
34" fir, N.79 1/2°E., 92.5 ft.
20" Alder, S.45 1/2°E., 12.0 ft. (bark scribed)
17" fir, N.60°E., 95.8 ft. (Prochnau BT)
20" fir snag, S.72°E., 56.6 ft. (Prochnau BT)
Note: Closing corner set by J. Prochnau in 1971 bears N.51°33'26"E., 23

★ SEE
C.S. 62/19
4/2/84

FD. OK 9/15/84
D.S. 10/1/84
C.S. 10/1/84

See Ren. #

85

Section corner for Secs. 31 and 32; and 5 & 6 of T.21-10.
Found - 1 1/2" iron pipe with 2 1/2" brass cap set in conc properly
marked. Ren. #65
21" red cedar bears N.6°W., 28.8 ft. with scribe marks "BT S"
visible on partially healed face.
27" D. fir bears S.43°E., 85.0 ft. with healed face.
New BTs - 13" D. fir bears N.55°E., 80.7 ft. blazed and scribed "T20S
R10W S32 BT".
19" big leaf maple bears S.81°W., 73.3 ft. bark scribed "T21S
R10W S6 BT".

Herman Pieske, LS 1651
AA Surveying Services
For: US Dept. of Agric.
Siustlaw National Forest
November 1983
M 95 - 59 A & B

CHANGES MADE PER A.F. PRODUCE EXHIBIT
1/10/84 Co. (See file C.S. 10/1/84)

86

1/4 Corner for Section 32; and Sec. 5 of T.21-10.
Set - 2 1/2" x 30" alum. pipe, 24" in the ground, with 3 1/4" cap mkd.
"US Dep of Agri-Forest Service T20S 1/4 S32 S5 T21S RLS 165:
1983 Unlawful to disturb".
BTs - 20" hemlock bears N.31°E., 57.2 ft. scribed "1/4 S32 BT".
24" hemlock bears S.8°W., 59.4 ft. scribed "1/4 S5 BT".

87

Section corner for Secs. 33 and 34; and Secs. 3 & 4 of T.21-10.
Found - 2" iron pipe loosely set 18" above ground with 3" brass ca.
firmed up. (1951 GLO cap.)
36" D. fir bears N.67°E., (75° rec.) 148.49 ft. healed.
35" hemlock bears N.84°W., 64.3 ft. scribes visible "R10W
S33 BT US".
36" D. fir bears S.59°W., 62.7 ft. healed blaze.
New BT - 36" big leaf maple bears S.10°E., 27.8 ft. blazed and scribed
"T21S R10W S3 BT".

FD. OK 2/92 BY R. STUNTZNER M114-80

88

Herman Pieske LS 1651
AA Surveying Company
For: U.S. Forest Serv.
November 1984
M 97 - 76 A & B

1/4 Corner for Section 31; and Section 6 of T.21-10
Set - 2 1/2" x 30" alum. pipe with 3 1/4" alum. cap mkd. "US Dep of Agri-
Forest Service T20S R10W S31 1/4 S6 T21S RLS 1651 1983 Unlawful
to Disturb". Set pipe and cap 12" below ground in pasture.
New BTS-10" alder bears N.85°47'E., 170.7 ft. bark scribed "1/4 S31 BT".
12" alder bears S.29°10' W., 264.2 ft. bark scribed "1/4 S6 BT".

89

Ronald Stuntzner
For: International
Paper Company
Oct. 19, 1984
M 97 - 80

1/4 Corner for Sections 35 and 36.
Found - 1951 GLO proportioned corner, 1" I.P. with 2 1/2" brass cap.
24" hemlock now 30", S.33°E., 41 lks. (tagged with visible
scar.
New BT - 8" hemlock bears N.38°E., 12.8 ft. (faced with no scribe a
tagged.
Note - 1951 SW BT lost in logging road construction.

10/84

90

Richard Hintz
For: International
Paper Co.
M 90 - 42
April, 1983

1/4 Corner for Sections 19 and 30
Found - 3/4" I.P.
60" fir windfall is lying approx 35 ft. south of hole and/or
depression in ground. Hole bears N.52°W. 19 ft. from I.P.
See USFS index file No. R-3 at Mapleton.
Set - Replace the 3/4" I.P. with 1 1/4" I.P./B.C.
From Which:
10" Fir bears S.48°30'E., 30.3 ft. Scribed.
20" cedar bears N.60°00'W., 46.0 ft. Scribed.

RENEWED, SEE CORNER #108

4/83

**Douglas County Surveyor's Record of
Government Corners Renewed**

20 T. S. 10 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORG. 21881

Michael J. Schwartz & L.W. Hunnemuller
 RPLS 1922 RPLS 1050
 Sulphur Cadastral Survey - Siuslaw Natl. Forest
 U.S. Forest Service
 October, 1985
 M 99 - 79 A & B

91

1/4 Section Cor. for Secs. 6 and 7. See Renewal #51

Found - Brass cap set by Prochnau in 1971

BT's - 18" Fir stump, bears N.72°E., 28.23 ft.
 26" fir stump, bears S.52°E., 13.4 ft.

SET - A 3 1/2" x 30" Aluminum flared pipe with alum. cap stamped:
 T20S R10W 1/4 S6 S7 1984 RPLS 1922. (Cap lies S69°51'20"E.,
 7.99 ft. from Prochnau's corner.)

New BT's- A 5" D. Fir, bears S.28°E., 14.8 ft. dist., scribed X BT.

NEW BO - Set a 3 1/2" x 30" aluminum flared pipe with alum. cap stamped:
 1/4 S6 RM S12-39W., 44.7 ft. 1984 RPLS 1922.

92

Section Corner for Secs. 5, 6, 7, and 8 See Renewal #53

Found - 1971 Brass cap, marked T20S R10W Sec. 5,6,7,8 1971 4185.

BT's - 8" Alder, bears N.54°W., 10.3 ft. dist., with a face high bark
 scribe. (Record, 10.8 ft. 1971)

 30" Fir stump, bears S.74°E., 60.0 ft. dist. Bark scribed
 "RENW S8" (Record, 59.60 ft. 1971)

 60" Fir stump, bears S.80°W., 42.27 ft. dist., bark scribed
 "BT E7" (Record, 40.78 ft. 1971)

 Spruce BT (1971) is windthrown.

NEW BT's- 7" Alder, bears S.48°E., 47.1 ft., marked: T20S R10W S8 BT

 11" Alder, bears N.70°E., 22.2 ft. dist., marked T20S R10W
 S5 BT.

NEW BO - Set a 3 1/2" x 30" aluminum flared pipe, with aluminum cap,
 stamped T20S R10W S6 RM S80-10E 72.4 ft. 1984 RPLS 1922.

93

WEST

1/4 Section Corner for Sec. 7 only See Renewal #50

Set - 3 1/2" x 30" aluminum flared pipe, with aluminum cap stamped
 T20S R11W R10W 1/4 S7 1985 RLS 1922.

Found - 2" iron pipe from Prochnau survey bears N12°09'12"W 2.14 ft. from
 corner set this survey. (Removed cap)

Old BT's- 24" C. Fir, bears N.31°E., 50.2 ft. dist. With a healed face.
 16" D. Fir, bears N.80°E., 75.2 ft. dist. With a healed face.

94

Center 1/4 Sec. Cor. for Sec. 7

Set - A 3 1/2" x 30" aluminum flared pipe, with aluminum cap stamped
 T20S R10W C1/4 S7 1985 RLS 1922

BT's - 5" D. Fir, bears S.71°W., 10.8 ft. Marked C1/4 S7 BT.

BO - Set a 3 1/2" x 30" aluminum flared pipe, with aluminum cap,
 for Reference Monument, stamped: RM S7 C1/4 N89-36W 41.2' 1985
 RLS 1922.

95

1/4 Sec. Cor. for Secs. 7 and 8 Renewal #42

Found - A 1971 Brass cap, marked: 1/4 S7 S8 1971 4185.

BT's - 18" D. Fir, bears(S69°E 26.6 ft. 1971) Tree so badly "J"d,
 couldn't tell where to measure to.
 11" maple, S.30°W 58.4 ft. dist., scribing visible. (Record,
 59.43 ft. 1971)

NEW BT - 10" D. Fir, bears S.43°E., 44.6 ft. dist., scribed 1/4 S8 BT.

96

1/4 Sec. Cor for Secs. 7 and 18

SET - A 3 1/2" x 30" flared aluminum pipe , with aluminum cap,
 stamped: T20S R10W 1/4 S7 S18 1984 RPLS 1922.

NEW BT's- 29" Red Cedar, bears S.67°W., 32.7 ft. dist., scribed: 1/4 S18
 BT.
 51" Red Cedar, bears N.7°W., 58.3 ft. dist., scribed: 1/4 S7 BT.

97

1/4 Sec. Cor. for Secs. 17 and 18

SET - A 3 1/2" x 30" aluminum flared pipe, with aluminum cap,
 stamped: 1/4 S18 S17 1984 RPLS 1922.

BT - 4" Alder, bears S.74°W., 57.3 ft. dist., scribed 1/4 S18 BT.

BO - Set a 3 1/2" x 30" aluminum flared pipe, with alum. cap
 for reference monument. Stamped: RM 1/4 S17 S13-56W 54.7 ft.
 1984 PLS 1922.

**Douglas County Surveyor's Record of
Government Corners Renewed**

20 T. S. 10 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 91881

Michael J. Schwartz, & L.W. Hunnemuller
 RPLS #1922 RPLS #1050
 Sulphur Cadastral Survey - Siuslaw Natl. Forest
 U.S. Forest Service
 October 1985
 M 99 - 79 A & B

98

Sec. Corner to Secs. 7, 8, 17, and 18 Ren. #19
 Found - Douglas County Brass cap, marked County Surveyor's Office
 T2OS S7 S8 S17 S18 R10W 1968.
 BT's - 18" Maple, bears S.22°E., 56.0 ft. dist., with healed face.
 (Record, 24" Maple 57.7 ft. 1968)
 Decayed Fir, bears S.40°W., 50.2 ft. dist., with a face ch
 slab, scribed W BT (1874)
 20" D. Fir stump, bears S.40°W., 55.3 ft. dist., with ba
 scribing visible: "T2OS R10W S17"
 25" D. Fir snag (12 ft.) bears S.76°W., 44.7 ft. dist., with
 bark scribing visible: "R10W"
 29" Maple, bears N.81°E., 7.0 ft. dist., With a severe lean
 and scars visible. (1968)
 New BO's- Marked a concrete nail in large sandstone boulder, N63°W.,
 10.7 ft.
 Set a 3 1/2" x 30" alum. flared pipe with alum. cap for Ref-
 erence monument. Stamped: T2OS R10W RM S18 N1-14E 49.3
 1985 RLS 1922.

99

EAST
 1/4 Sec. Cor. to Sec. 13 only, (T2OS R11W)
 SET - An Aluminum Surv-Kap on a 5/8 in. Iron Rod in rock. Stamped:
 T2OS R11W R10W 1/4 S13 1985 RLS 1922
 BT's - A 32" D. Fir, bears N.39°E., 16.1 ft. dist., scribed: 1/4 S18
 BT.
 12" Maple, bears S.61°E., 68.3 ft. dist., scribed X BT.

100

WEST 1/4 Corner to Section 18 only
 SET - A 3 1/2" x 30" aluminum flared pipe, with an alum. cap s ped:
 T2OS R11W R10W 1/4 S18 1985 RLS 1922
 BT's - 8" Alder, bears S.74°E., 29.7 ft. dist., bark scribed "1 S18"
 "BT"
 10" D. Fir, bears S.69°W., 26.9 ft. dist., scribed, X BT.
 BO - Set a 3 1/2" x 30" Alum. flared pipe, with alum. cap for
 Reference Monument, stamped: RM 1/4 S18 N1-17E 40.7 ft.
 1985 RLS 1922

101

Center 1/4 Sec. Cor. to Section 18
 SET - A 3 1/2" x 30" alum. flared pipe, with an alum. cap stamped:
 T2OS R10W C1/4 S18 1985 RLS 1922
 BT - 19" D. Fir, bears S.38 1/2°W., 51.0 ft. dist., scribed:
 C 1/4 S18 BT
 BO - Set a 3 1/2" x 30" aluminum flared pipe, with an alum. cap
 for a Reference Monument, stamped: RM C1/4 S18 N72-54W
 63.3 ft. 1985 RLS 1922.

102

1/4 Section Corner for Secs. 18 and 19 Ren. #26
 Found - Douglas County Brass cap, marked: T2OS 1/4 S18 S19 R10W
 1968
 BT's - 28" maple, bears N.45°E., 27.3 ft. dist., with open face.
 (Record, N.45°E., 26.4 ft. 1892)
 30" Maple stub, bears S.10°E., 11.9 ft. dist., with heal
 scar.
 NEW BT - 22" Double Alder, bears N.83°W., 38.4 ft. dist., scribed
 1/4 S18 BT.
 No suitable bearing trees to south.

103

EAST
 1/4 Section Corner for Section 24 only. (T2OS R11W)
 SET - 3 1/2" x 30" aluminum flared pipe with alum. cap stamped:
 R11W T2OS R10W 1/4 S24 1984 RPLS 1922
 BT's - 6" D. Fir, bears N.46°W., 16.6 ft. dist., scribed:
 1/4 S24 BT
 9" D. Fir, bears S.43°E., 16.6 ft. dist., scribed:
 1/4 S24 BT.

Douglas County Surveyor's Record of
Government Corners Renewed

20 T. S. 10 R. W. W. M.

MOORE-CHAPMAN CO., EUGENE, ORE. 97101

Michael J. Schwartz, & L.W. Hunnemuller
RPLS #1922 RPLW #1050
Sulphur Cadastral Survey - Siuslaw Natl. Forest
U.S. Forest Service
October, 1985
M 99 - 79 A & B

W. Carey Weatherly
L.S. 1667
For: International
Paper Co.
June 5, 1986
.S. 63/37

Richard J. Hintz
For: International
Paper Co.
Sept. 1985
M 99 - 51

Daniel Baker LS 1978
For: U. S. Forest Service
June 10, 1986
M 102 - 12

FD. OK
7/92
Royce Hill
M 115-71

WEST 104
1/4 Section Corner to Section 19 Only.
SET - 3 1/2" x 30" Aluminum flared pipe with Alum. cap.,
Stamped: T20S R11W R10W 1/4 S19 1984 PLS 1922
BT's - 7" D. Fir, bears S.10°E., 2.4 ft. dist., scribed 1/4 S19 BT.
10" D. Fir, bears N.38°E., 21.2 ft. dist., scribed 1/4 S19 BT.

Section Corner to Secs. 17, 18, 19, & 20 Renewal #24 105
Found - Douglas Co. Brasscap, marked T20S S17 S18 S19 S20 R10W 1968.
BT's - 19" Hemlock stub, bears N.69 1/2°E 36.0 ft. dist. (1968)
Badly decayed.
30" rotted hemlock stub, bears S.31°E., 4.2 ft. dist., with
axe marks.
10" Alder, bears N.84°E., 43.2 ft. dist., with partially
healed face and scribing visible. (Record, N.84°E., 43.6 ft.
1968)
10" Hemlock, bears N.48°W., 10.0 ft. with healed face.
(Record, N.48°W., 10.0 ft. 1968)
15" D. Fir, bears S.48°W., 28.4 ft. with pitch over face.
(Record, S.48°W., 28.4 ft. 1968)
NEW BT's - 8" Hemlock, bears S.42°E., 4.1 ft. dist., scribed:
T20S R10W S20 BT.

FD BC
By Shoner
4/1/93
1993-0072 A+B

1/4 Corner for Sections 33 and 28 106
Found - Brass cap/iron pipe in good condition. Ren. No. 77
68" D. fir stump, scribing visible, bears S.02°W., 19.5 ft.
24" D. fir BT of record, uprooted and slid down slope.
New BT - 18" D. fir stump with IPCO tag and nail bears N.33°E., 17.4 ft.
6/5/86

Section corner for Sections 29, 30, 31 and 32 107
Found - Iron pipe/brass cap, GLO 1951 Ren. #21
12" fir bears North, 53.2 ft. closed face
12" maple bears S.67°E., 28.8 ft.
24" cedar bears S.49°W., 7.9 ft. closed face
New BT - 16" fir bears N.23°00'00"W., 37.0 ft. scribed S30 BT.

1/4 Corner for Sections 19 and 30 108
Found - 1 1/2" iron pipe with brass cap. Ren. #90
14" fir, S.48 1/4°E., 30.3 ft. (closed face)
22" cedar, N.61°W., 46.1 ft. (closed face)
Set - 2 3/8" x 30" alum. pipe with 3" alum. cap as a reference point
bears S.0°16'53"W., 35.75 ft. Cap stamped "T20S R10W 1/4 S19
S30 PLS 1978 1986 35.75 N0°16'53"E"

1/4 Corner for Secs. 29 and 30. 109
Found - Boat spike with "X" in top in center of rotted fir stump. Ren.#55
14" rotted hemlock stump, N.6°E., 9.5 ft. (no record)
30" rotted hemlock stump, N.40 1/2°E., 34.1 ft.
20" hemlock, N.56°E., 40.6 ft. (scribe visible)
36" fir stump, S.52°E., 26.4 ft. (U.S.F.S. tag - not of rec.)
Set - I referenced the boat spike, then pulled it and replaced it with
a 5/8" x 27" rebar with 3" alum. cap marked "T20S R10W 1/4
S30 S29 PLS 1978 1986".

Center 1/4 Corner for Section 30 110
Set - 2 3/8" x 30" alum. pipe with 3" alum. cap marked " T20S R10W
C 1/4 S30 PLS 1978 1986"
New BTs - 10" hemlock, S.87°E., 26.9 ft. scribed "C 1/4 S30 BT"
16" cedar, N.4 1/2°W., 51.0 ft. scribed "C 1/4 S30 BT".
Set - 2 3/8" x 30" alum. pipe with 3" alum. cap as a reference
monument bears N.0°16'53", 38 ft.

Douglas County Surveyor's Record of
Government Corners Renewed

T 20 T. S. R 10 R.W.W.M.

KORE-CHAPMAN CO., EUGENE, ORE. 21891

Fd. OK 2/92
BY R. STUNTZNER
M 114-80
7/92-Royce Hill
M 115-71

Daniel Baker PLS 1978
For: U.S. Forest Serv.
June 1986
M 102 - 12

111
1/4 Corner for Sections 30 and 31
Set - 2 3/8" x 30" alum. pipe with 3" alum. cap.
New BTs - 16" cedar, S.2 1/4°W., 18.1 ft. scribed "1/4 S31 BT"
16" cedar, N.87 1/2°W., 26.5 ft. scribed "1/4 S30 BT"
Set - 2 3/8" x 30" alum. pipe with 3" alum. cap as a reference point
bears S.89°25'40"W., 37.38 ft.
Note - 1/2" iron pipe (M 10-3) bears S.88°32'09"W., 98.2 ft. Ren. No. 1

112
Section corner for Secs. 30 and 31; and Secs. 25 and 36 of T.20-11
Found - 2 1/2" iron pipe with brass cap Ren. No. 38
7" dead chittum bears S.71 1/2°E., 27.4 ft. (Rec. NE)
63" fir, S.17 3/4°W., 73.4 ft. bark scribed
18" rotted maple, N.31 1/2°W., 24.6 ft.
16" cedar, N.16 1/2°W., 46.2 ft. closed face
New BT - 72" spruce bears S.72 3/4°E., 74.3 ft. scribed "T20S R10W S31 BT"

113
1/4 Corner for Sec. 30; and Sec. 25 of T.20-11.
Set - 2 3/8" x 30" alum. pipe with 3" alum. cap marked "T20S R11W R10W
1/4 S25 S30 PLS 1978 1986".
New BTs - 8" fir N.28°E., 11.0 ft. scribed "1/4 S30 BT".
9" Fir, S43 1/2°W., 16.9 ft. scribed "1/4 S25 BT".

114
Section Corner for Secs. 19, 20, 29 and 30
Found - 1 1/4" I.P. stamped brass cap (PLS 497-1983 Ren. #79
From which:
27"hemlock stump bears N.61°05'E., 15.1 ft. to a 1/2" x 30" I.R.
set in the top center (visible scribe on partially
healed blaze.)
24" fir stump bears S.82°05'E., 24.1 ft. to a 1/2" x 30"
I.R. set in the top center (healed blaze.)
42" fir stump bears S.61°10'W., 42.5 ft. to a 1/2" x 30"
I.R. set in the top center (no visible scribe on rotted blaze.)
37" fir stump bears N.15°27'W., 20.6 ft. to a 1/2" x 30" I.R.
set in the top center (visible scribe on rotted blaze.)
No previous record of Iron Rods in center of stumps.

115
Center 1/4 Corner for Section 19
Set - 2 3/8" x 30" al. pipe with 3 1/4" stamped al. cap marked:
T20S R10W C1/4 . S19 1987 PLS 497.
New Accessories:
16" maple bears S.62°E., 6.7 ft. scribed C1/4 S19 BT.
2 3/8" x 30" al. pipe with 3 1/4" stamped al. cap bears
S.1°46'W., 55.9 ft. (RM)

116
1/4 Corner for Sections 19 and 20
Set - 2 3/8" x 30" al. pipe with 3 1/4" stamped al. cap. Cap mkd.
T20S R10W 1/4 . S19 . S20 1987 PLS 497.
New BTs - 10" maple bears N.26°45'E., 26.4 ft. scribed 1/4 S20 BT.
18" maple bears S.25°30'W., 42.4' scribed 1/4 S19BT.

117
1/4 Corner for Sec. 6 and 5. See Ren#44
Set - A USFS 2 1/2" x 30" aluminum pipe with 3 1/4" aluminum
cap stamped "T 20S R10W 1/4 S6|S5 1987 PLS 1305".
New BT's - A 16" Maple bears N 7 1/4°E, 64.0 ft. Scribed "1/4 S5 1987".
New BO's - A U.S.F.S. 2 1/2" x 30" aluminum pipe with 3 1/4" aluminum
cap stamped "RM 1/4 S5 1987 PLS 1305" bears N 2°25'E, 313.0 ft
A U.S.F.S. 2 1/2" x 30" aluminum pipe with 3 1/4" aluminum
cap stamped " RM 1/4 S5 1987 PLS 1305" bears S9°46'W, 90.3 ft.

118
1/4 Corner for Sec. 5, and 32 of T19-10. See Ren#17
Found - A BLM 3" brass cap on a 2" galvanized iron pipe.
BT's - A 42" Douglas Fir bears S 78°W, 103.0 ft. Record S78 1/4°W 158lks.
10" Alder stump bears N 4°E, 36.0 ft. Record N4°E, 56lks.
New Bt's - A 22" Alder bears N 47 1/2°E 42.6 ft. bark scribed "1/4 S 32 BT"
34" Alder bears S 2 1/2°W, 117.7 ft., scribed "1/4 S 5 BT".

Richard Hintz
For: Siuslaw National
Forest
April 1987
M 104 - 9

James W. Prochnau
For: Siuslaw National
Forest M 104-51A&B
June, 30, 1987

**Douglas County Surveyor's Record of
Government Corners Renewed**

20 T. S. 10 R. W. W. M.

FOKE-CHAPMAN CO., EUGENE, ORE. 21881

James W. Prochnau
For: Siuslaw National
Forest M 104 - 51 A&B
June 30, 1987

*FDOK BY
Clyde Huikins for: JP
David Craven
5/19/84 M/20-13
FNO OK
12/90 M/11-33*

Section Corner to sections 5 and 4, also sections 32 and 33 of T19-10 **119**
Found - GLO 2 1/2" brass cap on a 1 1/2" galvanized iron pipe set in 1952.
BT's - A 24" douglas fir stub bears S86°W, 10.7 ft. (rec. S85°W, 15 lks.) Healed. (BLM 1892)
34" douglas fir bears S 20°E, 66.7 ft. (rec. S 20°E, 101 lks) healed. (BLM 1952).
26" douglas fir bears N 40°E, 34.9 ft. (rec. N 40°E, 53 lks) healed (BLM 1979)
33" Alder bears N 12°W, 8.6 ft. (rec. N 16°W, 8.5 ft.) ✓ (1982 RLS 752).

1/4 Corner for sections 5 and 4. **120**
Found - A 2 1/2" Brass cap on a 1" galvanized iron pipe stamped " 1/4 S5/S4, 1952" Also a 2" iron cap on a 1 1/2" iron pipe mkd. "1/4 S5/S4" Reset by new monument.
BT's - A 28" douglas fir bears N 58°E, 33.7 ft. (rec. N 58 3/4°E, 51 lks.). healed. 1952 BLM Bt.
36" douglas fir stump bears N 75°W, 19.1 ft. (rec. N 75°W, 29 lks.). Healed.
Ref mon.- A U.S.F.S. 2 1/2" x 30" aluminum pipe with 3 1/4" aluminum cap bears S 89°24'W, 44.5 ft. marked "T20S R10W RM 1/4 S5 1987 PLS 1305".

Section corner for sections 5, 4, 8 and 9. **121**
Found - A 2 1/2" brass cap on a 2" galvanized iron pipe set by GLO 1952, stamped " T20S R10W S5 S4 S8 S9 1952".
BT's - 60" Douglas fir stump bears S 30°E, 56.1 ft. (rec. S 30°E, 85 lks.) healed. (1878 BT.)
Alder stump bears N 67°W, 36.7 ft. (rec. N 69°W, 53 lks) 1952 BT.
38" Douglas fir stump bears S 45°W, 91.7 ft, (rec. S 45°15'W, 139 lks) healed.
14" Alder bears N 9°E, 30.3 ft. Healed. (Unrecorded BT)
New - 4" Alder bears N 82°W, 43.1 ft. Scribed " X BT".
BT's 7" Hemlock bears S 57 1/2°W, 23.2 ft. scribed "T20S R10W S8 BT".
Ref - A U.S.F.S. 2 1/2" x 30" aluminum pipe with 3 1/4" aluminum cap mon set stamped "T20S R10W RM S9 1987 PLS 1305".

1/4 Corner section 5 and 8. **122**
Found - A 2 1/2" brass cap on a 2 1/2" galvanized iron pipe set by J. Prochnau in 1971.
BT's - 24" Douglas fir bears S 78°W, 92.5 ft., healed.
15" Douglas fir bears N 36°W, 90.7 ft. healed. See Ren#52
Set - A 8" Douglas fir Corner Tree replaces the brass cap on pipe. tree mkd. " SC 1/4 S5" on North side of tree.
Set - The found 2 1/2" brass cap on a 2 1/2" galvanized iron pipe has RM's been modified and used as a RM, bearing: S 25°23'W, 10.8 ft. marked "RM 1/4 S8".
NOTE : Removed tags and signs from 1971 BT's.

Center 1/4 Corner for section 5. **123**
Set - A 3 1/4" aluminum cap with magnet on a 2 1/2" x 30" aluminum pipe stamped " T20S R10W C 1/4 S5 1987 PLS 1305".
BT's - A 23" Douglas fir bears S 40°E, 7.2 ft. scribed "C 1/4 S5 BT".
Scibed 15" Douglas fir bears S 87 1/2°E, 17.7 ft. Scribed "C 1/4 S5 BT".

Section Corner for Secs. 23, 24, 25 and 26 **124**
Found - 56" Fir stump with scribing, S.13°E., 64.02 ft.
49" Fir stump with face seam showing at cut, N.57 1/4°W., 22.44 ft.
BTs from 1951 dependent resurvey. (See County Surveyors records, Vol. 27 Pgs. 11689-90 BLM records)
The BLM monument and other 2 BTs were removed by a road cut.
Set - 2" alum. cap on a 3/4" x 30" iron rod at record bearing and dist! from the 2 found BTs. Cap stamped: "Stuntzner Engineering T20S R10W S23 S24 S26 S25 1990 LS 2244".

New Accessories:
Scribed an "X" in the rock cut bank, N.50°E., 23.90 ft.
Set a spike in the top of a 17" alder stump, S.47°W., 43.85 ft.
East fork of Spencer Creek, a tributary of Smith River. Corner falls in a dirt cat road about 30 ft. south of a ridge. This corner falls in a freshly burned clear cut.

J. Prochnau
For: Siuslaw National
Forest M 104 - 51 A&B
June 30, 1987

Harvey Wilcox
Stuntzner Eng.
L.S. 2244
June 21, 1990
C.S. 63/104

**Douglas County Surveyor's Record of
Government Corners Renewed**

20 T. S. 10 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Les Roberts LS1039
For: International
Paper & US Forest
Service.
December 1990
M 111 - 33

Section Corner for Sec's 3, 4, 33 & 34 T. 19 R. 10 125
Found - 1952 G.L.O. brass cap
BT's - 12" fir S.53°E 13.7 ft. (scar vis.) 1952 BT.
13" fir snag S.25°W. 7.3 ft. (scar vis.) 1952 BT.
14" fir N.28°W. 10.9 ft. (scar vis.) 1952 BT.
18" fir N.57°E 6.4 ft. (scar vis.) 1952 BT.
Set - 2½" X 30" aluminum pipe and ~~XXXX~~ cap for reference monument
Brass cap bears N.89°42'30"E., 63.06 ft. from reference
monument. See renewal # 22. T.19 R.10 12/90

Harvey Wilcox LS2244
For: U.S.F.S.
December 1990
M 111 - 47 A - F

Section Corner for Sec's 30 & 31; & Sec's 25 & 36 of T.20 R.11. 126
Found - 2½" brass cap on 2¼" IP. 14" above ground with 1" IP alongside.
BTs Fnd-Original BT 32" maple, rotten face, tags, bears N.29°W., 25.30'.
17" cedar, healed face, tags, bears N.20°W., 47.3 ft. Ren # 112
76" spruce, visible scribe, tags, bears S.72°45'E., 74.3 ft.
Cascara, dead, tags, bears S72°E., 27.6 ft.
65" douglas fir, visible scribe, tags, bears S.18°W., 70.3 ft.
Set R.M. Std. U.S.F.S. disk "RM T20S R10W S30 S.88°20'W 43.40'
1990 RLS 2244" bears N.88°20'E., 43.4 ft. 12/90

Harvey Wilcox LS2244
For: U.S.F.S.
December 1990
M 111 - 47 A - F

*FD. OK BY STUNTZNER
2/92
M114-80*

South West Corner for Section 31. 127
Found - 2½" brass cap on 1½" IP 12" above ground, with 1" IP along side.
BTs Fnd 30" maple S.E. trunk of tree with healed face, tags,
bears N.14°W., 15.2 ft. Ren. # 25
21" douglas fir, healed face, tags, bears N.80°E., 83.6 ft.
37" douglas fir, healed face, tags, bears S.77°15'E., 42.9 ft.
39" maple, healed face, tags, bears S,27°W., 11.2 ft.
Note - This tree trunk has blown down (39" maple) retagged another
trunk of same tree, it bears S,25°30'W., 14.2 ft.
Set R.M-Std. U.S.F.S. disk "RM T20S R10W S31 S88°09'W 52.91 1990 RLS2244"

Ronald Stuntzner
For: The Travelers Co
Feb. 1992
M 114 - 80

Center 1/4 for Section 31 128
Set - 3/4" iron rod with 2" aluminum cap marked "C¼ S31 1992 LS 1342"
BT's - 13" Maple with face scribed "C¼ S31 BT" & tag bears N.26°W, 14.95'
18" cedar with face scribed "C¼ S31 BT" & tag bears N.16°E, 14.85'
39" cedar with face scribed "C¼ S31 BT" & tag bears S.23°E, 43.25'
44" cedar with face scribed "C¼ S31 BT" & tag bears S.17°W, 26.65'
4/92

Douglas County
Surveyors Office
R.W. Smith
S.J. Flause
J. Pike
May 6, 1992
C.S. 64/26

1/4 Corner for Section 1; and Section 36 of T.19-10 129
Found -A 2½" dia. 1952 BLM brass cap on a 1½" O.D. Iron Pipe firmly
set and protruding approx. 3" above ground.
A 36" Fir, now a fallen and partially rotted fir snag, with
evidence of a fully healed single blaze, the root hole of
which bears N.75°E., 39.6 ft. (as per record)
A 54" Fir now a 45" DBH D. Fir with a fully healed single
blaze bears S.86°E., 53.2 ft. (Rec. S.83°45'E., 52.1 ft.)
(previously recorded dia. appears to be erroneous)
New BTs - A 55" DBH 80 ft. tall fir snag with a high, open cruisers
blaze bears S.72°W., 57.8 ft.
A 6" DBH Alder bark scribed "1/4 S1 CS BT" bears N.86 3/4°W, 30.7 ft. distant.
Monument is on a south slope near bottom of very steep slope.
Monument on an east-west cutting line with older clear cut to north
Old growth to south. Monument is approx. 200 ft. south from a
closed logging spur road end.

5/6/92

Douglas County Surveyor's Record of
Government Corners Renewed

T. 20 S. T. S. R. 10 W. R. W. W. M.

FOKE-CHAPMAN CO., EUGENE, ORE. 21001

Les Roberts
Apr. 24, 1992
C.S. 63/138 (Corner Restoration Forms)

130

Center South 1/16 Corner Section 34. (Condition Report Only)

- Found - 1983 BLM iron pipe and brass cap lying on the ground. Re-set iron pipe and brass cap from found 1983 BTs.
11" Fir, N.85°W., 207.9 ft. (scar vis.) Rec. N.85¼°W., 207.9 ft.
16" Fir, S.6°E., 48.2 ft. (scar vis.) Rec. S.6¼°E., 48.2 ft.
- Set - 72" alum. post, with land survey monument sign attached to beside brass cap. Painted all bearing trees red.
- Note - Corner lies on flat ground about 80 ft. south of south bank of Smith River.

131

South 1/16 Corner Section 34 & Section 33.

- Found - 1951 GLO iron pipe and brass cap lying on ground. Re-set pipe and cap from NE Willow BT.
48" Downed Willow, N.41°E., 9.2 ft. (no marks) 1951 BT. Record N.41°E., 9.2 ft.
SW Alder BT was washed away by Smith River.
- Set - 72" alum. post with land survey monument sign attached beside brass cap.
- New Accessories -
18" Maple, S.50°W., 33.8 ft. (scribed/painted red)
24" Alder, S.83°E., 31.7 ft. (bark scribed/painted red)
- Note - Corner lies 25 ft. east of Smith River and 15 ft. north of small draw. Draw bears N.80°W.

132

Les Roberts
L.S.1039
For: International Paper
Dec. 1992
M 118-47

Corner Secs. 33 & 34; 3 & 4 T21-10

- Found - 1951 GLO brass cap
30" Hemlock, N.85°W., 64.3' (scribe vis.), 1951 BT
33" Fir, N.70°E., 148.5' (scar vis.), 1951 BT (rec. 87.1)
38" Fir, S.59°W., 64.5' (scar vis.), 1951 BT
36" Maple, S.20°E., 26.5' (scribe vis.) 1983 BT

133