

Douglas County Surveyor's Record of
Government Corners Renewed

T. 20 S. T. S. R. 10 W. R. W. W. M.

HOKE-CHAPMAN CO., EUGENE, ORE. 21881

Wilford N. Haines
For-U.S.F.S.-U.S.Plywood &
International Paper
Nov. 1965
Map File M 31 - 6

(continued)

Scribed New BT's: 40" Fir N. 3° W. 27.0 ft.
14" Fir N. 59° E. 21.5 ft.
30" Fir S. 6° E. 25.5 ft.
40" Fir S. 72° W. 59.6 ft.

West 1/16 Sec. 5, T20-10W. & Sec. 32, T19-10W. 16

Set - Iron Pipe with Brass Cap Mkd: RS239 W 1/16 S 32 T19S R10W
Scribed New BT's: 40" Fir S. 70° W. 19.7 ft. S 5 T20S R10W
18" Fir N. 5° E. 39.8 ft.

1/4 Corner to Sec. 5, T20-10W. & Sec. 32, T19-10W. #118 17

Set - Iron Pipe with Brass Cap Mkd: RS 239 S 32 T19-10W
Scribed New BT's: 33" Fir S. 72° W. 19.3 ft. S 5 T20-10W
28" Fir N. 61° E. 31.3 ft.

Sec. Corner to Sections 7 - 8 - 17 - 18. 18

Found - 5" Fir S. 40° W. 76 lks., now stub about 2 ft. high,
scribed W" BT, plain.

Set - 1" x 1" x 36" T. Iron

There is two unrecorded BT's., both Firs, These scribed trees
here in 1941 when I first visited this corner.

Section Corner to Sections 7 - 8 - 17 - 18. 19

Found - Haines' "T" Iron, see Ren. #18, set at corner from one Orig. BT.

Orig. 5" Fir, now badly decayed stump with "WBT" scribe S.40°W. 50.2 ft.

Unrecorded BT's. as follows:

20" D. Fir Snag S.35°W. 54.0 ft., bark scribed "T20 R10W S17". *Fd. by:*

23" D. Fir Snag S.73°W. 46.3 ft., bark scribed "BT S7 T20S R10W". *HINTZ 4/83*

Set - Brass Cap at Cor. Mkd: County Surveyor's T 20 S R 10 W
(Reset "T" Iron alongside) Office S 7 S 8
1968 S 18 S 17 *SEE M 90-42 #98*

New BT's: 26" Maple N.81°E. 7.0 ft. mkd. T20S R10W S8 CS BT.

24" Maple S.22°E. 57.7 ft. mkd. T20S R10W S17 CS BT.

No other suitable trees available.

This corner lies on steep easterly slope approx. 50 ft. W. of small ravine.

Section Corner to Sections 8 - 9 - 16 - 17. 20

Found - 1951 G.L.O. Brass Cap, properly mkd., out of ground. *Fd. by:*

38", now 40" Fir, alive, N.35 3/4°E. 33.3 ft., healed blaze. *HINTZ 4/83*

18", now 18" Fir, alive, badly injured on blaze sde. S.25°E. 10.6 ft. *M 90-42*

16", now 18" Fir, alive, S.20°W. 8.6 ft., healed blaze.

22" Fir, now stump, N.32°W. 20.8 ft., scribe visible on unhealed blz.

Reset Brass Cap at Corner Point.

New BT's: 9" D. Fir S. 63° E. 20.4 ft. mkd. T20S R10W S16 CS BT.

No other trees available in Sec. 8.

This corner lies on steep southerly slope approx. 60 ft. S. of ridge top.

Section Corner to Sections 29 - 30 - 31 - 32. 21

Found - 1951 G.L.O. Brass Cap, properly mkd., out of ground.

12", now 15" Cedar, alive, S.49°W. 7.9 ft., scribe visible on
nearly healed blaze.

N.W. BT. has slid downhill, now stump. S.E. BT. now stump in
proper position. *SEE CORNER NO. #107*

Reset Brass Cap at Corner Point.

New BT's: 10" D. Fir North 53.2 ft. mkd. T20S R10W S29 CS BT.

10" Maple S.67°E. 28.8 ft. mkd. T20S R10W S32 CS BT.

No trees available in Sec. 30. This corner lies on very steep southerly slope

Vernon "Ray" Tracy
Jack Heritage & V. Perron
April, 1968
C. S. File No. 53/66