

Douglas County Surveyor's Record of
Government Corners Renewed

T. 20-S. T. S. R. 10-W. R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

22

Section Corner: Secs. 19 & 30, T20-10W. and Secs. 24 & 25, T20-11W.
Found - Orig. 40", now 48" Fir, badly decayed stub, N.76°E. 9.2 ft.,
no scribe found.
Orig. 12", now 38" Fir, alive, S.3°E. 69.3 ft., old scar, opened prev.,
about 8" to false face.
Orig. 7", now 34" Fir, alive, S.61½°W. 29.0 ft., opened & find, "T20"
scribe & reverse under 70+ rings.
Orig. 8", now 40" Fir, alive, N.2°W. 70.6 ft. We do not open.
Set - Brass Cap at Cor. Mkd: County Surveyor's R T20S R
Office 11 S 24 S 19 10
1968 W S 25 S 30 W
New BT's: 7" D. Fir S.83°W. 21.7 ft. mkd. T20S R11W S25 CS BT.
12" D. Fir N.29°W. 27.8 ft. mkd. T20S R11W S24 CS BT.
14" Maple N.4°E. 24.6 ft. mkd. T20S R10W S19 CS BT.
14" Maple S.62°E. 26.5 ft. mkd. T20S R10W S30 CS BT.
Corner lies 30 ft. east of spur, sloping North.

FD. OK 6/86
D. BAKER
M102-12

23

Section Corner to Sections 16 - 17 - 20 - 21.
Found - 1951 G.L.O. Brass Cap, Gone.
66" Fir, alive, N.52°45'E. 132.0 ft., bark scribe (See C.S.16/58)
Orig. 32" Alder, alive, N.17°W. 26.4 ft., blaze decayed out.
30" Fir N.58½°E. 130.0 ft., alive & good condition.
30" Fir, S.69¼°E. 75.1 ft., alive & good condition.
All other 1951 BT's. down. T20S R10W
Set - Brass Cap at Cor. Mkd: County Surveyor's S 17 S 16
Office, 1968 S 20 S 21
No tree close for new bearing trees.
This corner lies in head of ravine on N.E. slope, very steep & brushy.

FD. by:
HINTZ
APR. 1983
M 90-42

Vernon "Ray" Tracy
Jack Heritage & V. Perron
March & April, 1968
C. S. File No. 53/66

24

Section Corner to Sections 17 - 18 - 19 - 20.
Found - 3/4" I. Pipe & BT's. as follows, recorded C.S.16/58.
17", now 19" Hemlock stump, N.69¼°E. 36.0 ft., scribe visible.
20", now 30" Hemlock stump, S.31°E. 4.2 ft., scribe visible.
All other BT's. down or gone. No trace of originals.
Set - Brass Cap at Cor. Mkd: County Surveyor's T20S R10W
(Deposit old pipe alongside) Office S 18 S 17 #105
1968 S 19 S 20
New BT's: 6" D. Fir S.48°W. 28.4 ft. mkd. T20S R10W S19 CS BT.
4" Hemlock N.48°W. 10.0 ft. mkd. S18 CS BT.
8" Alder N.84°E. 43.6 ft. mkd. T20S R10W S17 CS BT.
No trees suitable to S.E. This corner lies on moderate westerly slope.

FD. by:
HINTZ
4/83
M 90-42

RE-RENEWED SEE CORNER NO. #105

25

Township Corner: T20S.-T21S.-R.10W.-R.11W.
Found - 3/4" I. Pipe & BT's. as shown in Ren. #2, T20-10W.
20", now 28" Maple, alive, N.14°W. 15.2 ft., shows good scar.
We do not open.
4", now 20" Fir, alive, S.77¼°E. 42.9 ft. faint scar.
Rescribe: "T21S R10W S6 CS BT"
Set - Brass Cap at Cor. Mkd: County Surveyor's T20S 19 S 36 S 31 10
(Deposit old pipe alongside) Office, 1968 T21S W S 1 S 6 W
New BT: 15" D. Fir N.80°E. 83.6 ft. mkd. T20S R10W S31 CS BT.
This corner lies on very steep south slope approx. 300 ft. N. of
Smith River Road.

FD OK PER STUNTZNER
M109-13 OCT 1989

RE-RENEWED SEE CORNER NO. #127

26

1/4 Corner to Sections 18 and 19.
Found - Orig. 12", now 26" Maple, alive, N.45°E. 26.4 ft., open
& shows scribe on badly decayed blaze.
Rescribe: "1/4 S18 CS BT". T20S R10W
Set - Brass Cap at Cor. Mkd: County Surveyor's 1/4 S 18
Office, 1968 S 19
New BT: 30" Maple S.10°E. 11.9 ft. mkd. "1/4 S19 CS BT".
Note - No trace of Corner Tree or other Orig. BT's.
This corner lies on S.W. slope about 150 ft. E. of
Johnson Creek.

RE-RENEWED SEE CORNER NO. #102