

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 20 S. T. S. R. 10 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 91881

Section Corner to Sections 13 and 24, T20-11W.

Found - Unrecorded 1 1/4" I. Pipe at corner point.

Orig. 36", now 48" Fir, alive, S. 81° W. 29.6 ft., shows "T S24", bark scribe in poor condition. Rescribe: "T20S R11W S24 CS BT".

Orig. 15", now 30" Fir, alive, N. 74° W. 8.6 ft., shows good scar. Dont open. No trace original corner tree or other orig. BT's.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1968  
 (Reset Old Pipe Alongside)  

R	T 20 S	R
11W	S 13	10W
	S 24	

New BT: 15" Cedar N. 56° W. 15.6 ft. mkd: T20S R11W S13 CS BT.

Note - This corner lies on steep E. slope about 100 ft. above creek, course N. and 99.3 ft. N. 3 1/2° E. of CC. Secs. 18 & 19, T20-10W.

27

Closing Corner to Sections 18 and 19, T20-10W.

Found - 1/2" I. Pipe on N-S line, not at point for C.C., unrecorded.

(I.P. bears N. 85° E. 6.2 ft.)

Orig. 6", now 18" Maple, alive, N. 85° E. 39.6 ft., Open & find frag. scribe on decayed axe blaze. Rescribe: "CC S18 CS BT".

Orig. 6", now 14" Chittam, now decayed stub, hollow center, S. 76° E. 26.4 ft., no scribe. No trace other Orig. BT.

Set - Brass Cap at C. Cor. Mkd: County Surveyor's Office 1968  

R	T 20 S	R
11	S 18	10
W	S 19	W

New BT: 28" Maple S. 21° E. 41.7 ft. mkd. T20S R10W S19 CC CS BT.

Note - This corner lies 99.3 ft. S. 3 1/2° W. of Sec. Cor. 13 & 24, T20-11W. Creek course N. about 125 ft. E. of Cl. Corner.

4/12/68

28

East 1/4 Corner to Section 1, T20S-R10W.

Found - 1" I.P. filled with cement at corner point with BrassCap (1951) broken off.

Orig. 36", now 40" Fir, alive, S. 66° W. 16.5 ft., shows good scar. We do not open.

6" Yew S. 86 1/2° W. 38.9 ft., alive, scribe visible on partially healed blaze. (1951 BT)

Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1968  
 (Deposit old pipe alongside)  

R	T 20 S	R
10	1/4 S 1	9
W		W

Note - This corner lies on very steep N. slope approx. 50 ft. south of small creek, course N.W.

29

1/4 Corner to Sections 17 and 20.

Found - BT's. as recorded in Ren. #4, C.S. File 16/58 by Boyer.

36", now 48" Fir, alive, S. 81° E. 175.0 ft., scribed "1/4 S17 T20S R10W CS BT". No trace any corner pipes or other bearing trees.

At orig. cor. point, See letters by Boyer & Ganong, Feb. 1940, C.S. 16/58.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1968  
 (Set 6 ft. steel fence post alongside B.C.)  

T 20 S	R 10 W
1/4 S 17	
S 20	

New BT: 9" Ash N. 30° E. 354.0 ft. mkd. "1/4 S17 CS BT". No other trees available on west side of river.

Note - Boyer's BT. is on east side of river. Also point of Boyer's BT proportioned 1/4 corner bears S. 57° W. 103.3 ft. Corner falls in E. G. Dunn's field approx. 90 ft. west of N. Fork of Smith River.

Fd. by:  
HINTZ 1983  
Apr. 1983  
M 90-42  
1993-0072A/B  
4-1-93

30

North 1/4 Corner to Section 2 only, T21-10W.

Found - No trace of Brass Cap. - 1951 BT's. as follows:

60", now 60" D. Fir, S. 6° E. 63.4 ft., alive, blaze pitched over & healing

20", now 26" Hemlock, alive, S. 47° W. 36.3 ft., scrb. mks. vis. on heald. blz

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968  
 (6' steel fence post alongside Brass Cap)  

T 20 S	R10W 1/4	S 2
T 21 S		

Note - The 1/4 corner of Sec. 35, T20-10W bears N. 87 3/4° W. 13.9 ft.

This corner lies on edge of new logging road, course N. 30° W. - S. 30° E.

May 8, 1968

31

Vernon "Ray" Tracy  
Jack Heritage & V. Perron  
April, 1968  
C. S. File No. 53/66

Fd. OK 4/87  
R. HINTZ  
M 104-9

C. S.  
File  
No.  
54/1