

Douglas County Surveyor's Record of  
Government Corners Renewed

20 T. S. 10 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

56  
Sec. 35 and 36 T20-10 and Sec. 2 T21-10 Section corner between 35 & 36 only  
Found: U.S GLO Brass cap(1951) properly marked:  
The 1892 bearing trees noted during the 1951 resurvey are both down.  
We find them to be in their record positions.  
BT's - A 31" D Fir bears West 30.2 ft., scribed "T20S R10W S35 CS BT" on a double blaze.  
A 25" Hemlock bears N37°W., 31.9 ft., scribed "T20S R10W S35 CS BT" on a double blaze.  
Note: The NE Corner of Sec. 2, T21S R10W A Brass cap, bears S89°15'E., 86.5 ft. This corner is located on top of a ridge at the SW corner of a clear-cut unit. Compass Declination Setting: 20° East. 11/12/75

Gary L Langlitz  
Clell E Goodv  
A Vic. Cangie  
M. Lenora Lad  
CS 57/39  
11/12/75

57  
Sec. 36 T20-10 and Sec. 2 and 1 T21-10 Section corner between 1 & 2 only  
Found: U.S. GLO Brass cap leaning to south after apparent bulldozer damage properly marked.  
BT's - no identifiable trace of the S E 1919 Bt. The rotting remains of the SW 1919 BT are in their record position with reference to the 1951 resurvey. This tree is now down and any identifying marks are buried. The southeast BT marked in 1951 is down, bearing S42 3/4°E., 23.1 ft., with scribing visible on an unhealed blaze.  
We reset the Brass cap and the remains of the 1919 Iron post in the proper position and add the following markings to the brass cap. "CS 1975"  
New BT's- a 28" Hemlock bears S53°E., 41.7 ft., scribed " T21S R10W S1 CS BT" on a double blaze.  
a 17" D. Fir bears S22°W., 35.2ft, scribed "T21S R10W S2 CS BT" on a double blaze.  
Note: The SW cor. sec. 36 T20S R10W, a brass cap bears N89°15'W., 86.5 ft. This corner is located on a ridgetop near the SW Corner of a clearcut unit. 11/12/75

JAN 76

Center 1/4 for Section 36  
Set - Iron Rod Post  
From which:  
Steel fence post set by BLM bears S.18°E., 21.95 ft.  
6" Chittum, bears S.24°15'W., 26.9 ft.  
12" Hemlock, bears N.74°23'W., 56.1 ft.  
8/25/76

58  
F.D. 10/84  
R. STUTEMER  
M 97-80  
(Also fd. 1975  
B.L.M. UNRECORDED  
INFO.)

Forrest J. Ha s  
For: Internat ional  
Paper Co.  
August 25, 1976  
M 61 - 31

59  
Section corner for 2, 1, 11 and 12.  
Found - 1952 monument not found. (several trees are down and have rolled over this area).  
Found a squared wooden post at section corner (not of record).  
An 8" Hemlock now a badly decayed stump bears N.31 3/4°E., 17.8 ft. Face is nearly rotted out, fragmentary scribe marks visible near edge of blaze.  
A 40" Cedar now 48" bears S.13 3/4°W., 27.1 ft. Tree marked "T20S R10W S11 BT" on open blaze.  
A 8" Hemlock now 9", bears N.33°W., 39.3 ft. (Rec. N.35 1/4°W., 38.0 ft.) Tree has partially healed single blaze.  
SE 40" Fir is gone.  
Set - Brass cap at section corner marked "Douglas Co. Surveyor"  
T 20 S R 10 W  
S 2 | S 1  
S11 | S12  
1977

Larry E. Monrean  
Rod Kimberling  
Doug. Co. Surv  
Office  
April 6, 1977  
C.S. 59/31

Place wooden post along south edge of cap.  
New BT's- A Maple, 13", bears S.44°E., 29.1 ft. Tree double blazed and scribed "S12 CS BT".  
An Alder, 15", bears N.68 1/2°E., 25.0 ft. Tree double blazed and scribed "T20S R10W S1 CS BT".

4/6/77  
60  
N E corner Govt. Lot 8, Sec. 5  
Found - unrecorded 3/4" I. P. at the NE corner Lot 8.  
BT's - I witness this lot corner by marking the following bearing trees:  
26" Fir bears N.63°E., 3.4 ft. (S 4 BT)  
12" Fir bears N.3°W., 19.2 ft. (S 5 BT)  
Note: The Northeast corner of Sec. 5 bears N. 0°46'13" W. (True), 456.29 ft.

Richard J. Hintz  
For: Ford Investors  
Aug. 13, 1977  
C.S. 58/121

JAN 78