

Douglas County Surveyor's Record of
Government Corners Renewed

20 T. S. 11 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

19

C. S. File
No. 51/29

Center $\frac{1}{4}$ Corner Section 17.
I Set a Pipe & mark the following BT's:
Spruce 38" DBH, bears N.62°00'W., 18.2 ft.
Spruce 28" DBH, bears East 25.8 ft.

20

Warren D.
Hootman
For Crown
Zellerbach
C.S. File 51/196-M20-44

Witness Corner for the Center of Section 8.
Set W. C. 30.0 ft. South of the true corner position by setting
a capped pipe and marking a:
6" Spruce N.26°15'E. 8.6 feet
10" Spruce S.74°00'E. 10.7 feet

FD. OK. Feb. 1970 V.R.T. C.S. 53/66

21

H.L. Eppstein Township Corner
Frank Cain

S36	S31	T20S
S 1	S 6	T21S
R11W	R10W	

Wit : Set Corner from old Witness Tree in Sec. 6, Maple.
W. Dailey Set - $\frac{3}{4}$ " x 4" Galv. Iron Pipe, Mkd: new trees as follows:
Jan. 25, 4" Fir bears S.77°15'E. 65 lks.
1929 10" Maple S.27°W. 17 lks.
20" Maple bears N.14°W. 23 lks.
REN. CO. Vol. 1 No trees near in Section 31.
Pg. 7

REN. CO. Vol. 1
Pg. 7

22

Clifford A. Stephens
For Coos Head Timber
Filed April 1958
C.S. 42/362
Map File M 10 - 3

Section Corner to Secs. 25 and 36, T20-11W. & Sec. 30 & 31, T20-10W.
Found - 3 Orig. BT's., as follows:
Maple 24" bears N.29°W. 25.0 ft. (old face at base of tree.
New face approx. 4 ft. above the ground line, has been
rescribed in unrecorded survey.
Maple Stump 24" bears S.35°W. 39.6 ft. (remains of tree & old
face still visible)
22" Maple bears N.45°E. approx. 55.0 ft. (uprooted & down).
New BT: A Fir 60" bears S.18°W. 70.3 ft. (Scribed)
Set - $\frac{5}{8}$ " re-enforcing rod for the corner & post. Set distances
from BT's. as called for. The Orig. bearings did not check.

RE-RENEWED. SEE CORNER NO. #77
SEE CORNER NO. #77
SEE REN. #1

23

Map File M 22 - 36

West $\frac{1}{4}$ Corner of Sec. 18, T20 S., R. 11 W.
Find $1\frac{1}{2}$ " iron pipe for the W $\frac{1}{4}$ Corner which was witnessed by:
30" Spruce S.24°E. 35.40 ft. (now a windfall)
60" Doug. Fir N.12 $\frac{1}{2}$ °E. 95.25 ft.
I mark an - Alder 16", S. 60° E., 69.00 ft.

24

$\frac{1}{4}$ Corner of Sec. 13 only, T20S R12W.
Find a 1" iron pipe, said corner being witnessed as follows:
24" Spruce Snag S. 3° W., 27.10 ft. (Orig. BT)
I mark new trees as follows:
32" Hemlock S.50°W., 37.10 ft.
Schoolmarm Spruce N.52°W. 63.10 ft.

RE-RENEWED. SEE CORNER NO. #190

25

Warren D. Hootman
For Crown Zellerbach Corp.
January 1963
C.S. File No. 22/36 51/249 Map File M 22 - 36

Closing Corner Sections 19 and 30, T20S R11W.
Found - Post marking corner position. The Orig. 18" spruce N.44°E.
21.78 ft. and the Orig. 20" Hemlock S.80°W., 14.52 ft.
are windfalls; the Hemlock SE is apparently gone.
The post agrees with the closest position we can establish
with the position of the BT's.
I reset this corner with a 1" brass capped pipe and mark New BT's as follows:
4" Hemlock S.78°E., 10.7 ft.
4" Western Red Cedar S.4°W., 7.8 ft.

RE-RENEWED. SEE CORNER NO. #215

26

West $\frac{1}{4}$ Corner for Sec. 19, T20-11W. Set at the midpoint betwn. CC.
Secs. 18 & 19, 19 & 30. 1" Brass capped pipe witnessed by:
8" D. Fir N.32°E., 20.3 feet.
6" D. Fir S.63°E., 6.8 feet.

FD OK
2/93
By John Miner
M 116-56