

Douglas County Surveyor's Record of
Government Corners Renewed

T 20 T. S. R 11 R. W. W. M.

FOUR-CHAPMAN CO., EUGENE, ORE. 21881

214

Section Corner for Secs. 24 and 25 only of T.20-12
 Found - 3" dia. brass cap on a 1 1/4" O.D. Iron pipe, protruding 12" above ground. Ren. No. 29
 24" now 60" dia. 8 ft. high Spruce stump, no blazes or scribing found, bears S.38°E., 40.8 ft. (Rec. S.35°E., 38.3 ft.) Orig.
 40" now 56" dia. 7 ft. high Spruce stump, with an axed "X" facing BC/IP and scribing found, illegible scribe marks and a "W" found facing S.70°W., on a previously opened blaze, bears N.15°E., 25.1 ft. (agrees with record) Orig. BT.
 3" now 10" dia. down and rotted Spruce, no blazes or scribing found, roots bears S.25°W., 46.2 ft. (agrees w/rec) Orig. (?)
 Unrecorded 28" dia. R.Cedar with a healed blaze, bears S.20°E., 15.6 ft. (tag dated 1968, N.20°W 15.0 ft.)
 Bew BTs - 14" R.Cedar double blazed and scribed "T20S R12W S24 CS BT" bears N.46°W., 2.8 ft.
 21" dia. Hemlock double blazed and scribed "T20S R12W S25 CS BT" bears S.52°W., 43.5 ft.

6/9/92

215

Section Corner for Secs. 19 and 30 only .
 Found - 3" dia. brass cap on a 1 1/4" O.D. Iron pipe, protruding 12" above ground. Ren. No. 25
 18" now 24" dia. uprooted and down rotting spruce trunk is earth covered, root hole bears N.44°E., 21.8 ft. (agrees w/rec.) Orig
 20" now 30" dia. uprooted and down rotting Hemlock, trunk unhearthed, a blaze with illegible scribe marks found. Root hole bears S.80°W., 14.5 ft. (agrees w/rec) Orig.
 8" dia. Hemlock now roots found, bears S.66 1/2°E., 21.1 ft. Orig. BT (?)
 4" now 21" dia. Hemlock with a fully healed single blaze facing N.30°W., bears S.78°E., 10.7 ft. Ren. No. 25
 4" now 12" dia. R.Cedar with a fully healed single blaze, bears S.4°W., 7.1 ft. (Rec. S.4&W., 7.8 ft. Ren. No. 25
 New BTs - 13" dia. Hemlock double blazed and scribed "CC T20S R11W S19 CS BT" bears N.64°E., 43.1 ft.
 21" dia. D.Fir double blazed and scribed "CC T20S R11W S30 CS BT" bears S.36°E., 13.6 ft.

6/10/92

1/4 Corner for Sec. 19 and 20. Ren. No. 56
 Set - 1" X 30" IP with 2" Brass cap stamped T20S R11W 1/4 S19 S20 1993 LS2052

216

New BTs -
 11" Spruce S39°E 0.1' Scribed 1/4 S20 BT
 14" Spruce S6°W 13.8' Scribed 1/4 S19 BT
 11" Spruce N38°W 19.3' Scribed 1/4 S19 BT
 8" DF N76°E 23.0' Scribed 1/4 S20 BT

Section Corner for Sections 19,20,29, and 30

217 2/93

Found -
 2" Alum. pipe (Cs 51/311) SW 0.7' Ren. No. 42, from found 3/4" iron pipe Ren. No. 61 with Doug. Co. brass cap 8" above ground. (CS 53/66).
 41" Doug. fir stump S62°E 13.7' (GLO)
 52" Doug. fir stump N80°W 19.8' (CS 51/311)
 3/4" iron rod N4°E 9.8' (CS53/66)
 3/4" iron rod N3°E 15.1' (CS 53/66)

New BTs-
 19" Hem. S62°W 31.1' scribed S19 T20S R11W BT
 8" Spruce N7°W 7.5' scribed S20 T20S R11W BT

2/93

Section Corner for Sections 17,18,19,and 20

218

Found -
 3/4 " iron pipe 1.5' above ground.
 35" Spruce stump N30°E 49.9' to face. Original scribe visable.

New BTs -
 12" Alder S27°E 27.4' to spike side center, Bark scribed S20 T20S R11W BT.
 14" Alder S6°W 18.9' to spike side center, bark scribed S19 T20S R11W BT

2/93

Douglas County
 Surveyors Office
 Randall Smith
 Stephen Flause
 June, 1992
 C.S. File 64/26

John Minor
 For: Menasha
 Corp.
 Feb. 1993
 M 116 - 56