

Douglas County Surveyor's Record of
Government Corners Renewed

T. 20 S. T. S. R. 11 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

33

1/4 Corner to Sections 28 and 33.

Found - 48" Old Maple, Corner Tree, hole in north side, tree hollow,
no marks found.

48" Old Maple N.75 1/2°W. 34.3 ft., cut open & fd. good scribing "4s".
No trace of Alder to S. W.

At Base of corner tree (North Side) Set Brass Cap Mkd:

County Surveyor's Office, 1964 T20S R11W 1/4 S28
S33

FD. OK 10/81
R. STUNTZNER
M 91-53

New BT's: 66" D. Fir N.11°E. 63.1 ft. Mkd: 1/4 S28 CS BT., dist. from Cap.,
Add 2.5 more to center of Corner Tree.

11" Alder S.49°W. 28.0 ft. Mkd: 1/4 S33 CS BT. Dist. from Brass Cap,
Subt. 2.5 ft. for center of corner tree.

34

Section Corner to Secs. 28 - 29 - 32 - 33.

Found - 48" Old Fir Stump S.46°E. 6.0 ft., opened & found good scribing "B".
Rotten Spruce Stump N.60°E. 39.6 ft., too far gone to find scars, scbng.

Rotten remnants of Hemlock Stump S.13°W. 37 ft. (not 38.9 ft.)

No trace of Corner Tree or N. W. BT.

Set - Brass Cap at Cor. Mkd: County Surveyor's T.20S R11W S29 | S28
Office, 1964 S32 | S33

New BT's: 10" D. Fir N.12°W. 11.0 ft. Mkd: T20S R11W S29 CS BT.

8" D. Fir N.17°E. 12.4 ft. Mkd: T20S R11W S28 CS BT.

13" D. Fir S. 9°W. 18.5 ft. Mkd: T20S R11W S32 CS BT.

11" D. Fir S.69°E. 33.0 ft. Mkd: T20S R11W S33 CS BT.

RE-RENEWED SEE CORNER NO. #143

35

Section Corner to Sections 20 - 21 - 28 - 29.

Found - 60" Spruce, prev. opened on N.E. face, scribing visible "20S".
No trace of any bearing trees.

Set - Brass Cap at Base of Cor. Tree (North Side) Mkd: S20 | S21
County Surveyor's Office, 1964 T20S R11W S29 | S28

New BT's: 7" Hemlock S.55°E. 38.4 ft. Mkd: T20S R11W S28 CS BT.

50" Spruce S.25°W. 23.8 ft. Mkd: T20S R11W S29 CS BT.

48" D. Fir N.52°E. 118.0 ft. Mkd: T20S R11W S21 CS BT.

Note - Corner is approx. 25 ft. south of small stream flowing west.

FD. OK
5/27/80
E. ALVARADO
C.S. 61/6

RE-RENEWED SEE CORNER NO. #137

36

1/4 Corner to Sections 23 and 24.

Found - 30" Red Cedar N.12°E. 29.0 ft., prev. opened, good scribing "BT".
Other Bearing Tree not found.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1964
T20S R11W 1/4 S23/S24

Rescribe - 30" Red Cedar N.12°E. 29.0 ft. Mkd: 1/4 S24 CS BT.

26" D. Fir S.41°E. 33.4 ft. Mkd: 1/4 S24 CS BT. (49 ft. at 47° slope).

No trees convenient W. of line.

Note - Corner is in bottom of draw, approx. 10 ft. S. of stream line.

FOUND IN GOOD COND. 6/69 BY FRAHAR C.S. 55/117

37

1/4 Corner to Sections 21 and 22.

Found - Corner Tree & Both BT's. have been uprooted & slid into canyon.
Corner set on affidavit of Albert Lam, See field notes C.S. 53/66.

Set - Brass Cap at Cor. Mkd: County Surveyor's T30S R11W 1/4 S21/S22
Office, 1964

New BT's: 10" Hemlock S.85°E. 76.0 ft. Mkd: 1/4 S22 CS BT.

14" Hemlock Snag S.16°W. 46.8 ft. Mkd: 1/4 S21 CS BT. This Snag
on top of ridge. (62.6 ft. at 41 1/2° Slope)

Note - Corner is on very steep north slope.

FD. OK
OUT OF
GROUND -
5/28/80 SEE
C.S. 61/6

RE-RENEWED SEE CORNER NO. 210

38

Sec. Cor. to Secs. 33 & 34, T20-11W. & Sec. 3 & 4, T21-11W.

Found - 48" Fir S.55°W. 19.8 ft. (from old face) prev. opened, good
scribing visible on old face "B", upper scar visible.

Fir, uprooted & down, N.55°W. 31.0 ft., both scars visible

48" Fir Stump S.25°E. 11.9 ft. No scars visible, prob. cut too low.

No trace of N. E. Tree.

Set - Brass Cap at Cor. Mkd: County Surveyor's Off, 1964 T20 R11W S33 | S34
T21 R11W S4 | S3

New BT's: 9" Hemlock S.58°E. 27.4 ft. Mkd: T21S R11W S3 CS BT.

48" D. Fir S.55°W. 19.8 ft. (to face. Mkd: T21S R11W S4 CS BT. (old BT)

36" D. Fir N.17°W. 50.0 ft. Mkd: T20S R11W S33 CS BT. This BT. is
on top of ridge.

RE-RENEWED SEE CORNER NO. #111