

Douglas County Surveyor's Record of
Government Corners Renewed

T. 20 S. T. S. R. 11 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

54

$\frac{1}{4}$ Corner to Sections 20 and 21.
At the midpoint on E. line of Section 20, the E $\frac{1}{4}$ corner was established by driving into the ground a 1 $\frac{1}{2}$ " Iron Pipe, from which:
A 24" Red Cedar Stump bears N.17°E. 30.2 ft., scribed $\frac{1}{4}$ S BT.
A Red Cedar Stump 30" diwm. bears East, 56.8 ft. scribed $\frac{1}{4}$ S BT.
Both BT's are tagged and measured from the face.
Corner is approximately 50 ft. west of main creek bottom.

55

$\frac{1}{4}$ Corner to Sections 20 and 29.
The south line of the section was surveyed a few years ago by Gleason & Lamb and subsequently the S $\frac{1}{4}$ corner and the E 1/16 corner on that line were established.
At the S $\frac{1}{4}$ corner I set a 2" aluminum pipe from which:
A 16" Hemlock bears N. 38° 30' W. 37.2 ft. scribed $\frac{1}{4}$ S BT (Tagged)
Leitel Creek road bears west 100 ft. distant approximately.

56

$\frac{1}{4}$ Corner to Sections 19 and 20.
At the midpoint on W. line of Section 20, I set a 3" post for $\frac{1}{4}$ corner, from which:
A 24" Spruce bears N. 65° W. 19.8 ft.
A 12" Spruce bears N. 26° E. 1.5 ft.
(These trees face, but not scribed)
At a later date I will scribe the BT's. & set more durable monument.

FO. OK 8/2/77 L. MANREAN - Co. SURVEYOR OFFICE C.S. 59/38

57

Center of Section 20.
At the intersection point, I drive into the ground a 2" aluminum pipe for the center $\frac{1}{4}$ corner, from which:
A 10" Cedar bears N. 30° E. 7.7 ft. scribed C $\frac{1}{4}$ BT (tagged)
A 44" Fir bears N.1° 30' E. 64.5 ft. scribed C $\frac{1}{4}$ BT (Tagged)

sect 68

58

$\frac{1}{4}$ Corner to Sections 15 and 16.
Found - Remains of 5" Hemlock Corner Tree, fragments of scribe " $\frac{1}{4}$ S".
38" D.Fir, now stump, S.20 $\frac{1}{2}$ *W. 8.6 ft., shows good scar.
30" D.Fir, now stump, S.55 $\frac{1}{2}$ *E. 5.9 ft., badly burnt.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 20 S R 11 W
Office, 1968 $\frac{1}{4}$ S 16 S 15
New BT: 9" Hemlock S. 60* E. 42.6 ft. scribed $\frac{1}{4}$ S15 CS BT.
Note - 2 Iron Bolts $\frac{3}{4}$ " x 24" bear South 15.0 - 20.0 ft. 9/18/68

59

$\frac{1}{4}$ Corner to Sec. 33, T20-11W. and Sec. 4, T21-11W.
Set by proportionate measurmnt. The $\frac{1}{4}$ corner has been searched for but not found.
Set - 1" Iron Pipe.
Bark Scribed 32" Fir N. 50° W. 1.8 feet/
Scribed 42" Fir N. 82° E. 9.5 feet.
Jan. 23, 1969

60

Section Corner to Sections 29 - 30 - 31- 32.
Found - 36", now 48" D.Fir, S. 65° W. 33.0 ft., shows scar already opened, "BT" visible. No trace of other BT's.
Call on canyon 3 chs. south is good.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 20 S R 11 W
Office 1968 S 30 S 29
S 31 S 32
New BT's: 46" D.Fir S. 73° E. 37.1 ft. mkd: T20S R11W S32 CS BT.
38" D.Fir N. 83° E. 36.4 ft. mkd: T20S R11W S29 CS BT.
No good trees in reasonable distance for N. W. quadrant.

63

Ronald L. Durham
For Menasha Corp. & U.S. Plywood
Date 1966-67 Filed May, 1968
C.S. File No. 55/65 M 35 - 74

Vernon "Ray"
Tracy &
Crew
C.S. File
No. 53/66

Ronald E.
Stuntzner
For Timberland
Services, Inc.
1/23/69
C.S. File
55/103

John M. Powell
& Crew
9/19/68
C.S. File
No.
53/66