

Douglas County Surveyor's Record of
Government Corners Renewed

T 20 S. T. S. R. 11 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

61

Section Corner to Sections 19 - 20 - 29 - 30.
Found - 2" Pipe near Section Corner, See Ren. #42.
42" D.Fir Stump N.86°W. 20.6 ft. scribed S19 BT.
24" D.Fir, now stump, S.55°W. 4.0 ft., scribe visible.
30" D.Fir, now stump, S.51°E. 13.2 ft., shows good scar.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office T20S R11W
1968 S 19 | S 20
S 30 | S 29
New Bearing Objects: 3/4" I.Rod North 15.0 ft.
3/4" I.Rod North 10.0 ft.
2" Pipe S.31°W. 0.9 ft.
This corner lies north of flat bench approx. 100.0 ft.

RE-RENEWED, SEE CORNER NO. #217

John M. Powell
F. Jones & W. Penley
9/19/68 C.S. 53/66

62

1/4 Corner to Sections 7 and 8.
Found - Unrecorded 1" I.Pipe for corner.
Orig. 8", now 28" Fir, alive, S.43 1/2°E. 7.9 ft., prev. opened.
We Rescribe: "1/4 S8 CS BT".
No trace of Orig. N.W. BT.
18" Spruce bears N.73°W. 24.8 ft., shows scar, we open, no scribe.
New BT: 6" Spruce N.31°W. 20.8 ft. mkd: "1/4 S7 CS BT".
DO NOT SET BRASS CAP
This corner lies on west slope in dense brush.

Vernon Ray
Tracy &
Crew
6/25/69
C.S. File
No.
53/66

6/25/69

63

Section Corner Common to Sections 29 - 30 - 31 - 32.
Found - Orig. Doug. Fir BT Stump 46" in diam., bears S.66°W.
32.2 ft. with scribe marks visible. See Ren. #60.
41" Doug. Fir Stump bears S.74°E. 36.4 ft., scribe marks vis.
36" Doug. Fir Stump bears N.82°E. 35.1 ft., scribe marks vis.
Set - A Brass-Capped Iron Pipe, from which:
A 72" Steel Fence Post driven 30" into the ground, each
one driven 40 ft. from and on an East-West Line through
the corner.
A Post and Location poster beside the Leitell Creek Tie
Road bears N. 5° W. 298 ft. SEE ALSO REN. #73

Dennis A. Crowe
October, 1969
C.S. File No.
55/128

64

1/4 Corner to Section 17 and 20.
Found - No trace of Iron Pipe or N. E. BT., See Ren. #18.
(Due to corner falling in log landing)
24" Hemlock, now stob, S.16°W. 11.0 ft., scribe visible.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office T 20 S R11 W
(Steel Fence Post Set Alongside) 1969 1/4 S 17
S 20
Set - 3/4" Iron Rod bears North 20.0 ft.
New BT: 8" Hemlock S.26°E. 53.1 ft. mkd: "1/4 S20 CS BT".

9/22/69

65

Wit. Section Corner to Sections 8 - 9 - 16 - 17.
Found - No trace of I. Pipe in pasture, probably plowed up. Ren. #12.
23", now 29" Maple, S.56°E. 213.8 ft., shows scar.
30" Cedar, now ?, S.41°W.
Unable to get across creek at this time so by using 2 bearings &
1 distance, also information from property owner, I set Wit. Corner.
Set - Brass Cap at Wit. Cor. Mkd: County Surveyor's Office W. C. 90' S 8 | S 9
(Set Steel Fence Post Alongside) 1969 North to S 17 | S 16
Reblzd. & Rescrbd: 29" Maple S.79°E. 178.5 ft. mkd: "W.C. T20S R11W S16CS BT.
No other trees available.
This corner lies on N. bank of creek, about 15.0 ft. from centerline
of creek

RE-RENEWED, SEE CORNER NO. #212

9/23/69

John M. Powell
Frank Jones & W. Penley
Sept. 22, 1969
C.S. File 53/66