

Douglas County Surveyor's Record of
Government Corners Renewed

T 20 S. T. S. R. 11 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

79

1/4 Corner to Sections 5 and 8.
Reestablished by Hootman OLS 399 in 1957, See Ren. #11
Found - 1" Iron Pipe from which: 12" Alder bears N.41°E. 3.0 ft.
scribing visible, has FS tags.
10" alder bears S.82°E. 4.4 ft. scribing visible, has FS tags.
(Doug. Co. Tags)
Set - 2"x30" iron pipe with brass cap mkd: T 20 S R 11 W
5
Set 2 fence posts ± 5 ft. east facing south 8
5 ft. south facing east. 1970
650

FO 12/23/87
D. BAKER
M105-40

1/4 Corner common to Sections 7 and 8.
Found - 1" Pipe, (See Ren. #62), from which:
32" Fir bears S.43 1/2°E. 6.9 ft. (orig) face sealed over, with tag.
6" Spruce bears N.31°W. 20.8 ft. scribing visible, with tag.
20" Spruce bears N.70°W. 23.9 ft. scribing visible, with tag.
Set - 2"x30" Iron pipe with brass cap mkd: T 20 S R 11 W
7 | 8 1/4
Set 2 fence post with signs ± 5' E. facing N. 1970
± 5' S. facing W. 650

1/4 Corner common to Sections 8 and 9.
Found - 1" Pipe (See M 20 - 44), from which:
26" Fir Stump bears S.74°W. 4.6 ft. (orig) face chopped out,
scribing visible.
Set - 2"x30" Iron pipe with brass cap mkd: T 20 S R 11 W
8 | 9 1/4
from which 1970
18" Fir stump bears N.50°E. 35.0 ft. 650
scribed 1/4 BT, with tag.
Set 2 fence posts with signs ± 5.0' west facing south.
+ 5.0' south facing west.

Standard Corner for Sections 12 & 13 only, T20S-R12W.
Found - 1" Pipe & old Post (), from which
70" Fir bears N.51°E. 17.8 ft., old face chopped out, with tags.
40" Fir Shell bears S.22°W. 6.9 ft.
Set - 2"x30" iron pipe with brass cap mkd: R12 T 20 S R11W
12 | 7
13 | 1970
from which: 650
18" Spruce bears N.18°W. 28.7 ft. scribed
S12 R12 BT
6" Spruce bears S.20°W. 27.6 ft. scribed
S13 R12 BT.
Set 1 fence post ± 5 ft. west facing north.
Placed the 1" Pipe East of Corner.

1/4 Corner to Sections 18 and 19.
Found - 3/4" Alumn. Pipe, loosely set & BT. stumps, See M 22 - 36.
Do not find any orig. bearing trees.
24" Spruce Stump, poor condition, S.17°W. 15.5 ft., scribe barely visible
30" Spruce Stump, poor condition, N.59°W. 19.8 ft., scribe barely vis.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 20 S R 11 W
(Reset old pipe alongside) Office 1/4 S 18
1970 S 19
New BT's: 4" D. Fir S.54°E. 56.3 ft. mkd: "1/4 S19 CS BT".
4" Spruce N.20°W. 58.5 ft. mkd: "1/4 S18 CS BT"
Also Set - 5/8" I. Rod West 10.0 ft. & 5/8" I. Rod North 15.0 ft.
This corner lies about 50 ft. W. & 50 ft. S. of top of spur sloping N.W.
2/26/70

Section Corner to Sections 7 - 8 - 17 - 18.
Found - 1 1/4" I.P., as set by W. Hootman, See Ren. #14.
(M. Martin, land owner, says pipe has not been moved.)
No bearing Trees found due to roadway.
New BT: 17" Spruce N.73°E. 172.9 ft. mkd: "T20S R11W S8 CS BT" on upper side
of road. No other suitable trees close. Cor. lies under B.P.A.
Trans. Line about on center line. USFS line marker on Co. Rd. 1100 ft.
East of Corner

TOM O. MCGULLOUGH
FOR: U. S. FOREST SERVICE - Siuslaw Nat'l. Forest
February, 1970
C. S. File No. 55/142

Vernon "Ray" Tracy
J. Heritage & V. Perron
Feb. 1970 C.S. File 53/66

RE-RENEWED SEE CORNER NO. #136

FD OK By Minor
2/1/83 John Miller-56

FD OK 7/88
D. BAKER
M106-67

FD 7/88
D. BAKER
M106-67