

Douglas County Surveyor's Record of
Government Corners Renewed

T. 20 S. T. S. R. 11 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97101

89

$\frac{1}{4}$ Corner to Sections 6 and 7.
Found - No trace of Orig. BT's., however, find old 36", now 60" Fir
Line Tree mkd. with 2 notches on East & West sides at foot
of hill, as described. This Line Tree bears West 122.1 ft.
From this point set for temp. $\frac{1}{4}$ corner, we chain E. to top of spur,
Record call distance was 528.0 ft., we measure 529.2 ft. Because the
calls check so well from old line tree & spur, we Set:
Set - Brass Cap at Cor. Mkd: County Surveyor's T 20 S R 11 W
(Set 6.0' Steel fence post Office $\frac{1}{4}$ S 6
on W. side of Brass Cap) 1970 S 7
New BT's: 10" D. Fir S. 26° W. 78.2 ft. mkd: " $\frac{1}{4}$ S 7 CS BT".
60" D. Fir West 122.1 ft. mkd: " $\frac{1}{4}$ S 6 CS BT".
This corner lies on west edge of old logging road.

FD OK 7/28
D. BAKER
M 106-67

3/30/70

90

Closing Corner Sections 7 and 18, T20-11W.
Found - 1 $\frac{1}{2}$ " Iron Pipe & BT's. as called for in Ren. #199.
48", now 54" Fir, alive, N. 54° E. 108.0 ft. shows good scar, we tag.
7", now 9" Spruce, dead, decaying, S. 60° W. 10.2 ft., scribe visible.
Orig. 18" Alder snag, N. 69° E. 23.3 ft., scribe visible, by #399.
Bearing tree gone.
New BT: 22" Spruce N. 43° E. 31.4 ft., mkd: "T20S R11W S7 CC CS BT."
20" Spruce S. 63° E. 62.5 ft. mkd: "T20S R11W S18CC CS BT."
This closing corner lies on E. edge of clear cut which extends N. to
corner of Sections 12 and 13, See Ren. #82.

RENEWED, SEE CORNER NO. #199

3/31/70

91

East $\frac{1}{4}$ Corner to Section 12 only, T20-12W.
Found - Old 1" Bolt, badly rusted and BT's. by R. Lecklider, See Ren. #6, T20-12W
38", now 40" Fir, alive, N. 72° W. 65.2 ft., lower blaze healed,
upper blaze, nearly healed.
6", now 12" Hemlock, alive, South 69.4 ft., blazes healed.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 20 S R 12 W
(Reset Old Bolt alongside) Office, 1970 $\frac{1}{4}$ S12 R11W
This corner lies 20 ft. north of creek bottom approx. 350 ft. East of
very old, unusable logging road.
Found only badly decayed remains of stump of Orig. BT.

FD OK
D. BAKER
M 106-67

3/30/70

92

Renew Corner # 3 of H. E. S. 190. (Sec. 10)
Found - Old Corner Stone, in place, broken, fragmentary marks &
"190" left.
Orig. 12", now 24" Fir, N. 21 $\frac{1}{4}$ ° E. 31.7 ft. (slope Meas.) Alive, shows
good scar, We tag.
Orig. 26", now 32" Fir S. 31 $\frac{1}{2}$ ° E. 55.4 ft. (level) Alive, shows very good
scar. We tag.
Set - Brass Cap at Cor. Mkd: County Surveyor's T. 20 S. R. 11 W.
Office, 1970 Cor. #3 | HES 190
We do not mark New BT's. This corner lies on very steep
southerly slope approx. 150 ft. S. of top of spur, ridge sloping N.W.

Renew Corner #1 of H. E. S. 190. FD OK Daniel 5/93
BY Baker 4118-6
Found - Sandstone Rock, broken, and 1916 USFS Brass Cap mkd: "1 HES 190"
Concrete showing thru I.P. just under cap.
Orig. 32", now 42" Fir, alive, N. 54° W. 29.0 ft., shows good scar, we tag.
Orig. 12", now 26" Fir, alive, S. 18 $\frac{1}{4}$ ° W. 33.7 ft., shows good scar.
We Rescribe " $\frac{1}{4}$ S10 CS 1 HES 190 BT".
Set - Brass Cap at Cor. Mkd: County Surveyor's T 20 S R 11 W
(Deposit Old Pipe & Office $\frac{1}{4}$ S 3
Rocks Alongside) 1970 S 10 | 1 HES 190
New BT: 14" D. Fir N. 70° W. 10.5 ft. mkd: " $\frac{1}{4}$ S 3 CS 1 HES 190 BT".
This cor. lies on moderate N.W. slope approx. 300 ft. E. of creek, course S.

Vernon "Ray" Tracy
Jack Heritage & V. Perron
March and April 1970
C.S. File No. 53/66