

Douglas County Surveyor's Record of
Government Corners Renewed

T. 20 S. T. S. R. 12 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

18

West $\frac{1}{4}$ Corner of Sec. 18, T20S., R11W.
Find $1\frac{1}{2}$ " iron pipe for the $W\frac{1}{4}$ Cor. which was witnessed by:
30" Spruce S. $2\frac{1}{2}$ ° E. 35.40 ft. (now a windfall)
60" D. Fir N. $12\frac{1}{2}$ ° E. 95.25 ft.
I mark a - Alder 16", S. 60° E., 69.00 ft.

19

$\frac{1}{4}$ Corner of Sec. 13 only, T20S R12W.
Find a 1" iron pipe, said corner being witnessed as follows:
24" Spruce Snag S. 3° W., 27.10 ft. (Orig. BT.)
I mark new trees as follows: 32" Hemlock S. 50° W., 37.10 ft.
Schoolmarm Spruce N. 52° W. 63.10 ft.

20

Closing Corner Sections 19 and 30, T20S R11W.
Found - Post marking corner position. The orig. 18" Spruce N. 44° E.
21.78 ft. and the Orig. 20" Hemlock S. 80° W., 14.52 ft. are
windfalls; the Hemlock SE is apparently gone. The post
agrees with the closest position we can establish with the
position of the BT's.
I reset this corner with a 1" brass capped pipe and mark New BT's. as follows:
4" Hemlock S. 78° E., 10.7 feet.
4" Western Red Cedar S. 4° W., 7.8 ft.

21

West $\frac{1}{4}$ Corner for Sec. 19, T20S R11W. Set at midpoint between CC. Secs. 18
& 19, 19 & 30. 1" Brass capped pipe witnessed by:
8" D. Fir N. 32° E., 20.3 feet.
6" D. Fir S. 63° E., 6.8 feet.

22

$\frac{1}{4}$ Corner Sections 24 and 25.
Set on line between the Sec. Cors. & at the proportioned distance.
 $\frac{1}{4}$ Corner is a 1" brass capped pipe witnessed by:
5" Alder S. 5° W., 9.0 ft.
Spruce Stump N. 85° E., 12.0 ft.

23

Center of Section 24, CS $\frac{1}{4}$.
1" Brass capped pipe witnessed by:
36" D. Fir N. 28° E. 29.0 ft.
48" D. Fir S. 27° W. 4.0 ft.

24

$\frac{1}{4}$ Corner to Sections 13 and 24 .
Set - 1" brass capped pipe, witnessed as follows:
8" Hemlock S. 70° W., 30.5 feet.
32" Spruce N. 60° W., 50.6 feet.
This corner is about 10 ft. West of the west cut slope of the Forest
Service Road.

25

Section Corner to Sections 24 and 25 only, T20-12W.
This corner lays 40 ft. East of a small creek and 37 ft. South of a
logging road up the S. Side of Perkins Creek. The corner is
witnessed by the stumps of the original spruce trees to the East,
which were: 40" Spruce N. 15° E., 25.08 ft.
24" Spruce S. 35° E., 38.28 ft.
I set a new corner with a 1" brass capped pipe.

Warren D. Hootman
For Crown Zellerbach Corp.
January 30, 1963
C. S. File No. 51/249 Map File M 22 - 36.

RE-RENEWED SEE CORNER NO. #109
RE-RENEWED SEE CORNER NO. #120
FOOK BY John Diner 2/93 4/11/56
FOOK M 101-31 C. MULKINS 10/30/87
RE-RENEWED SEE CORNER NO. #119