

Douglas County Surveyor's Record of
Government Corners Renewed

T. 20 S. T. S. R. 12 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97401

Township Corner : R 12 W $\frac{S 36}{S 1} \frac{S 31}{S 6}$ R11W T19S T20S *FD. OK. 6-81 P. Fox - M 88-13* **26**

Found - 36" D. Fir N. 49 $\frac{1}{2}$ ° E. 7.3 ft., cut open & found good scribing. Remnant of Alder Stump N. 47° W. 24.4 ft., small fragment of reverse scribing on overgrowth of old face.

No trace of S. E. or S. W. BT's.

Set - Brass Cap at Cor. Mkd: Co. Surveyor's Office, 1964 $\frac{S 36}{S 1} \frac{S 31}{S 6}$ R12W R11W T20S

Blaze & Rescribe - 36" D. Fir N. 49 $\frac{1}{2}$ ° E. 7.3 ft. Mkd: T19S R11W S31 CS BT.

New BT's: 26" D. Fir S. 50° E. 11.0 ft. Mkd: T20S R11W S6 CS BT.

36" D. Fir S. 35° W. 14.0 ft. Mkd: T20S R12 W S1 CS BT.

No trees available to N.W. - Township corner is on nose of small, very steep, spur, slopping N.E.

Milo E. Godfrey & Crew
Doug. Co. Park Dept.
Aug. 17, 1964
C. S. File No. 53/65

Section Corner to Sections 1 and 12.

Set at position for $\frac{1}{4}$ Corner, as computed from survey of Section Line and between ridges. *SEE ALSO - REN. # 116*

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1964 $\frac{S 1}{S 12}$ T20S R12W $\frac{1}{4}$ S 1

New BT's: 36" Spruce S. 63° E. 18.0 ft. Mkd: $\frac{1}{4}$ S12 CS BT.

36" Spruce N. 72 $\frac{1}{2}$ ° W. 47.2 ft. Mkd: $\frac{1}{4}$ S 1 CS BT.

South $\frac{1}{4}$ Corner of Section 36.

Drive 2" x 3 ft. Alum. Pipe 2 ft. into ground, from which: 45" Red Cedar bears S. 21° E. 11.9 ft., Orig. BT., face has been chopped out.

New BT: 34" Fir bears N. 21 $\frac{1}{2}$ ° E. 35.0 ft. scribed S36 BT.

24" Fir Snag bears N. 17° W. 23.7 ft. with a tag & Painted Red.

$\frac{1}{4}$ Corner to Sections 10 and 11. *SEE ALSO - REN. # 68*

Found - 2" I. P., Orig. Sp. B.T. Stump bears S. 16° E. 7.9 feet.

New BT's: 12" Hemlock bears S. 81 $\frac{1}{2}$ ° E. 15.2 ft. $\frac{1}{4}$ S 11 B. T. (metal tag)

12" Fir bears S. 51 $\frac{1}{2}$ ° W. 18.6 ft. $\frac{1}{4}$ S 10 BT.

October, 1966

Closing Township Corner:

Found - Orig. 40"?, now 22" Fir Stump, N. 6° E. 21.1 ft., shows "S R11W" on opnd. blaze, probably 14" when mkd. Ring Ct. 60+ yrs.

Orig. 40", now 48" Fir, tipped out stump, laying face down, N. 43° W. 20.5 ft. No trace of SE. BT. *FD. OK 3/80 R. HINTZ M 79-30* **# 144**

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1967 $\frac{S 31}{S 6}$ T 20 S CC R11W T 21 S R12W

New BT: 30" D. Fir Stump S. 20° E. 6.3 ft. mkd. T21S R11W S6 CC CS BT.

Note - This corner lies on very steep, N.E. slope, approx. 195 ft. south of Twp. Cor. of T20 & 21S., R. 12W., see below.

Brass Cap is set on east side and under 30" log.

Township Corner - T 20 S $\frac{S 36}{S 1}$ R12W R11W *FD. OK 3/80 R. HINTZ M 79-30* **31**

Found - Orig. 15", now approx. 30" Fir, N. 5 $\frac{1}{2}$ ° E. 28.4 ft., now shattered stump with "T20S 11W 31 BT" scribe revealed.

Orig. 15", now 30" Fir, 20' high snag, S. 85° W. 40.9 ft., shows faint scar. **# 145**

Orig. 12", now 18" Fir, badly decayed stump, with frag. reverse scribe marks, N. 8 $\frac{1}{2}$ ° W. 31.7 ft. No trace of S.E. BT.

Unrecorded 40" Fir Stump bears N. 48° E. 40.1 ft. mkd. "S31 BT".

New BT: 24" Hemlock N. 15 $\frac{1}{2}$ ° E. 30.1 ft. mkd. T20S R11W S31 CS BT.

Note - This corner lies on moderate SE. slope approx. 100' S. of top of ridge. Cl. Corner, Ren. #30, bears S. approx. 195 ft. This area logged in recent years.

(MICROFILM TO HERE 10/67)

M.E. Godfrey
For. M.M. Berry
Sept. 1964
C. S. File
No. 53/65
RM 1 - 47

Ronald Durha
For Menasha
Corp.
March 1965
C. S. File
No. 51/311

Richard J.
Hintz
For. G. Karjiloff
10/1966
Map File
M 32 - 31

Vernon "Ray" Tracy
Jack Heritage & E. West
March, 1967
C.S. File No. 54/1