

Douglas County Surveyor's Record of
Government Corners Renewed

T 20 T. S. R 12 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21081

87

Meander Corner, Secs. 3 and 10.
Found - Orig. BT's and 6x6x3 ft. cedar post scribed CS MC called for at 15.60 chains. AS the position of post did not check with notes,
I set - 1 1/2" x 4' I. Post on South side of post from which bears:
Orig. 14" Hemlock, now 18" and dead but standing, S.63°E., 12.54 ft. to boat spike, scribed BT, rest covered. Cruiser's mark "X".
Orig. 24" Hemlock, now 30" stump, N.69°E., 17.82 ft. to boat spike scribed R12W. The upper portion has been cut off. BT covered
I mark: With crayon, 30" Cedar, S.19°15'E., 13.1 ft. to nail S10 MC RP BT.
Set - 2x2x5 Cedar limb in Iron Pipe. 4/14/43

88

Meander Corner, Secs. 3 and 10.
Found - Orig. 24" Hemlock BT called for at 12.05 chains, has fallen over to the North, blazed face up.
The other 24" Hemlock has fallen over and mostly rotted away.
Reset - M.C. as near as possible from these two trees using 1 1/2" x4' Iron Pipe and 2x2x5 ft. Cedar post, crayon mkd: S3, S10 M.C. W.G. Corbitt 1943, from which bears:
Orig. 24" Hemlock N.2°30'W., 12.7 ft. to nail scribed B.T.
4" Alder N.48°W., 6.6 ft. to nail
4' Fir stump S.45°15'W., 31.8 ft. to nail crayon marked. 4/14/43

89

1/4 Corner for Secs. 4 and 9. SEE ALSO: 1974 Rev. #46
Found - Bearing tree to 1/4 bearing SW which is a dead Spruce snag. Although it showed no scar on the surface, I cut into wood and found scribe marks 1/4S, so
Reset - Corner from that tree using 1 1/2" Iron Pipe & 2x2x5 ft. Spruce post crayon mkd: 1/4 S4-S9 Aug. 10, 1943, W.G. Corbitt, from which bears:
Orig. 12" Fir, now 25" Spruce snag 30' high, S.27°W., 17.82 ft. to face scribed 1/4S and 17.6 ft. to nail.
I reference - 4 ft. Spruce S.38°15'E., 45.8 ft. crayon mkd. RP BT S9 out 45.8'.
Mkd: 5 ft. Fir N.89°30'W., 24.7 ft. to nail crayon mkd: RP BT S4 out 24.7'.
Corner stands on steep side hill 17.0 fto east of Creek. Course South by East. 8/10/43

90

1/4 Corner for Secs. 10 and 15.
Found - Corbitt found 24" Fir stump as related by John Miller, 1941. 1943 - Returned to Fir stump and cut into bump below burnt face where BT marks should be. Found blazed face and one axe notch. Counted annual rings on growth since blaze made & got about 72 years which agrees with period of orig. survey & Miller's statement.
From this set 1/4 Corner:
With 1 1/2" Pipe 5 ft. long from which bears:
Orig. 36" Spruce which is really a 30" Fir stump S.65°E., 13.2 ft. to nail crayon mkd: 1/4 S15 RP BT
Orig. 24" Spruce really a 36" Rotten stump, N.14°30'W., to nail on east side. No marks visible.
I blazed - 24" Fir stump, N.70°30'E., 24.9 ft. to nail crayon mkd. 1/4 S10RPBT. 4/15/43

91

1/4 Corner for Sec. 33; and Sec. 4, T21-12. #148
No BT's found so set:
Pipe at proportional distance between MC 33/4 and Cor. 32/33/5/4. 8/21/43

92

Sec. Corner for Secs. 32 and 33; and 5 and 4 of T21-12.
Found - Orig. 8" Hemlock, really only 5" when scribed, now 12" scribed T12W (?) R20S S33. From it relocated cor, S.63°W., 49.5 ft. Creek West 75.5 ft.
Crayon mkd: 5' Spruce stump, S.28°E., 27.1 ft. RP BT S4, out 27.1 ft. ✓
6' Spruce stump, RP BT S5 out 106.7 ft., S.83°W., 106.5 ft.
6' Spruce stump RP BT S32, out 98.1 ft. N.70°15'W., 98.2 ft.
3' Hemlock stump RP BT S33, out 41.4 ft., N.83°E., 41.4 ft to spike in top of stump.
N.86°30'E., 72.2 ft. to face of old blaze 86 yrs. old. on 3' Spruce stump. W side of truck road.
Set - 1 1/2" I.P. 2x2x5 Fir post crayon mkd. S32 S33 T20S R12W
S 5 S 4 T21S R12W

July/Aug. 1943

W.G. Corbitt
H. Hendrickson
for: Crown Zellerbach
1941-43
C.S. 52/91

FD. 0540
1952 - D5

RE-RENEWED & RE-CORNERED NO. #113

RE-RENEWED & RE-CORNERED NO. #148