

Douglas County Surveyor's Record of  
Government Corners Renewed

T 21 S . T. S. R 4 W . R. W. W. M.

KOYE-CHAPMAN CO., EUGENE, ORE. 21881

45

Bruce A. Shaner, #430  
For Lee Kruse & Weyerhaeuser Co.  
February 1962  
RM 2 - 17

7/1/60  
1990-0034  
Fd. OK  
11/3/89  
Re-assess  
M108-12

1/4 Corner to Sections 19 and 30.

Found - 5/8" Bolt at fence corner (N-S & W) as described by Follet & Ford in 1950 survey. From the bolt, N.40°W., 30 lks, I found an old rotted D. Fir stump, no scribes visible; this was a probably BT. As the bolt is close to the computed corner, I accepted it as corner, and from which:  
18" D. Fir bears N.74°W., 30.2 ft., I scribed "1/4 S BT".  
24" D. Fir bears S.20°E., 2.8 ft., I scribed "1/4 S BT".

46

Section Corner to Sections 19 - 20 - 29 - 30.

Found - 26" D. Fir BT, bark scribed "S30 CS.", set by Frear in 1938 and used by Follet & Ford in 1950 survey. AS road grade was raised several feet since 1950 (it is freeway access road now) No pipes could be found.  
Set - 5/8" x 30" Steel Bar 2" under blacktop road, from which:  
28" D. Fir BT. mkd. by Frear bears S.62 1/2°W., 32.5 ft., measured to old tack on scribed face.  
11" Oak bears S.53°E. 69.0 ft., I scribed "S29 BT".  
1 1/4" x 36" Iron Pipe was set as reference point due North, 42.0 ft., flush with ground. Also, old line fence bears due South.

O.S.M.D. Fd. R.R.  
SPIKE 21/4  
M.C.S. PIPE  
N-6

RE-REVIEWED

#131  
#13  
#28  
Fnd. OLSEN by 3/12/82  
C.S. 58/269

SHOULD BE S49°E. 71.4' SEE M 23-25-L.L.

Milo E. Godfrey, Deputy County Surveyor  
Verthon Tracy & Cleate Putnam  
March 12, 1962  
C. S. File No. 49/42

47

Section Corner to Sections 34 and 35 only.

Found - Laurel Tree, now 24", N.48°W. 27.7 ft. Faint Scribing visible on old rotted face, "S3 T2 R".  
Old Fir Stump, 42", S.50°W. 22.4 ft., bark facing corner shows old smoothed off face.  
Old Fir Stump, 32", S.87°E. 44.9 ft., slope dist. No scars or scribing found, Thiel's Tree.  
Mound of Rocks at Corner.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962  
T21S R4W S34/S35  
New BT's: 20" I. Cedar N.64°E. 28.0 ft. Mkd: T21S R4W S35 CS BT.  
7" W. Fir N.19°W. 15.6 ft. Mkd: T21S R4W S34 CS BT.

48

South Boundary of 21-4W. Closing Corner to Sections 3 & 2, T22S-4W.

Found - Dead Cedar Snag, 16", S.65°W. 17.8 ft., scribing visible on old face "CC T22S R" - Rest of old face rotted away.  
Rotted remains of Hemlock Stump S.47°E. 15.2 ft. Too far gone to find scars or scribing.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962  
T22S R4W CC S3/S2  
New BT's: 5" D. Fir S.26°W. 10.2 ft. Mkd: S3 CC CS BT.  
15" W. Fir S.53°E. 32.1 ft. Mkd: T22S R4W CS BT CC S2.

SEE SKETCH OF PENDING COR. 3/1/81  
BLM - CS 42/90

By Bruce A. Shaner  
For Mt. Baldy Lumber Co.  
March 21, 1962  
M 23 - 25

49

S. E. Corner Samuel Hall D. L. C. No. 37.

Found - Orig. D. Fir B.T. Stump, now 44", with scribed "##" visible on Orig. face, later scribes on outer surface show "C 3" +. Stump faces S.88°E. Measured from old face S.88°E, 115.5 ft. and - - -  
Set - 1" x 30" Alum. Pipe, from which a:  
16" D. Fir bears N.23°W. 6.6 ft. scribed DLC 37.  
14" D. Fir bears S.35°E. 12.9 ft. scribed "DEC 37".  
The Pipe is also at an old fence corner, the fence running North & West.

Milo E. Godfrey  
Vern. Tracy & M. Stone  
Sept. 20, 1962  
C.S. File 49/42

50

1/4 Corner to Sec. 31, T21-4W. & Sec. 6, T22-4W.

Found - Iron Bolt 1" diam. with sq. head at corner.  
Fir, uprooted & down, now 36", S.10°E. 32.3 ft. This tree shows an old face, now charred & with no scribing visible, which would have faced corner when tree was still standing, attached affidavit (in file) by Mr. Glen Coons swears he saw scribing on this tree while it was still standing - (Cole, 1914). - REN. #10  
No trace found of either Original Bearing Tree.  
DID NOT SET BRASS CAP  
New BT's: 16" W. Fir S.32°E. 63.6 ft. Mkd: 1/4 S6 CS BT.  
24" D. Fir N.24°W. 32.5 ft. Mkd: 1/4 S31 CS BT.  
Corner lies 4.5 ft. North of E. & W. Fence Line.

FD OK  
BY Les Roberts  
12/94 4121-26