

Douglas County Surveyor's Record of
Government Corners Renewed

T. 21 S. T. S. R. 4 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

1/4 Corner West Side Section 24. 64
Found - 1" Iron Pipe in Fence Corner.
30" W.Oak N.50°E. 139.9 ft., now gone
10" W.Oak S.30°W. 126.7 ft., now gone.
Fence Corner & I. Pin were set before BT's. were destroyed.

1/4 Corner North Side Section 24. 65
Found - Stone & 1 Fir BT, standing, 28" Fir N.84°E. 28.0 ft.,
18" when marked.
Fence running East and West from Corner.

Sec. Corner NW Cor. Sec. 26. 66
Section Corner to Sections 22 - 23 - 27 - 26. ?
Found - Old Cedar Stake badly rotted in fence corner.
BT. Stumps badly burned. - NOT ENOUGH EVIDENCE
SEE C.S. FILE 42/31 - M 2-16

Sec. Corner common to Secs. 23 - 24 - 25 - 26. 67
Found - Stone in Fence Corner.
Bearing Trees all gone.
Stone --marked with "X".

1/4 Corner to Sections 25 and 24. 68
Found - 1 BT., 24" Fir S.40°E. 16.5 ft. - SEE REN. #63
Set - 2" Iron Pipe 48" long mkd. from which:
New BT's: 50" D. Fir N.17°E. 20.0 ft.
17" D. Fir S.20°E. 26.5 ft. mkd: 1/4 S BT.

1/4 Corner E. Side Sec. 36 & W. side Sec. 31. 69
Found - with these BT's. set by Original gov't. survey:
12" I. Cedar N.15°E. 13.9 ft. (now dead)
10" Laurel, gone.
Fence running North and South from big Yew Post.

1/4 Corner S. side Sec. 36. 70
1/4 Cor. found with these BT's. set by original gov't. survey.
18" Fir N. 31° E. 13.2 ft., now 28" standing.
40" Cedar S.10°W. 48.2 ft., now blown down.

Section Corner to Sections 20 - 21 - 28 - 29. 71
Found - 3/4" Galv. Iron Pipe. See Ren. #22
Old Fir Stump N.46°W. 30.4 ft., shows evidence of old scar,
but face now entirely rotted & burned away. (Orig. BT.)
Remnant of Orig. S. W. BT., no marks.
Young Fir Stump N.9°E. 31.5 ft. No markings.
Young Fir Stump N.17°W. 31.2 ft., no markings.
DID NOT SET BRASS CAP.
New BT's: 13" D.Fir N.64°E. 9.0 ft. Mkd: T21S R4W S21 CS BT.
16" D.Fir N.49°W. 23.7 ft. Mkd: T21S R4W S20 CS BT.
8" D.Fir S.48°W. 27.0 ft. Mkd: T21S R4W S29 CS BT.
4" D.Fir S.58°E. 27.9 ft. Mkd: S28 CS BT.

Section Corner to Sections 28 - 29 - 32 - 33. 72
Found - Old, scribed Cedar Stake, so rotten it broke off when
touched. See Ren. #38.
36" Fir Stump S.7 1/2°W. 15.2 ft., opened & found scribing "W"
on badly charred face.
Rotted remains of Fir Stump N.67°E. 68.0 ft.
Rotted Fir Snag S.71°E. 128.0 ft. No marks left.
Set - Brass Cap at Corner Mkd: County Surveyor's T21S R4W S29/S28
Office, 1964 S32/S33
New BT's: 14" D.Fir S.55°E. 23.5 ft. Mkd: T21S R4W S33 CS BT.
10" D.Fir N.85°E. 33.7 ft. Mkd: T21S R4W S28 CS BT.
11" D.Fir N.7 1/2°W. 115.0 ft. Mkd: T21S R4W S29 CS BT.
Corner is in fence corner, fences E.&N. & in E. edge of logging road.

Gilbert Gardner
For W. A. Woodard Lumber Co.
July - Dec., 1955
C. S. File No. 53/1

Mike E. Godfrey, Deputy Co. Surv.
Wm. Steffel & Mike Stone
October 22, 1964
C. S. File No. 49/68

10/79
M 80-23
J. Andrews
FD B. CAP