

Douglas County Surveyor's Record of
Government Corners Renewed

T. 21 S. T. S. R. 4 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

79

Township Corner R5W

S36	S31
S1	S6

 R4W

T21S
T22S

Found - 40" Fir (burned Stub) S.11°30'W., 200 lks. 113
Orig. S.14°W., old scribed post. BT's. destroyed. *SEE ALSO THEIL'S BOOK 5 PG 18*

Set - 2" I. Pipe & Scribed New BT's:
24" Fir N.42°30'E. 26.4 ft. Mkd: T21S R4W S31 BT.
28" Fir N. 9°30'W. 51.7 ft. Mkd: T21S R5W S36 BT.
28" Fir S.21°10'W. 60.7 ft. Mkd: T22S R5W S1 BT.
26" Fir S.25°30'E. 5.0 ft. Mkd: T22S R4W S6 BT.

Corner Set by McGillicuddy, 1953 - Pipe & 4 BT's. are still in good condition Oct. 1964 - Found by M.E. Godfrey. C.S. 49/68

B. H. McGillicuddy
July 1953
C. S. File No. 41/182

80

1/4 Corner to Sec. 35, T21-4W. & Sec. 2, T22-4W.
(N. Line T.22S R.4W. & on Lane-Douglas County Line)

Found - 1/2" Galv. I. Pipe extending 12" above ground. - Ren. #78-T22-4W
42" Fir Stump S.4°W. 15.8 ft., old bark scribing vis. "1/4 S".
Uprooted Fir Stump N.30°E. 2.6 ft., no scribing found.

DID NOT SET BRASS CAP

New BT's: 17" W. Fir N.76°W. 27.7 ft. Mkd: 1/4 S35 CS BT.
10" D. Fir N.49°E. 49.7 ft. Mkd: 1/4 S35 CS BT.

81

1/4 Corner to Sections 16 and 21.

Found - 2" I. Pipe set by Evans. Ren. No. 15.
36" Cedar N.65°E. 32.0 ft., opened & found good scribing.
42" Fir Stump S.53°E. 50.5 ft., bark scribed "1/4 S CS BT".

New BT's: 8" Hemlock S.68°E. 8.0 ft. Mkd: 1/4 S21 CS BT.

DID NOT SET BRASS CAP.

Fnd. OK by
W. EIMSTAD
OCT. '81 M. 89-25

Milo E. Godfrey, Deputy County Surveyor
Wm. Stoffel & Mike Stone
November 1964
C. S. File No. 49/68

82

Mst. Westerly N.W. Corner D.L.C. No. 37.

Found - Rotted Snag of 18" Fir S.78°E. 142.6 ft., good scribing.
Stump of 36" Fir S.88°E. 142.6 ft., no marks or scribing found.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1964
T21S R4W W NW DLC 37

New BT's: 12" D. Fir N.54°E. 26.6 ft. Mkd: W NW DLC 37 CS BT.
17" D. Fir S.12°W. 24.0 ft. Mkd: W NW DLC 37 CS BT.

Note - Corner is approx. in old fence corner (fences E. & S.)
Cannot tell exact location of old fence corner.

83

Interior "L" Corner D.L.C. No. 37.

Found - Old Oak Stump S.88°W. 82.5 ft., good reverse scribing, "4W 21S".
No trace of Original N. W. Bearing Tree.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1964
T21S R4W Int. L DLC 37

New BT's: 4" W. Fir S.70 1/2°W. 49.7 ft. Mkd: Int. L. DLC 37 CS BT.
A power pole "7 - 131" bears S.45°E. 10.5 ft.

Note - Corner is at an old fence corner, fences W, N. & S.E.) and approx. 100 ft. west of centerline of Old Hiway 99.

FOUND O.K. DEC. 1968 V.R.T.

84

Mst. Northerly N.W. Corner DLC No. 37.

Found - 1" Iron Pipe with Alumin. Sleeve Mkd: "C37". (No record)
Old Cedar Stump S.73°E. 14.5 ft., W. side of stump gone.
Evidence of old face on chips at base of stump, but no scribing.

Base of old Fir Stump N.75°E. 38.3 ft., not enough left for scribing or scars. 100

Iron Pipe (also old Cedar Stake alongside) is in 3-way fence corner (fences East, West & South).

New BT's: 9" I. Cedar N.45 1/2°W. 71.0 ft. Mkd: NW DLC 37 CS BT.
10" I. Cedar S.64°W. 29.0 ft. Mkd: NW DLC 37 CS BT.

SEE ALSO
THEIL'S BOOK 5
PG 35

RE-RENEWED CORNER NO.