

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 21 T. S. R. 4 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21981

123

Section Corner for Secs. 18 and 19; and Secs. 13 & 24 of T.21-5  
 Found - 1968 County Brass cap properly marked, on a 1" x 3 ft. I.P.  
 protruding 1.2 ft. above ground. Ren. #102  
 3/4" (I.D.) x 37" Iron pipe lying along side cap. Ren. #87  
 Cap lies .2 ft. North of a fence bearing S.85°E., N.85°W. An old  
 fence is North of cap 1.0 ft.  
 BT's - No originals found.  
 A 14" Fir, now 25" with healed over blaze bears S.48 1/2°E.,  
 34.3 ft. Ren. #5  
 A 14" Fir, now a 33" x 4 ft. stump badly rotted scribe visible  
 on open face "T21" bears N.71 3/4°W., 129.0 ft. Ren. #5  
 A 27" D. Fir, now a 28" with pitched over blaze bears S.32 1/2°E.,  
 37.4 ft. Ren. #87  
 A 12" Fir, now a 16" With well healed double blaze bears N.69°W.,  
 133.2 ft.  
 A 6" D. Fir, now 12" with well healed double blaze bears N.16°E.,  
 34.1 ft. (Record N.1 1/2°E., Ren. #102)  
 PUT new tag on this tree.  
 Left cap in place. No new accessories. No available trees to the SW.

Karen Reed Deputy  
 Douglas County  
 Surveyors Off.  
 Ed R. Scott  
 Witness  
 Aug. 4, 1980  
 C.S. 61/11

FND. 7/92 BY  
 FINDORFF 1993-0016

Section corner for Secs. 9, 10, 15 and 16  
 NOT found - Orig. post marker.

124

Axle set by Oregon State Hwy. Dept. set in 1947 survey.  
Ren. #20 (1953 Bayles survey) red top stake.  
 BLM brass cap or 1" iron pipe, 1972 resurvey.  
 1" iron rod that was found by Tracy, 1969, C.S. file 54/14.

These monuments evidently destroyed by Hwy construction.

FOUND - 5/8" x 30" iron rod set by Eimstad (1981 survey, see accompanying  
 notes in C.S. file 61/27). This monument was set by use of  
 State Hwy. field notes, State Hwy map and found right of  
 way monuments for position control. The 1947 and 1950 field notes  
 show ties to the axle set in 1947 as well as evidence of  
 bearing tree information.

The original survey notes were checked for collateral call information.  
The following were located:

The original notes for the line ran to the north call for a  
 stream 12 links (7.92 ft.) wide, course north, 4 chains  
 (264 ft.) north of the corner. From Eimstads iron rod, we  
 find a creek, 10 ft. wide course west bears north 267.2 ft.  
 to center.

The east line calls a creek, 3 links wide (1.98 ft.) at 4.75  
 chains (313.5 ft.) course north-west. We find a stream 2 ft.  
 wide, course north-west bears east 321.8 ft. to center.

The position of the destroyed 1972 B.L.M. brass cap is approx. N.62°W., 144.1 ft.  
 (according to Oreg. State Hwy. Dept. information). We are not able to  
 clarify the reason for the B.L.M. accepting a 1" dia. iron pipe for corner  
 position as the Baylis Ren. #20, 1953, indicates a red top stake set at  
 corner position. A measurement was made by the B.L.M. from the section  
 corner to the west, the found 1" diam. iron pipe beared N.89°08'E., 79.13 chains  
 original records show N.89°44'E., 80.00 chains.

Set - At position of found 5/8" x 30" iron rod set by 1981 Eimstad  
 survey, WE SET a 1" x 30" iron pipe with attached brass cap  
 stamped: "Douglas County Surveyor" Monument protrudes  
 approx. 5 inches above  
 ground.

FD. B.C. 10/90 M110-72

T 21 S R 4 W  
 S 9 | S 10  
 S16 | S 15  
 1981

We place found iron rod along south edge of monument, flush  
 with ground.

New BT's - A maple, 14" diam. blazed and scribed "T21S R4W S10 CS BT"  
 bears N.73 1/2°E., 305.5 ft.  
 A fir, 21" diam., blazed and scribed "T21S R4W S15 CS BT"  
 bears S.60°E., 288.3 ft.  
 A fir, 8" diam., blazed and scribed "T21S R4W S16 CS BT"  
 bears S.6°W., 275.0 ft.  
 A fir, 14" diam., blazed and scribed "T21S R4W S16 CS BT"  
 bears S.81°W., 398.8 ft.

Larry E. Monrean, Deputy, Douglas Co. Surveyors Office  
 Witnesses: D.L. Stewart; T. R. Plouff  
 August 31, 1981  
 C.S. 61/27  
 \*Douglas Survey  
 M89-25  
 Compass declination: 19° East.