

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 21 T. S. R 4 R. W. W. M.

FOKE-CHAPMAN CO., EUGENE, ORE. 97101

Charles W. Guile
For: Weyerhaeuser Co.
Feb. 27, 1987
M 103 - 68
C.S. 63/45

140

West 1/4 Corner for Section 2
Set - 1" x 36" iron pipe with cap
Fd. BTs-Rotted stump hole bears N.79°E., 14.4 ft. with scribe.
20" chinquapin bears N.67°W., 6.4 ft. to nail.
17" fir bears S.72°E., 23.9 ft. to nail.
New BTs-14" fir bears N.2°W., 14.7 ft. to "W" nail scribed "E½S3BT".
11" fir bears S.20°E., 28.4 ft. to "W" nail scribed "W½S2BT".
Also found a steel fence post bearing N.19°E., 0.35 ft.
FO OK M120-70 10/5/94 CW Guile 2/87

Donald Peel
For: Weyerhaeuser Co.
May 20, 1987
M 104 - 28

141

1/4 Corner for section 26 & 27.
Set - 2" x 42" iron pipe with brass cap stamped "T21S R4W
1/4 S27 S26 PLS 752 1987".
BT's -A 12" Fir bears S60°E, 7.9 ft. scribed "1/4S26 BT"
Scribed- 20" Fir bears S31W, 19.3 ft. scribed "1/4 S27 BT".

142

1/4 Corner Corner 23 & 26
CORNER REPORT ONLY:
Found - 5/8" rebar - 2" x 2" white post See Ren.#125.
Bt's - A 14" fir bears S13W, 4.2 ft.
16" fir bears N10-3/4°W, 8.0 ft.
NOTE: 1/2" ironpipe set by G. Gardner (Roll File D-412 Lane Co. or M2-16,
Douglas County records. bears N29°03'23"W, 81.26 ft.
ALSO NOTE: Peel presumes 1/2" I.P. per Gardner, does not say on maps noted.
(DCSO)

143

1/4 Corner for Sections 27 and 34
Set - 2" x 42" iron pipe with brass cap mkd. "T21S R4W 1/4
S27 S34 PLS 752 1988"
New BTs-10" White fir, N.40°W., 20.7 ft. scribed "1/4 S27 BT".
10" Fir, S.52°W., 27.4 ft. scribed "1/4 S34 BT".

Peel Baker Land
Surveying
Don Peel
July 13, 1988
For: Weyerhaeuser Co.
M 106- 48

144

1/4 Corner for Secs. 34 and 35.
CORNER REPORT ONLY
Found - U.S.B.M. 2½" iron pipe with brass cap dated 1980 - 3/4" rebar
alongside.
27" cedar, N.81°E., 57.0 ft. closed face Ren. #29
8" white fir, S.69°E., 6.3 ft. closed face.
9" fir, S.63°W., 12.6 ft. closed face.(Note:Record is N.62°W.)
19" white fir, N.30 3/4°W., 36.1 ft. closed face.

145

Center 1/4 Corner for Section 34
Set - 2" x 42" iron pipe with brass cap mkd. "T21S R4W C 1/4 + 34
PLS 752 1988"
New BTs-20" fir, S.65°E., 24.1 ft. scribed "C 1/4 S34 BT"
17" fir, S.53°W., 18.7 ft. scribed "C 1/4 S34 BT".
ED OK, D. BAKER, 1/4/96, M129-4

146

1/4 Corner for Sections 33 and 34
Set - 2" x 42" iron pipe with brass cap mkd. T21S R4W 1/4 S33|S34
PLS 752 1988"
New BTs-10" fir, N.57°E., 7.8 ft. scribed "1/4 S33 BT"
14" Fir, N.0½°W., 15.5 ft. scribed "1/4 S33 BT".
Note: 30" cedar stump (unknown origin) opened to visible scribing bears
S.22°13'18"E., (approx. 70 years of overgrowth.)
ED OK, D. BAKER, 1/4/96, M124-4 7/13/88

147

1/4 Corner for Sections 8 and 17 *Fd. OK 5/96 BY BRADSBY M 123-76*
Ren. #111
Found - 1969 County brass cap out of position lying on top of ground.
Orig. decayed fir stump, 48", bears S.74°W., 126 lks. dist. No
scribe marks visible on opened blaze.
A 26" fir bears N.64°E., 39 lks. with healed blaze.
A 18" fir bears S.29°W., 52 lks. with healed blaze.
Set - Drilled 1" hole 7" deep in bedrock, drove 3/4" pipe into drill
hole and cemented base, drove 12" long, 1½" pipe with county
Sruveyors office B.C. over 3/4" I.P. Added marks "RESET 1988
to brass cap.
Corner is located in a ravine draining S.45°W.

Wayne Rogers, LS #2137
For: BLM
Dec. 28, 1988
C.S. 63/87