

Douglas County Surveyor's Record of  
Government Corners Renewed

T 21 T. S. R 4 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 31881

159

C O N T - - -

Doug. Co. Surveyors Offi.  
R.W. Smith; S.W. Flauser  
Nov. 13, 1991  
C.S. File 64/21

A Fir 10" dia. now a 16" D.B.H. D. Fir with a fully healed single blaze bears S.48 $\frac{1}{4}$ °W., 12.5 ft. (as per record)  
A Fir 9" dia. now a 16" D.B.H. 5 $\frac{1}{2}$  ft. tall Fir stump with a fully healed single blaze bears N.16 3/4° W., 25.7 ft. (as per record)  
New BTs -13" DBH D. Fir scribed T21S R4W S36 CS BT on a double blaze bears S.02 $\frac{1}{2}$ °E., 3.4 ft. dist.  
22" DBH D. Fir scribed t21S R4W S35 CS BT on a double blaze bears S.89°W., 34.0 ft. dist.

Corner is in large clear-cut with large second growth timber remaining in SW quadrant. Corner is approx. 100 ft. Southerly from Wyerhaeuser Timber access road.

11/13/91

N.W. Township Corner to T. 21 S. R. 4 W.

160

Found - 2 $\frac{1}{2}$ " dia. DCSO brass cap on 1 $\frac{1}{4}$ " O.D. iron pipe, protruding 14" above ground. See renewal no. 92. marked DCSO 1965.  
3/4" I.D. iron pipe found along east edge of BC/IP (source unknown)  
A stone measuring 20" x 9" x 5" marked "R5WS36" is found loose along NE edge of BC/IP (source unknown)

Accessories Found -

8" now 14" dia. rotted D. Fir stump, no blazes or scribing visible, bears N.50°W., 5.3 ft. agrees w/record (orig. BT)  
8" now 17" dia rotted D. Fir stump, no blazes or scribing visible, bears N.72°W., 7.0 ft. agrees w/BLM rec. (orig. BT)  
7" now rotted D. Fir stump of indeterminate size, no blazes or scribing visible, bears S.15°W., 5.9 ft. agrees w/ rec. (orig. BT)  
8" now 12" dia. 7 ft. high D. Fir stump, with a fully healed double blaze, bears N.4°W., 7.0 ft. agrees w/renewal No. 92  
7" now 7" dia. 30' high D. Fir snag with a fully healed double blaze, bears S.44 $\frac{1}{2}$ °W., 4.5 ft. (agrees with BLM bearing and ren. No. 92 dist.)  
7" now 10" dia. D. Fir with a fully healed double blaze, bears S.88°E., 17.2 ft. (rec. is east in ren. No. 92 and N.85 $\frac{1}{2}$ °E., by BLM, dist 17.3 ft. agrees.)  
8" now 9" dia. D. Fir with a fully healed double blaze bears S.23°E., 23.1 ft. (rec. S.21°E., ren. No. 92 and S.20 $\frac{1}{2}$ °E., by BLM, dist. 23.2 agrees with rec.)

New Accessories -

17" dia D. Fir double blazed and scribed "T21S R5W S1 CS BT" bears S. 72 $\frac{1}{2}$ °W., 21.3 ft.  
11" dia. D. Fir double blazed and scribed "T20S R5W S36 CS BT" bears N.17 $\frac{1}{2}$ °W., 81.1 ft.

Note - Corner lies approx 35 ft. south of a gravel road.

12/3/91

161

Section Corner for Secs. 1 and 2; 35 & 36 of T20-4

Found - 3 $\frac{1}{4}$ " BLM brass cap on a 2 $\frac{1}{2}$ " O.D. Iron pipe protruding 4" above ground.  
A firmly set sandstone rock is found along East edge of BC/IP top measures 8" x 4", protrudes 4" above ground. Unknown origin.  
20" now 33" dia. 1 $\frac{1}{2}$  ft. high D.Fir stump, no marks visible bears S.12 $\frac{1}{2}$ °W., 33.0 ft. (Rec. S.14°W., 33.0 ft.) Orig. BT.  
6" now 8" dia. 3 $\frac{1}{2}$  ft. high burnt cedar stub, no marks visible, bears N.28 $\frac{1}{2}$ °W., 54.1 ft. (Rec. N.25°W., 54.1 ft.) Orig. BT.  
6" now 25" D.Fir with a fully healed double blaze, bears N.56°E., 5.9ft. (agrees w/rec) Ren. No. 58  
22" dia. 1 $\frac{1}{2}$  ft. high D.Fir stump with a fully healed lower blaze, bears S.52°E., 18.8 ft. (Rec. S.46 $\frac{1}{2}$ °E., 18.8 ft.) 1958 W.C.  
33" dia. 2 $\frac{1}{2}$  ft. high D.Fir stump with a rotted blaze, no scribing visible, bears S.2 $\frac{1}{2}$ °W., 32.5 ft. (Rec. S.5 $\frac{1}{2}$ °W., 33.0 ft.) 1958  
45" dia. 5 ft. high D.Fir stump with a fully healed single blaze, bears N.45 $\frac{1}{2}$ °W., 31.0 ft. (Rec. N.42 $\frac{1}{2}$ °W., 31.0 ft.) 1958 W.C.  
10" now 14" dia. I.Cedar with a fully healed single blaze, bears N.16°E. 16.5 ft. (Rec. N.21°E., 16.5 ft.) 1971 BLM  
12" now 20" dia. W.Fir with a fully healed single blaze, bears S.23 $\frac{1}{2}$ °E., 18.5 ft. (Rec. S.19 $\frac{1}{2}$ °E., 18.5 ft.) 1971 BLM  
New BT - 6" dia. D.Fir double blazed and scribed "T20S R4W S35 CS BT" bears N.58°W., 15.0 ft.

Corner is approx. 150 ft. west of a BLM gravel rd. All bearings taken away from corner. Wire fence effects compass bearings.

Douglas County Surveyor's Office  
R.W. Smith S. J. Flauser  
Nov. 7, 1991  
C.S. 64/21

Douglas County  
Surveyors Office  
Randall Smith  
Stephen Flauser  
November 4, 1991  
C.S. 64/21