

Douglas County Surveyor's Record of
Government Corners Renewed

T. 21 S. T. S. R. 5 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

102

Section Corner to Secs. 33 & 34, T21-5W. & Secs. 3 & 4, T22-5W.

Found - 1" Alum. Pipe set by Calder, 1960. - Ren. #62

Stump of 24" D. Fir N.40°W. 104.0 ft., scribing still visible. (See Ren. #3)

Rotten Fir Stump S.15°E. 169.0 ft., No mks. vis. (Orig. BT.)

Stump of 8" Alder S.30°E. 244.7 ft. (faces visible but

scribing rotted away. This tree mkd. in Ren. #3)

Stump of 4" I. Cedar S.37°E. 36.8 ft. (Calder's BT)

8" D. Fir S.70°E. 82.2 ft., blaze & scribe this Fir "T22S R5W S 3 CS BT".

8" D. Fir S.78°W. 44.2 ft., bl. & sc. this Fir "T22S R5W S4 CSBT"

New BT's: 8" D. Fir N.86°E. 57.2 ft. Mkd: T21S R5W S34 CS BT.

8" D. Fir N.54°W. 34.6 ft. Mkd: T21S R5W S33 CS BT.

Did not set BRASS CAP - Alum. Pipe extends approx. 12" above ground.

FD OK 10/95 D BAKER M119-77

FD OK
10/88 D. WEAVER
M107-26

103

1/4 Corner to Sections 31 and 32.

Found - Fir, down & split open, N.28°E. 48.8 ft., good scribing. visible.

No trace of S. W. Bearing Tree.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1964

T21S R5W 1/4 S31/S32

New BT's: 24" Madrone N. 9°E. 35.4 ft. Mkd: 1/4 S32 CS BT.

7" D. Fir N.44°E. 24.3 ft. Mkd: 1/4 S32 CS BT.

No trees near West of Line.

Fence Corner (Fences North, South & East) bears South 5.5 feet.

FD OK - M121-24 - 11/10/94

FD OK
8/84
F.O. WILLIAMS
M 97-48

104

1/4 Corner to Sections 30 and 29.

Found - 1/2" Iron Pipe - (See Ren. #9)

54" Fir Stump N.10°W. 68.0 ft., bark scribing plainly visible.

10" Madrone S.52 1/2°E. 24.0 ft., bark scribed.

Badly rotted large Fir Stump N.56°E. 20.5 ft., no marks visible.

Blaze & Rescribe: 10" Madrone S.52 1/2°E. 24.0 ft. Mkd: 1/4 S29 CS BT.

New BT: 11" D. Fir N.41°W. 182.2 ft. Mkd: 1/4 S30 CS BT.

Note 1/4 - Corner is in N. & S. Fence Line.

FD OK
3-91 M111-71

105

1/4 Corner to Sections 26 and 27.

Found - Steel Axle. - (See Ren. #51)

36" Fir Stump N.71°W. 91 ft., bark scribed, cut open & found scribing "1" at 8" Diam.

36" Fir Stump N.70°E. 120.8 ft., top of stump shows burl wood near Orig. Diam.

Tree marked by Evans, 22" D. Fir N. 10°E. 13.8 ft., scribing vis.

New BT: 14" D. Fir N.45°W. 18.7 ft. Mkd: 1/4 S27 CS BT.

Note: Corner is in E. & W. Fence Line along N. edge of open field.

RENEWAL NO. #199

Milo E. Godfrey, Deputy Co. Surveyor
Wm. Stoffel & Mike Stone
December 1964
C. S. File No. 49/68

106

Section Corner to Secs. 26 - 27 - 34 - 35.

Found - Old Scribed Cedar Stake, rotted off at ground & 1/2" Iron Rod.

Badly rotted, old, uprooted Fir N.23°E. 15.8 ft., on under side found bark with flattened area showing fragmentary bark scribing.

Cedar Stump S.69°W. 37.0 ft. showing evidence of upper & lower faces, but no scribing, faces badly rotted.

No trace of Original S. E. or N. W. Bearing Trees.

15" Maple S.73°E. 11.0 ft. scribing vis. "21R 5 S35 CSBT".

27" Maple N.34°W. 32.0 ft., scribing vis. "T21SR5W S27 CS"

(No record of renewal found) See M 19-53

DID NOT SET BRASS CAP.

New BT's: 6" D. Fir N.81°E. 4.5 ft. Mkd: T21S R5W S26 CS BT.

13" I. Cedar S.51°W. 23.3 ft. Mkd: T21S R5W S34 CS BT.

FD OK 12/8/70 V.R.T. C.S. 54/14

FD 2/81
E. KINGSBURG
M 73-69

107

Int. "L" Corner D. L. C. No. 37.

Found - "T" Iron set by Haines, no cap. (See Ren. #58)

26" D. Fir S.20°E. 35 ft., bark scribed, good condition.

Both Orig. BT's., as mentioned in Haines' Renewal #58.

N.E. Tree, down & prev. opnd., good scribing visible.

N.W. Tree, W. Oak, still standing, but been open for many years & face is badly rotted.

New BT: 13" D. Fir N.74°W. 21.7 ft. Mkd: "Int. L DLC 37 CS BT.

Corner is approx. 4 ft. North of fence corner - Fences N. & W.

FD OK
W. HAINES
5/18/70
M 92-30