

Douglas County Surveyor's Record of
Government Corners Renewed

T. 21 S. T. S. R. 5 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Sec. Cor. to Secs. 30 & 31, T21-5W. & Secs. 25 & 36, T21-6W. 113

Found - "T" Iron at Corner from which: (See Ren. #61) #156
12" E. Cedar, now snag, S.11°W. 83.6 ft., scribing visible.
16" Fir N.53°W. 54.3 ft., bark scribing visible.
(Rescribed in Wood T21S R6W S25 CS BT)

New BT's: 12" Maple S.26°W. 76.9 ft. Mkd: T21S R6W S36 CS BT.
(78° @ - 9½°)
12" Cedar S.45°E. 184.3 ft. Mkd: T21S R5W S31 CS BT.
(100° @ 14½° plus 92° @ 18°)

Bruce R.
Rogers, Deputy
C. S.
File
No.
53/101

June 7, 1965

RE-RENEWED

¼ Sec. Cor. to Sec. 3, T21-5W. & Sec. 34, T20-5W. 114

(County Line, Lane - Doug. Co.)

Found - 2" Sq. Post & BT's. as follows:

Orig. 8", now 20" Maple S.43°W. 13.9 ft., open & shows
"½S" reverse scribe.
Orig. 6", now 16" Fir N.34°W. 45.5 ft., down & out of place.
We do not open, badly rotted.

Set - Brass Cap at Cor. Mkd: Doug. Co. Surv. Office, 1965 $\frac{1}{4} \frac{S \ 34}{S \ 3} \frac{T20S}{T21S} R5W$

New BT's: 18" D. Fir N.34°W. 35.9 ft. Mkd: ¼ S34 DCS BT.
19" Maple S.43°W. 17.2 ft. Mkd: ¼ S 3 DCS BT.

Sec. Cor. to Secs. 2 & 3, T21-5W. & Secs. 34 & 35, T20-5W. 115

(County Line, Land - Doug. Counties)

Found - Orig. 16", now 22" Fir N.59°E. 16.5 ft., probably 10 lk. error
in dist., should be 23.1 ft., shows scribe in 6.0 ft. stump.
Orig. 30", now 44" Fir S.15°E. 35.6 ft., shows bark scribe.
Orig. 12", now 25" Cedar S.30°W. 21.8 ft., open face rotted.
No scribe found. Alive.

No trace N. W. Bearing Tree.

Set - Brass Cap at Cor. Mkd: Doug. Co. Surv. Office, 1965 $\frac{S \ 34}{S \ 3} \frac{S \ 35}{S \ 2} \frac{T20S}{T21S} R5W$

New BT's: 6" Hemlock S.87°W. 23.3 ft. Mkd: S3 DCSBT.
7" D. Fir S.77°E. 21.4 ft. Mkd: T21S R5W S2 DCS BT.
No trees available to North.

Vernon "Ray" Tracy
Mike Darby and Terry Connell and Mike Stone
July 1965
C. S. File No. 54/14

Section Corner to Sections 9 - 10 - 15 - 16. 116

Found - Haines' "T" Iron, See Ren. #39.

6", now 7" Fir N.76°E. 23.4 ft., shows good scar.
30", now 31" Fir S.75°E. 32.0 ft., shows T21S R5W S15 BT
(bark scribe)

New BT's: 5" D. Fir N.62°W. 13.9 ft. Mkd: S 9 CS BT.
9" D. Fir S.37°W. 17.5 ft. Mkd: T21S R5W S16 CS BT.

¼ Corner to Sections 3 and 4. 117

Found - Orig. 10", now 19" Fir S.75°E. 21.8 ft., open & find scribe.
Orig. 60" Fir N.47°W. 14.5 ft., rotted off about 12" - 18"
above ground, no scribe found.

Set - Brass Cap at Cor. Mkd: County Surv. Office, 1965
 $\frac{1}{4} \frac{S \ 4/S \ 3}{S \ 3} \frac{T21S}{T21S} R5W$

New BT's: 21" D. Fir S.24°E. 13.8 ft. Mkd: ¼ S 3 CS BT.
41" D. Fir N.68°W. 37.0 ft. Mkd: ¼ S 4 CS BT.

¼ Section Corner to Sections 22 and 23. 118

Found - Orig. 8" Fir N. 8° W., 19.4 ft., now 36" rotted stump,
found scribing "½S" BT".
No trace of N. E. Bearing Tree.

Set - ¾" Iron Rod 18" in ground, 6" out of ground at corner.

New BT's: 12" D. Fir N. 66° W. 29.7 ft. mkd: ¼ S22 CS BT.
6" D. Fir S. 77° E. 27.8 ft. mkd: ¼ S23 CS BT.

Note - This corner lies on a steep north slope approx. 200 ft.
North of spur ridge and 100 ft. south of small creek.

Sept. 14, 1965

RE-RENEWED