

Douglas County Surveyor's Record of
Government Corners Renewed

T 21 T. S. R 5 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

161

C O N T - -

Gregory Quibell, Deputy
Doug. Co. Surveyors Off.
John Powell - Randy Smith
May 10, 1983
C.S. 62/7

16" fir per resurvey, now 24" with well healed blaze bears
S.59°E., 35.6 ft.
6" fir per resurvey, now 16" with well healed blaze bears
S.37°W., 99.7 ft.
6" fir per resurvey, now 10" with well healed blaze bears
N.22°W., 108.9 ft.
Set - Since found hole fits well, I reset found brass cap in its
original hole and add the marks 1983 to cap.

5/10/83

162

Frank O. Williams
For: Weyerhaeuser
Company
Aug. 25, 1984
M 97 - 48
C.S. 58/300

Center 1/4 corner for Section 32

Set - 1" x 36" iron pipe with yellow plastic cap inscribed "Weyer Co."
BTs - 34" fir, N.65 1/2°W., 39.1 ft. to "W" nail.
22" W. Fir, S.41 1/2°W., 56.3 ft. to "W" nail.
Found - 1/2" galv. pipe of unknown origin bears N.18°46'05"W., 35.75 ft.
with associated bearing tree:
36" fir, S.59°W., 31.7 ft.

8/25/84

163

Frank O. Williams
D. Wellman; K.
Perkins.
For: Weyerhaeuser Co.
Nov. 2, 1984
C.S. 58/300
M 97 - 48

North 1/4 Corner, Section 32
CORNER REPORT ONLY

Found - 2 1/2" Alum. BLM cap. 1981 resurvey.
13" fir, S.8°W., 30 lks. (Rec. S.8°E., 30 lks.; tag reads N.8°E
30 lks.)
11" fir, N.1 1/2°E., 35 lks. as per record. Tag reads S.1 1/2°W
30 lks.
1" iron pipe of unknown origin bears N.41°37'E., 0.383 chains with
associated BTs:
26" cedar N.8 1/2°W., 24 lks. and
26" fir, S.30°W., 14 1/2 lks.

Corner lies near top of ridge.

11/2/84

Charles Guile
For: Weyerhaeuser
Nov. 1986
M 103 - 9
C.S. 63/45(n)

East 1/4 Corner Section 13, and Sec. 18 of T21-4.

Set - 1" x 36" Iron Pipe with cap stamped "Guile PLS 472".
Found - 3/4" Iron Pipe bears S 75°20'46"W, 23.74 ft.
New - 18" Fir bears N 53 1/2° W, 8.8 ft. to "W" nail "E 1/4 S 13 BT".
BT's 19" Fir bears N 86 3/4°E, 14.2 ft. to "W" nail, "W 1/4S 18 BT".

164

FND. OK 9-93 BY BAKER M118-10

David H. Wellman
L.S. #2163
For: Weyerhaeuser
Oct. 28, 1988
M 107 - 26
C.S. 63/85

1/4 Corner for Section 34 and Sec. 3 of T.22-5

Found - 72" rotted fir stump with axe marks N.8°E., 72 lks. (1855 BT)
Set - 1" x 36" iron pipe with yellow plastic cap inscribed "Weyer Co"
New BTs - 14" fir, N.38°W., 28.9 ft. to "W" nail and tag scribed 1/4 S34BT'
15" fir, S.2°W., 42.8 ft. to "W" nail and tag scribed 1/4 S3BT'.
14" fir, S.70°W., 60.8 ft. to "W" nail and tag scribed 1/4 S3BT'.

FDOK 10/95 D. BAKER M119-17

10/28/88

165

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
C.S. 62/63
April 19, 1989

1/4 Corner for Sections 35 and 34.

Found - Co Surveyors office 2 1/2" brass cap on a 1 1/4" O.D. iron pipe, 2"
below ground leaning 8" southeast of plumb. (per M19-53)
3/4" bolt with nut protruding 8" above ground bears N.44 1/2°W.,
0.8 ft. from DCSO BC/IP plumb position. (source unknown)
18" fir per M19-53 is gone, probably removed by road work
on Highway.

54" now 60" dia. 2 1/2 ft. high cedar stump with a previously
opened blaze and axe mark, no scribing found bears S.49°W.,
101.5 ft. (Rec. S.59°W., 100.5 ft. per M19-53).

3/4" I.R. now bent 3/4" bolt bears S.1°W., 170.8 ft. (agrees
well with record, per M19-53)

5/8" I.R. bears S.1°W., 223.68 ft. (agrees well with record
per M81-72)

Set - DCSO BC/IP returned to plumb position, BC is flush with ground.
Position of corner as determined in M19-53 perpetuated by
new BTs below:

New BTs - 24" D. fir double blazed and scribed "1/4 S34 CS BT" bears
S.49 1/4°W., 50.7 ft.

A double trunked I. Cedar double blazed and scribed "1/4 S35 CS
BT" on 7" southwest trunk bears S.38°E., 69.9 ft. to root
crown.

Corner is approx. 140 ft. north of highway.

4/19/89

166