

Douglas County Surveyor's Record of  
Government Corners Renewed

T 21 T. S. R 5 R. W. W. M.

MOKE-CHAPMAN CO., EUGENE, ORE. 91801

167

Center 1/4 Corner for Section 18  
Set - 2" x 42" iron pipe with brass cap mkd. "T21S R5W C1/4 S18 PLS 752 1989"  
Set 6' steel fence post 1 ft. west.  
BTs - 9" Alder, N. 33 1/2° E., 3.7 ft. bark scribed "C 1/4 S18 BT".  
11" fir, N. 28 1/2° W., 23.8 ft. scribed "C 1/4 S18 BT".

Donald Peel LS 752  
For: Weyerhaeuser Co.  
July 1989  
M 108 - 55

RE-RENEWED CORNER NO #178

168

1/4 Corner for Sections 7 and 18  
Set - 2" x 42" iron pipe with brass cap mkd. "T21S R5W 1/4 S7 S18  
PLS 752 1989".  
Set 6 ft. steel fence post 1 ft. west.  
New BTs - 11" hemlock, N. 18° E., 5.9 ft. scribed "1/4 S7 BT"  
27" hemlock, S. 9° E., 21.6 ft. scribed "1/4 S18 BT"  
Note: 1" alum. pipe bears N. 81° 26' 52" W., 29.17 ft. (See CS File #62/6)

Martin C. Stewart  
For: Shiloh  
Forestry, Inc.  
Oct. 31, 1989  
C.S. 63/85

169

West 1/4 corner for Section 31 of T.21-4  
Found - Found disturbed, a BLM 1988 brass cap on a 2" alum. pipe.  
(Not of record yet). Shiloh Logging operation had pushed  
monument in a northeast direction.  
Also found, BT stumps with tags and scribes visible on the NW & SE BTs and  
healed blaze on E-SE BT. All stumps have alum. sheets covering them.  
4 ft. high 20" W. fir stump bears S. 83 1/2° E., 18.0 ft. healed  
blaze. Ren. #96  
4 ft. 15" D. fir stump bears S. 22° E., 12.6 ft. Placed LS 2057  
brass shiner in lower portion of blaze.  
4 ft. high 13" D. fir stump bears N. 46 1/2° W., 18.5 ft. Placed LS  
2057 brass shiner in lower portion of blaze.  
Set - I excavated the found BLM monument and found a 3/4" x 34" galv.  
Iron pipe inside of monument. I was able to reestablish GIP  
position as it was set 3 to 4 inches deeper than BLM monument.  
I straightened both monuments and reset accordingly. Ren. #96  
No new accessories marked, as stumps should perpetuate corner position  
until suitable trees can be used, I painted and re-tagged BT stumps.  
This 1/4 corner is located within a clear-cut approx. 150 ft. west of a  
Guistina Logging road on a NW aspect.

10/31/89  
170

1/4 Corner for Sections 34 and 35  
Found - A 2 1/2" dia. DCSO brass cap on a 1 1/4" O.D. iron pipe flush with  
ground. (Per M 19-53) Ren. #166  
3/4" bolt with nut protruding 8" above ground bears N. 44 1/2° W.,  
0.8 ft. from DCSO BC/IP.  
BTs and BOs found as recorded in Ren. No. 166 (Apr. 19, 1899).  
All references with the exception of the 5/8" I.R. bearing S. 1° W., 223.68  
will be destroyed in near future by new highway construction.  
New BTs - 9" dia. I. Cedar double blazed and scribed "1/4 S34 CS BT"  
bears S. 82° W., 96.8 ft.  
19" dia. D. fir double blazed and scribed "1/4 S35 CS BT"  
bears N. 39 1/2° E., 197.4 ft.  
13" dia. double trunked I. cedar, double blazed and scribed  
"1/4 S35 CS BT" on west trunk, root crown bears N. 55 1/2° E.,  
176.3 ft.

3/29/90

171

North 1/4 Corner for Section 12  
CORNER REPORT  
Found - 1962 Douglas Co. brass cap. Ren. #73  
42" Fir stump, N. 70° W., 6.9 ft. (no marks) 1854 BT. (Not found  
in previous renewal)  
48" Fir stump S. 07° E., 9.3 ft. bark scribe 1854 BT.  
20" Fir, S. 65° W., 22.2 ft. scar visible. 1962 BT.  
24" Fir, N. 01° W., 20.8 ft. scar visible. 1962 BT.

Les Roberts  
L.S. 1039  
For: Seneca Timber  
June, 1990  
M 110 - 25

FND. OK 8-92  
B. ROGERS 1992-0059