

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 21 T. S. R 5 R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 21881

Douglas County
Surveyors Office
Randall Smith
Stephen J. Flauser
March 16, 1992
C.S. File 64/24

Tsp. Corner - SW Cor. Section 31 180
Found - 1990 DCSO brass cap flush with ground. (Set in 1990)
Note: Renewal of this corner not recorded in 1990. DCSO
BC/IP was set at position of stone. (Set by Haines in 1943,
Ren. No. 52) Stone was set along edge of BC/IP below ground.
40" now 46" dia. D.Fir with a fully healed blaze, bears
S.21°E., 31.0 ft. (agrees w/rec.) ren. No. 52
8" now 22" dia. d.Fir with a fully healed double blaze, bears
N.72°E., 56.0 ft. (agrees w/rec) Ren. No. 52
10" now 14" dia. B.Oak with a fully healed double blaze, bears
S.28°W., 18.8 ft. (agrees w/record)
8" now 11" dia. W.Oak with a fully healed double blaze,
bears N.2°W., 10.0 ft. (agrees w/record)
20" now 39" dia. W.Oak with a fully healed blaze, bears
S.7½°E., 97.9 ft. (Rec. S.7½°E., 95.7 ft. dist. is a face
measurement) Orig. BT.
24" now 24" dia. 1½ ft. high rotted Oak stump with a rotted
blaze, no scribing visible, bears S.13°W., 138.6 ft.
(agrees w/record) Orig. BT.

Randall W. Smith and Stephen J. Flauser set DCSO 1990 BC/IP during control
survey on file in Douglas County Surveyor's Office.

FD OK - M121-21 - 11/10/94

3/16/92

WEST ¼ COR. SECS. 14 & 15 181

No evidence found of Orig. Cor.

Set - 5/8"x30" iron pin by proportionate measure.
BTs - 18" Fir, S.82°E., 2.4', (scribed/painted red)
20" Fir, S.18°W., 18.2', (scribed/painted red)
12" Fir, S.81°W., 43.9', (scribed/painted red)
24" Fir, S.55°E., 21.5', (scribed/painted red)

9/93

COR. SECS. 14, 15, 22, & 23

Set corner from stump pattern and creek calls. 182

Found - Root hole, S.60°E., 14.2', 1856 BT.
Root hole, S.50°W., 40.3', 1856 BT.
Set - 5/8"x30" iron pin with yellow plastic cap.
BTs - 8" Fir, S.43°W., 16.0', (scribed/painted red)
10" Fir, N.52°W., 9.2' (scribed/painted red)
12" Fir, N.27°E., 20.0', (scribed/painted red)
18" Fir, S.23°E., 14.1', (scribed/painted red)

9/93

WEST ¼ COR. SECS. 22 & 23 183

Found - 1993 BLM Iron pipe and Brass cap
30" Fir, stump, N.08°W., 19.5', (scribe vis.), 1856 BT
12" Fir, S.78°E., 27.8' (scar vis.), 1965 CS BT (REN # 118)
22" Fir, N.65°W., 29.0' (scar vis.) 1965 CS BT

9/93

COR. SECS. 22, 23, 26, & 27 184

Found - 1993 BLM Iron pipe and brass cap
50" Fir, N.15°W., 10.0' (scar vis.), 1856 BT
8" Fir, N.85°W., 16.5' (scribe vis.), 1993 BT
8" Fir, S.30°W., 26.4' (scribe vis.), 1993 BT
10" Fir, S.60°E., 16.4' (scribe vis.), 1993 BT
16" Fir, N.32°E., 11.9' (scribe vis.), 1993 BT

9/93

Les Roberts, L.S. 1039
For: Giustina Timber Co &
Giustina Resources Inc.
July 30, 1993
M 117-53