

Douglas County Surveyor's Record of
Government Corners Renewed

21 T. S. 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97301

Douglas County
Surveyor's Office
Randall W. Smith, Deputy
Stephen J. Flause
3/31/94
C.S. File 64/51

185

1/4 Cor. Secs. 4 & 5

Found - Nail set by Les Roberts.

20" now down and rotting D.Fir, of indeterminable size with scribing found "S $\frac{1}{4}$ BT" bears N.75°W., 2.0' (Agrees with orig. rec. and nail by Les Roberts).

Orig. SE BT not FD.

Set - 2 3/8" dia., DCSO brass cap on a 1 3/8" by 32" long iron pipe is set at referenced position of nail. BC/IP protrudes 5" above ground. Stamped:

DOUGLAS COUNTY SURVEYOR'S

T 21 S
R
S5 | S4 5
1994 W
OFFICE

New Accessories -

8" dia., D.Fir, double blazed and scribed "1/4 S4 CS BT" bears N.6 $\frac{1}{2}$ °E., 12.8'.

12" dia., D.Fir, double blazed and scribed "1/4 S4 CS BT" bears S.71°E. 10.9'.

15" dia., D.Fir, double blazed and scribed "1/4 S5 CS BT" bears S.29 $\frac{1}{2}$ °W., 10.6'.

12" dia., D.Fir, double blazed and scribed "1/4 S5 CS BT" bears N.83°W., 13.5'.

See file for sketch.

Note - Corner lies on top of a North-South ridge approx. 100' West of a dirt road.

Les Roberts
M 120 - 64
Aug. 15, 94
for : Seneca
Sawmill Co. &
Giustina Resources

186

East 1/4 corner sec. 10

BT Fd. - 14" fir stub, N.40°W., 27.1' (scribe visible), 1856 BT.

Monument set -

5/8" x 30" i.p. at rec. bearing & distance

New Accessories -

12" fir, N.80°W., 50.1' (scribed/metal washer/painted red)

14" fir, S.56°W., 4.3' (scribed/metal washer/painted red)

18" fir, S.16°E., 1.6' (scribed/metal washer/painted red)

34" fir, N.76°E., 45.5' (scribed/metal washer/painted red)

SE CORNER SEC. 10

Monument Fd. -

1957 Wilford Haines "T" iron

BTs Fd. -

18" fir, N.86°W., 38' (scar vis.), 1957 B.T.

20" fir, N.21°E., 21.6' (scar vis.), 1957 B.T.

12" fir, S.70°W., 36.1' (scribe vis.), NO REC.

14" fir, S.51°E., 35.3' (scribe vis.), No REC.

187

Donald Peel
For: Weyerhaeuser Co.
Feb. 1992
M114 - 60

1/4 Corner for Section 32 and Section 5 of T.22-5

CONDITION REPORT ONLY See renewal #54.

Found - 1 1/4" iron pipe with Douglas Co. Brass Cap dated 1959.

19" Fir, S.72 $\frac{1}{2}$ °E., 70.0 ft. - closed face, BLM tag.

19" Madrone, S.55°E., 44.1 ft. - face rotted, no visible scribing, BLM tag.

38" Fir BT to north now uprooted and down.

188

Section Corner for 32, 33 and 4 & 5 of T.22-5.

CONDITION REPORT ONLY See renewal #53.

Found - 3/4" iron pipe

48" Fir, N.41 3/4°E., 12.2 ft. closed face BLM tag.

17" Fir stump, S.22 $\frac{1}{4}$ °E., 37.0 ft. - cut below scribing.

15" Fir stump, S.37 $\frac{1}{4}$ °W., 39.1 ft. - cut below scribing.

17" Fir, N.51 $\frac{1}{2}$ °W., 17.7 ft. - closed face.

RE-OPENED CORNER NO. #195 189