

Douglas County Surveyor's Record of
Government Corners Renewed

21 T. S. 5 R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21891

1/2 Section Corner to Sections 27 and 34. *Ren. #2*
Found - Fish Plate, knocked out & 2 Bearing Trees:
12" Fir N.49°E. 18.5 ft.
18" Fir S.49°W. 15.3 ft. *REN #2*
Reset Fish Plate with 1/2" Iron Pipe alongside.
Remark BT's.

55

RE-NEWED, SEE CORNER NO. 81

A. R. Evans, Deputy
Jan. & Feb. 1951
C. S. File 44/87
Map File M 11 - 1

N. W. Corner Estes D. L. C. No. 37.
Found - Rock at Fence Corner & 2 Bearing Trees: - *FD O.K. 12-1964 M.E.G.*
36" Cedar N.45°E. 22.2 ft.
14" Cedar N.80°E. 37.0 ft.
Both Mkd: N.W. Estes, D.L.C. S. B.T.

56

S. W. Corner Estes D. L. C. No. 37.
Found - Rotted Stump of O. B. T.:
Fir, now 24", N.5 1/2°W. 180 lks. faint scribe
mark visible.
Line Tree Fir bears East 2.29 chains.
Set 1" Iron Pipe for Corner, blazed & scribed 2 Bearing Trees:
14" Fir N.80°E. 4.2 ft. (Both BT's. mkd. S.W. Cor. Cl. 37,
18" Fir N.32°W. 7.9 ft. (CS BT.)

208 57

RE-NEWED, SEE CORNER NO. 208 57
FD PIPE & TREES IN GOOD COND. Dec 1964 M.E.G.

Int. E. Corner D. L. C. #37.
Found - Orig. Oak B.T. N. 4°E. 240 lks.
Orig. B.T. N.3°12'W. 132.1 ft.
Set 1" x 1" x 36" T Iron.
Scribed - 26" Douglas Fir S.20°E. 35 ft.

58

RE-NEWED, SEE CORNER NO. 107

Wilford N.
Haines
Aug. 26, 1959
Map File
M 15 - 36

Reset Corner to Secs. 6 & 7, T21S R5W. & Secs. 1 & 12, T21S R6W.
I find angle iron at true corner, as recorded by Haines,
from which corner as renewed by Kerr bears S.39°E. 7.2 ft.
The 1855 original survey records 12" Fir N.27°W. 9.9 ft. I
find stump of this BT. previously opened, shows good scribing.
SI checks for ring count & size. I find no 1884 BT's.
I move Brass Cap st for 1958 renewal, N.39°W. 7.2 ft. &
reset alongside angle iron set by Haines. - *REN. #28*
BT's. are as follows, recorded by Kerr:
28" R. Fir S.87°E. 10.4 ft. scribed on SW face.
22" R. Fir S.18°E. 15.2 ft.
14" R. Fir S.17°W. 21.5 ft.

59

RE-NEWED, SEE CORNER NO. #179
FDOCK PER GEISLER MAY-87 M104-14

James W. Byron
Milo Godfrey
Clete Putnam
Dec. 22, 1959
C.S. File No. 49/89

1/2 Section Corner To Sec. 19, T21S R5W & Sec. 24, T21S R6W. 60
As determined by old BT's:
10" Fir S.45°E. 10.6 ft. which is now 31" with visible
scribes.
6" Fir N.79°W. 10.6' which is now a decayed stump with some
scribe markings visible.
Set 1/2" x 36" Iron Pipe from which:
21" Fir bears S.79°W. 20.7 ft. marked 1/4 S24 B.T.
6" W. Red Cedar bears S.6°E. 34.4 ft. marked 1/4 S19 B.T.
Recent scribes on 36" Fir mkd. 1/4 S BT bears N. 7°W. 28.0 ft.
from which a scribed stake bears S.23°W. 8.5 feet.
This stake and scribed tree do not refer to this actual corner.
This corner is approximately 200 feet north of small creek and 120 ft. south of
south of ridge top.

60

Burton W. Holt
Witness: Ken Hebard
Feb. 24, 1960
C. S. File No. 51/71

Sec. Corner to Secs. 30 & 31, T21-5 & Secs. 25 & 36, 21-6.
Found T. Iron & BT's. which had been damaged by Fire:
Maple S.58°W. 14.5 ft. - *REN #22*
I. Cedar N.69°W. 14.2 ft.
Scribed - 12" Cedar S.11°W. 83.6 ft.
16" Fir N.53°W. 54.3 ft.

61

RE-NEWED, SEE CORNER NO. 113

Wilford N.
Haines.
Woolley Logging .
July 1961
M 20 - 76