

Douglas County Surveyor's Record of
Government Corners Renewed

T. 21 S. T. S. R. 5 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

84

S31	S32	T20S
S 6	S 5	T21S R5W

Found - Dead Fir Snag, now 66", N.18°E. 17.1 ft., previously opened. scribing visible on old face "S & W" & portions of other letters. 42" R. Cedar N.68°W. 5.3 ft., center dead, no scribing visible. Cedar S.70°E. 21.1 ft. is uprooted & down, impossible to fix exact location where it stood. Did not find S.W. tree.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962

S31	S32	T20S
S 6	S 5	T21S R5W

New BT's: 42" Cedar N.68°W. 5.3 ft. Mkd: T20S R5W S31 CS BT(rescribed)
6" Hemlock N.10°E. 20.6 ft. Mkd: T20S R5W S32 CS BT.
38" R. Cedar S.53°W. 87.6 ft. Mkd: T21S R5W S6 CS BT.
No suitable trees near in Section 5.

85

1/4 Corner to Section 29 and 28.

Found - Scribed Stake & 3/4" Iron Pipe in fence corner, fences N. S. & E. Set by Thiel. - *REN. #6*

36" Fir N.18 1/2°E. 19.1 ft., shows good scars. Tree leans to East. Cedar Stump N.73°W. 39.3 ft., not 35.3 ft. scribing plainly visible. Rotted Base of Fir Stump N.59°E. 35.6 ft. too far gone to find scars or scribing.

No trace found of Original N.W. BT.

DID NOT SET BRASS CAP.

New BT's: 30" E. Cedar N.85°W. 38.3 ft. Mkd: 1/4 S29 CS BT.
36" Fir N.18 1/2°E. 20.0 ft. (to center) Mkd: 1/4 S28 CS BT(rescribed)

86

Section Corner to Sections 21 - 22 - 27 - 28.

Found - 1/2" Pipe set by Thiel. A badly burned Stake alongside pipe and remnants of scribing still visible. - *REN. #5*

Fir Stump N.63°W. 11.8 ft., good scribing visible "BT".

Fir Stump S.81°W. 12.2 ft., shows good scar.

Fir Stump N.79°E. 23.1 ft., scar not very noticeable.

Fir Stump S.24°E. 42.2 ft., shows faint scar.

Badly rotted stumps of Orig. N.W. & SW. BT's. No scars or scribing visible now.

1/2" Pipe extends 14" above ground, no new monument set.

New BT's: 15" Chinquapin S.31°E. 126.8 ft. Mkd: T21S R5W S27 CS BT.

9" D. Fir N.18°E. 98.4 ft. mkd: T21S R5W S22 CS BT. - *See Ren. No. 99 for New BT.*

No live trees available west of line.

Drove 3/4" I. Rod West 89.3 ft. from Corner in N. & S. fence line on west side of Churchill Road.

87

1/4 Corner to Sections 27 and 34.

In 1902 O.F. Thiel Mkd 2 New BT's See C.S. 64/48 Pg 13

Found - Angle Iron set by Frear with 3/4" I. Pipe set by Evans, alongside.

Stake scribed "1/4 S27 CS" on N. face & "S34" on S. face. - *REN. #2 #55*

Fir Stump S.49°W. 15.3 ft. scribing "1/4" visible on old face.

Fir Stump N.49°E. 18.3 ft. scribing visible on old face.

DID NOT SET BRASS CAP.

New BT's: 10" D. Fir N.25°E. 14.4 ft. Mkd: 1/4 S27 CS BT.

12" D. Fir S.72°W. 40.6 ft. Mkd: 1/4 S34 CS BT.

No trace of Original Bearing Trees found. Corner lies in N. & S. fence line.

88

Section Corner to Sections 28 - 29 - 32 - 33.

Found - 60" Fir N.63°E. 35.0 ft., old bark scribing visible "T 2 R".

56" Fir N.84°W. 62.0 ft., old bark scribing visible "S29 T21S R5W".

28" I. Cedar S.55°W. 72.6 ft. shows two faint scars.

Did not find S.E. Bearing Tree - Corner falls in bottom of deep gully.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962

20 ft. North of cor. for Wit. Cor. T.21S R5W W.C.

S29	S28 20' S.
S32	S33 to Cor.

New BT's: 9" W. Fir S.65°W. 20.6 ft. Mkd: T21S R5W S32 CS WC BT.

6" I. Cedar N.71°W. 38.2 ft. Mkd: T21SR5W S32 CS WC BT.

16" R. Cedar N.48°E. 47.3 ft. Mkd: T21S R5W S28 CS WC BT.

18" D. Fir S.56°E. 62.0 ft. Mkd: T21S R5W S33 CS WC BT.

Milo E. Godfrey, Deputy County Surveyor
Vernon Tracy and Cleto Putnam
April 1962
C. S. File No. 49/89.

*FD 1184
L. DeWan
M92-5*

*FD 1184
2/94 C. Mullins
M118-63*