

Douglas County Surveyor's Record of
Government Corners Renewed

T. 21 S. T. S. R. 6 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

111
 $\frac{1}{4}$ Section Corner to Sec. 7, T21-6W. & Sec. 12, T21-7W.
 Found - "T" Iron set by Haines. See Ren. No. 37.
 24" Fir N.72°W. 19.8 ft, scribing visible on old face,
 prev. opened, " $\frac{1}{2}$ " S".
 Badly rotted Fir Stump N.28°E. 20.5 ft., No marks found.
 New BT's: 9" D. Fir N.88°E. 18.6 ft. Mkd: $\frac{1}{2}$ S7 CS BT.
 7" D. Fir N.16°W. 17.4 ft. Mkd: $\frac{1}{2}$ S12 CS BT.
 Old N. W. Tree appears to be dying.

Miloe E.
 Godfrey &
 Crew.
 Mar. 3,
 1964
 C.S. 49/143

112
 $\frac{1}{4}$ Section Corner to Secs. 26 and 27.
 This $\frac{1}{4}$ corner may be destroyed by the construction
 of logging road so I mark reference points as shown
 on sketch in C. S. File No. 51/222.
 Set - 1" x 1" x 1" T. Iron S. 67°52'E. 116.36 ft.
 Maschery Nail in N. face of Rock Outcrop 2' x 3',
 S. 67°52'E. 172.68 ft. from Orig. Cor.
 Note - For Renewed Corner See Cor. No. 87.

Wilford N.
 Haines
 Sept. 1964
 C. S. File
 No. 51/222

113
 Sec. Cor. to Secs. 25 & 36, T21-6W. & Sec. 30 & 31, T21-5W.
 Found - "T" Iron at Corner from which: See Ren. #43
 12" I. Cedar, now snag, S.11°W. 83.6 ft., scribing vis.
 16" Fir N.53°W. 54.3 ft., bark scribing visible.
 (Rescribed in Wood T21S R6W S25 CS BT)
 New BT's: 12" Maple S.26°W. 76.9 ft. Mkd: T21S R6W S36 CS BT.
 (78° @ - 94°)
 12" Cedar S.45°E. 184.3 ft. Mkd: T21S R5W S31 CS BT.
 (100° @ 14 $\frac{1}{2}$ ° plus 92° @ 18°)

Bruce R.
 Rogers, Deputy
 M. Stone
 C. S.
 File
 No
 53/101

114
 Sec. Corner to Secs. 12 & 13, T21-6W. & Secs. 7 & 18, T21-5W.
 Found - Co. Surv. Brass Cap as recorded in Ren. #81 &
 BT's., as follows:
 Orig. 24" Cedar N.75°W. 23.1 ft.
 Orig. 40" Fir Stump N.47°E. 5.3 ft.
 Orig. 34" Fir Stump S.54°E. 9.4 ft.
 New BT: 7" Chinquapin N. 78° E. 19.9 ft. Mkd: T21S R5W S7 CS BT.

Vernon "Ray"
 Tracy & Crew
 C. S. File
 No. 54/14

115
 Township Corner :
 Found - Haines' "T" Iron, See Ren. #43, under a 16" Log,
 set from Orig. BT, as follows:
 Orig. 20", now 28" Fir, N. 59° E. 37.6 ft. Open & find
 "31 T21 6W" scribe. Now Snag.
 All other BT's. destroyed.
 Set - Brass Cap 6" S. of "T" Iron alongside of Log & Mkd:
 County Surveyor's T21S R7W S 36 | S 31 R6W
 Office, 1966 T22S S 1 | S 6
 New BT's: 7" Hemlock N. 26° W. 13.2 ft. mkd. T21S R7W S36 CS BT.
 9" Hemlock N. 80° E. 24.9 ft. Mkd: T21S R6W S31 CS BT.
 26" R. Cedar S. 61° E. 29.9 ft. mkd. T22S R6W S6 CS BT.
 No suitable tree close to S. W.
 Corner lies on steep, N. W. Slope.

Vernon "Ray" Tracy
 Joe Brady & Jack Heritage
 Sept. 1, 1966
 C. S. File No. 54/14

116
 $\frac{1}{4}$ Corner to Sections 13 and 24.
 No trace of Original Corner - SET - $\frac{1}{2}$ " Steel Rod at Corner. #169
 Scribed - 10" Fir S. 27° W. 13.9 ft.
 7" Fir N. 40° W. 44.7 ft.

Wilford N. Haines
 For Wobley Logging
 Dec., 1966
 Map File M 32 - 44

117
 $\frac{1}{2}$ Corner to Section 23 and 24.
 Found - 36" D. Fir, bark scribed, now 48", rescribed below old scribe.
 (S.87° W. 30 lks.)
 12" Fir, now stub, no scribe.
 Set - $\frac{1}{2}$ " Steel Rod at $\frac{1}{4}$ Corner.
 New BT: 28" Fir S. 50° E. 34.1 ft.