

Douglas County Surveyor's Record of  
Government Corners Renewed

21

T. S. 6

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21851

L.E. Monrean  
P.L.E.  
C.S. 57/36  
10/30/75

1/4 Corner to Section 2 and 3

130 Ren.#84

Found: 1961 CS Brass cap properly stamped.  
BT's 44" now 39" Fir stump bears S49 1/2°E., 11.0 ft. (Rec. S55°E., 10.6 ft.)  
stump is rotted, has bottom of blaze no scribing.  
36" now 33" diameter fir stump bears S67°W., 10.6 ft. (rec. 9.2 ft.) shows  
good scar nearly healed over, portion of scribing visible, stump  
has been capped with aluminium sheeting, bark has been removed and a  
preservative applied to wood.  
6" now approx. 14" Dia. Hemlock stump bears N 52 1/2°E., 24.3 ft. to face  
(rec. 24.1). Shows good blaze, scribed "S2 CS BT" visible, stump has  
been shattered and in poor condition.

New-BT's-

21 1/2" dia. maple S3 1/2°E., 173.5 ft. scribed "1/4 S2 CS BT"

Note: Corner lies on easterly slope, approx S25°E., 200 Yds from end of BLM  
road #21-6-3.1 off Blind Creek Rd. Corner lies approx 200 ft. west of  
creek bottom and approx 400 ft. east of deep saddle on ridge top.  
Maple bearing tree is on south edge of recently cleared area.

10/30/75

Gary Langlitz  
Clell Goodwin  
M. Lenora Ladig  
CS 57/39  
12/9/75

1/4 Corner to Sec. 14 & 13

REN#59

131

Found- 1"x1" T-Iron (Haines, 1961)-firmly set at the corner point, from which  
OBT-a 60" now 68" D Fir bears S 28°E., 27.7ft., alive, no marks visible.

a 18" fir now a 36" stump bears N 66°W., 25.1ft. Decaying with no marks  
visible. Trees Marked by Haines in 1961 as follows.

A 16" now 20" D fir bears S 85°E., 49.8ft. (Rec. S 85°E., 48.5 ft.) alive with  
bark scribe " 1/4 S 13 BT" visible.  
and a 28" D Fir now a 30" stump bears N77°W., 36.2 ft. now marks visible. At  
the corner point, we set a 1" X 30" iron pipe, with brass cap attached  
marked:

DOUGLAS CO. SURVEYOR  
1975

T21S  
R6W

1/4 S14 S13

We place the "T-iron" along side the brass cap and mark the following New  
BT - A 7" Hemlock bears N 57°W., 30.8 ft. scribed " 1/4 S 14 CS BT" on a  
double blaze. Compass declination setting; 20° East

Note: This corner is located along a dirt road approx. 300 ft. from it's  
intersection with the south fork of Smith River Access Road. 12/9/75

1/4 Corner Sec. 11 & 14 *ADOK Christensen 1/1999 M131-17* REN # 85

132

12/20/75

Found- A 1" X 30" IP with brass cap from County Surveyor 1961 properly  
marked.

From which: The stump hole from a 72" blown down fir bears N21°E., 28.4 ft.  
A 24" fir alive and well healed bears S 55°E., 13.4 ft.

A 15" Hemlock with visible scribe marks bears N 37°E., 46.0 ft. now blown down  
New BT - A 13" hemlock scribed " 1/4 S11 CS BT" in a double blaze. Bears N29°E  
16.3 ft. Compass Declination 20° East

*JAN 76  
JAN 78  
1-78*

Sec. Corner to Secs. 25 & 36; and Secs. 30 & 31, T.21S. R.5W.

133

Found - Haines "T" Iron protruding approx. 10" from ground and  
firmly set from ren. #22. (T21-5) *SEE ALSO REN. #113*

We found no evidence of the original 6" B. Oak or the original  
8" fir.

An original 18" fir now a 30" stump at record bearing and dist.  
An original 45" fir now a 49" stump at record bearing and dist.  
Both stumps are cut low and we find no scribing or blazes.

Haines BT's from ren. #22 gone, we find some evidence of fire  
having burned area since then as noted in ren. #62.98

A 12" Cedar now a 17" cedar snag 25 feet tall bears S.11°W.,  
85.5 feet (Rec. dist. 83.6 ft.) partially healed single blaze  
has scribing "T21S R6W S30" visible (Should be S36) with Haines  
washer at bottom of blaze.

A 16" now a 24" D. Fir bears N.53°W., 52.3 ft. (Rec. dist. 54.3  
ft.) double blaze with no scribing visible.

A 12" now a 15" Maple bears S.26°W., 77.9 ft. (Rec. dist. 76.9  
ft.) has partially healed double blaze with scribing "T21S R6W  
S36 BT" visible.