

Douglas County Surveyor's Record of
Government Corners Renewed

21 T. S. 6 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21861

133

Secs. 25 & 36, T.22S. R.5W. and Secs. 30 & 31, T.21S. R.5W. (cont.)

We do not find any evidence of 12" cedar.

Set- Accepting the position of Haines "T" Iron as the original corner position because of agreement of bearing and dist. calls to orig. BT's stumps and stream call 0.6 chains south of corner we reference out "T" iron.
Set a Douglas County Surveyor's Office brass cap on 1" x 30" iron pipe properly stamped and replace "T" iron on north edge of cap.

New BT's- An 11" D. Fir bears N.45°E., 17.0 ft. scribed on double blaze "T21S R5W S30 CS BT".

We tag original BT stumps and all other found BT's. Cap and "T" iron are approx. 25 ft. east of a random north/south fenceline.

Stephen J. Flause
Terry Plouff
D.C. Surveyor's Office
April 1980
C.S. 61/6

134

1/4 Corner to Sec.'s 19 & 20.

Found - Haines T iron bent to North, still solid, app.18" in ground.
Renewal # 104.

52" Fir (Orig. 10"), fnd. with open blaze. Face is 24" in from outside of tree with no scribing visible. A bark scribed "BT" is visible above blaze. This tree bears S52°W., 48.8-ft.

Orig. Dogwood is completely gone (NOT fd.).

15" Fir (Orig. 9"), bears S.7°E., 65.4-ft., with well healed double blaze.
Renewal # 104.

26" Fir (Orig. 20"), with well healed double blaze, (1/4S scribed in bark above blaze) bears S.78°W., 53.2-ft. (REC. S.75°W., 51.1-ft.)
Renewal # 104.

Set - Brass Cap protruding 10" above ground, stamped "DOUGLAS CO SURVEYOR 1981 T21S 1/4 S19 S20 R6W". (T iron was reset alongside B.C.)

New B.T. 6" Fir bears N.13°E., 18.7-ft., scribed "1/4 S20 CS BT" in double blaze.

DCSO BT tags put on all trees.

Gregory E. Quibell
D.C.Surv. Office
Debbie Stewart
June 22, 1981
C.S. 61 / 24

135

1/4 Corner to Secs. 26, & 27.

Fd - "T" bar (reference monument), S.67°32'58"E., Renewal #112.
116.36-ft. from I. Pipe.

Masonry Nail in Brass Disc in rock face, S.67°32'58"E., 56-ft.± from "T" bar.

Set - 1-1/2" x 36" I. Pipe w/Brass Cap in mound of stone mkd: T21S R6W 1/4 S27 S26 PLS 752 1982.

New BTs- 7" fir, N.89°E., 61.5-ft.

8" fir, S.8°W., 78.8-ft. 7/12/82

Donald L. Peel,
L.S.#752
For: I.P. Co.
July 12, 1982
C.S. 58/274
M 92 - 48

Center 1/4 Corner of Sec. 26.

Set - 1-1/2" x 36" I. Pipe w/Brass Cap mkd: T21S R6W C1/4 S26 PLS 752 1982.

New BTs - 7" fir, N.70°E., 6.5-ft.

8" fir, S.25°W., 16.4-ft.

137

Township corner, Secs. 36, 31, 1 and 6; of T.20-5 & 6
T. 21-5 & 6.

Found - 1958 Doug. Co. brass cap lying on ground alongside road.
Also found hole which brass cap had been pulled out of. Ren. #29

Cap marked: Doug Co. Lane Co.

	1958		
R	T 20	S	R
6	S 36	S 31	5
W	S 1	S 6	W
	T 21 S		

USBLM 1962

Surveyors Office

Gregory Quibell
Deputy, Doug. Co.
Surveyors Office
Randy Smith
John Powell
May 10, 1983
C.S. 62/7

From hole BT's bear:

Orig. 30" now 52" cedar with well healed blaze bears N.36°E., 69.3 ft.

Orig. 20" now 48" sawed fir stump with well healed blaze bears S.82°W., 58.7 ft.