

Douglas County Surveyor's Record of  
Government Corners Renewed

T 21 T. S. R 6 R.W.W.M.

146

Cont - - - -

Doug. Co. Surveyors Off.  
R. Smith; S. Flause  
Feb. 24, 1992  
C.S. File 64/24

New BTs - 13" dia. W.Fir double blazed and scribed "T22S R6W S4 CS BT"  
bears S.58°W., 38.8 ft.  
13" dia. W.Fir double blazed and scribed "T22S R6W S3 CS BT"  
bears S.18½°E., 33.2 ft.  
Corner lies at the intersection of a west and south running fence lines.  
*Fd OK 2-24 M118-37* 2/24/92

1/4 Corner between Sections 22 & 27.

147

Found - 'T' iron with brass washer marked R.L.S. 239  
protruding 10" above ground. See renewal # 55.  
3½" brass cap on 2½" dia iron post, firmly set protruding  
2" above ground. Cap marked U.S. Bureau of Land Management  
Dept of Interior 1979. (next to 'T' iron)

Accessories Found -

16" fir now a 36" D.B.H. D.fir with a fully healed double  
blaze, (original tree) rescribed with the bark scribing  
'1/4 S27 BT' renewal # 55 bears S.50½°E., 16.4 ft. (Original  
record S.50½°E., 15.2 ft.)  
10" fir now a 3½' tall 16" dia. D. fir stump with a fully healed  
double blaze, with the bark scribing '1/4 S22 BT', bears  
N.50½°W., 12.5 ft. (original BT rescribed by Haines Ren.55)  
10" fir now a 17" D.B.H. D. fir with a fully healed double blaze  
bears N.04°W., 92.4 ft. (1979 BLM tree)

New BT - 5" D.B.H. D. fir scribed '1/4 S27 CS BT' on a double blaze bears  
S.74°W., 35.8 ft.

Note - Corner is on west slope just off crest of north-south ridge  
where ridge intersects east-west cutting line; small trees  
to north and old growth to south of line.

5/1/92

148

Corner common to Sections 22,23,26 and 27.

Found - A 12" x 14" x 36" stone with an "X" scribed in top, partially  
buried and firmly set.  
'T' iron on west edge of above stone with Haines identifying  
brass washer missing protrudes 14" above ground and is firmly  
set. See renewal # 88.

Accessories Found -

16" D. fir now a 37" D.B.H. with a fully healed double blaze  
bears S.46°E., 9.9 ft. (original tree)  
7" Red cedar now a 16" D.B.H. with a partially healed single  
blaze scribed 'S23 T21S R6W BT' bears N.51°E., 12.1 ft. (rec  
dist. is to Haines washer on tree) See renewal # 88.

New BTs - 15" D B H. Maple scribed 'T21S R6W S27 CS BT' on a double blaze  
bears S.09°W., 44.1 ft.  
5" D.B.H. D. Fir scribed 'T21S R6W S22 CS BT' on a double blaze  
bears N.18°W., 11.7 ft.

Note - Corner is in NW corner of clear cut unit, other 3 quadrants  
are old growth and large second growth. Monument is 150'  
northerly from sharp switch back in dirt logging road.

5/1/92

149

Section Corner for Secs. 14, 15, 22 and 23

Found - Haines T Iron protruding 15" above ground. Ren. #53  
DCSO 2½" dia. brass cap on a 1½" O.D. ironpipe, protruding  
14" above ground. Ren. #128

An original corner stone measures 18" x 12" x 4" with "X" on  
flat side, lies loose on top of ground along northeast side  
of DCSO BC/IP.

DCSO BC/IP bears S.0½°E., 5.0 ft. from Haines T Iron (Rec.  
S.4°E., 5 ft.)

Accessories Found: (Brgs' & dists taken from Haines T-Iron):

36" now 30" dia. 7 ft. high rotted and burnt D.Fir snag, no  
scribing visible, bears S.50½°W., 41.8 ft. (orig. Rec.  
S.52°W., 40.9 ft.)  
60" now 48" dia. 3 ft. high rotted and burnt D.Fir stump, no  
scribing visible, bears N.60°W., 66.9 ft. (Orig. rec. N.57°W  
64.0 ft.) Orig. BT.  
54" now 40" dia. 10 ft. high rotted and burnt D.Fir snag, no  
scribing visible, bears N.28½°E., 51.3 ft. (orig. rec.  
N.30°E., 60.7 ft., dist. is a slope measurement) Orig. BT.  
40" now 38" dia. down, a rotted D.Fir with an open rotted  
blaze, root hole bears S.42½°E, 67.3 ft. (Orig. rec. S.41°E.,  
67.3 ft.) Orig. BT.

Douglas County Surveyors Office  
Stephen J. Flause, T.R. Fransen  
April 15-16, 1992  
C.S. 64/26

Douglas County  
Surveyors Office  
Larry E. Monrean  
Randall Smith  
April 4, 1992  
C.S. File 64/26

*Fd OK  
Christensen  
1/1999  
M131-17*

Cont. Next Page - -