

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 21 T. S. R 6 R. W. W. M.

149

Cont - - - - -

Doug. Co.
Surveyors Office
Larry Monrean
Randall Smith
April 4, 1992
C.S. File64/26

16" now 30" dia. D.Fir with a fully healed single blaze, bears N.82°W., 17.6 ft. (agrees w/rec) Ren. No. 53
10" now 15" dia. D.Fir with a fully healed single blaze, bears S.17°E., 10.4 ft. (agrees w/rec) Ren. No. 53
Set - 1975 DCSO Brasscap/iron pipe from Ren. No. 128 set in error. Brass cap is removed from IP - IP protudes 11" above ground with a yellow DCSO plastic cap inserted in center. Original stone is placed along northeast edge of Haines T Iron. From Haines T Iron, bearings to orig. BTs have a small rotation to the left. Distances are acceptable. (one slope distance)
New BT - 13" D.Fir double blazed and scribed "T21S R6W S15 CS BT"
1975 DCSO BC/IP set by a proportion method from orig. BTs. Review of distances to BTs in field uncovered probable distance errors in Ren. 3128 resulting in an errant setting of BC/IP.

4/15/92

1/4 Corner for Sections 1 & 12.

150

Found - 1962 B.L.M. Brass Cap.
Fd BT's - 22" Fir stump, S.45°W., 14.4 ft. (scribe vis.) 1884 BT
16" Maple, N.12°W., 25.5 ft. (scar vis.) 1962 BT
New BT's - 22" Fir, S.02°E., 42.1 ft. (scribed/washer/painted red)
24" Fir, N.82°W., 35.7 ft. (scribed/washer/painted red)

1/4 Corner for Sections 11 & 12.

151

Found - 16" downed Fir, N.58°E., 13.2 ft. (no marks) 1884 BT.
(1945 GLO bearing tree tag nailed to tree)
18" Fir stub, S.87°W., 4.6 ft. (chaining notch vis.)
1884 BT.
Set - 5/8" x 30" iron pin with yellow plastic cap. Iron pin set from original 1884 Southwest BT.
New BT's - 8" Fir, N.38°W., 26.8 ft. (scribed/washer/painted red)
12" Fir, N.31°E., 29.4 ft. (scribed/washer/painted red)
Note - Corner lies on south slope about 150 ft. north of draw.
Draw bears S.45°E.

Center 1/4 Corner for Section 12.

152

Set - 5/8" x 30" iron pin with yellow plastic cap.
New BT's - 8" Fir, S.74°E., 28.4 ft. (scribed/washer/painted red)
14" Fir, N.61°W., 16.9 ft. (scribed/washer/painted red)
18" Fir, N.07°E., 18.4 ft. (scribed/washer/painted red)
22" Fir, S.31°W., 27.9 ft. (scribed/washer/painted red)

Ren. #121

153

West 1/4 cor. sec. 34
Found - No evidence of original corner.
Set - 5/8" x 30" I.P. Haines "T" iron set in M32-71 bears S.22°39'E., 15.48' see C.S. 54/14.
New BT's - 12" fir, N.04°E., 19.5' (scribed/washer/painted red)
14" fir, S.79°W., 23.8' (scribed/washer/painted red)
12" fir, S.30°W., 18.1' (scribed/washer/painted red)
8" fir, S.01°E., 18.5' (scribed/washer/painted red)

South 1/4 cor. sec. 34

154

Found - No evidence of original corner.
Set - 5/8" x 30" I.P.
New BT's - 12" fir, N.17°E., 47.4' (scribed/washer/painted red)
14" fir, S.82°W., 42.5' (scribed/washer/painted red)
12" fir, N.64°W., 50.7' (scribed/washer/painted red)
22" maple, N.75°E., 22.1' (scribed/washer/painted red)

East 1/4 cor. sec. 34

155

Found - Haines "T" iron set in survey M8-30
12" fir stump, N.46°W., 240.4' (scar vis.) 1957 B.T.
28" fir stump, S.19°E., 142.2' (scar vis.) 1957 B.T.
Set - 16" Fir, N.80°W., 25.1' (scribed/washer/painted red)

Les Roberts
For: Seneca Timber Co.
April 20, 1993
M 116-77, C.S. 63/153

Les Roberts
for: Seneca Timber Co.
Feb. 10, 1994
M 118 - 39