

**Douglas County Surveyor's Record of
Government Corners Renewed**

T. 21 S. T.S. R. 6 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

98
 Found - $\frac{1}{4}$ Corner to Sec. 13, T21-6W. & Sec. 18, T21-5W.
 Found - 33" D.Fir S.19°E. 31.0 ft., chopped open & fd. good scribing,
 portion of "S".
 42" D.Fir S.17°W. 22.4 ft., partially opened previously, but
 not deep enough to expose scribing.
 Set - Brass Cap at Cor. Mkd: County Surveyor's T21S S13/S18 $\frac{1}{4}$
 Office, 1962 R6W R5W
 New BT's: -Blaze & Rescribe Original Trees:
 33" D.Fir S.19°E. 31.0 ft. Mkd: $\frac{1}{4}$ S18 CS BT.
 42" D.Fir S.17°W. 22.4 ft. Mkd: $\frac{1}{4}$ S13 CS BT.
 Corner lies on west slope of spur running south from ridge top.
 Corner approximately 60 ft. west of top of spur.

*Fd 7/87
D. PEET
#108-55*

99
 Section Corner to Sections 8 - 9 - 17 - 16.
 Found - Haines "T" Iron at Corner & 36" Fir N.30°W. 37.6 ft. chopped
 open & found good scribing, part of "R" or "B". - ~~SEE COR #106~~
 No trace of any of the other 3 original BT's.
 Blaze & Rescribe: 36" Fir N.30°W. 37.6 ft. Mkd: T21S R6W S8 CS BT.
 New BT's: 9" Hemlock N.52°E. 52.9 ft. Mkd: T21S R6W S9 CS BT.
 10" Hemlock S.58°E. 31.8 ft. Mkd: T21S R6W S16 CS BT.
 9" Hemlock S.14°W. 35.7 ft. Mkd: T21S R6W S17 CS BT.
DO NOT SET BRASS CAP
 Corner lies in slide area on a very steep N.W. slope approx.
 100 ft. south of a sharp draw running N.E.

100
 Section Corner to Sections 4 - 5 - 8 - 9.
 Section 4 - 5 - 8 - 9.
 Found - Haines "T" Iron at Corner & 8" Fir, now 36", N.64°E. 29.0 ft.
 Cut open & found good scribing "S R6".
 10" Fir, now 38", S.74°E. 28.4 ft. shows good scar. Do not open.
 Badly rotted Fir Snag bears N.20°W. 18.5 ft. No scars or
 scribing found - too much of it rotted away. #139
 No trace found of S.W. BT.
 Set - Brass Cap at Cor. alongside Haines "T" Iron, Mkd:

S5	S4	T21S
S8	S9	R6W

 County Surveyor's Office, 1962
 Rescribe - 38" Fir S.74°E. 28.4 ft. Mkd: T21S R6W S9 CS BT.
 New BT's: 30" D.Fir N.81°E. 36.8 ft. Mkd: T21S R6W S4 CS BT.
 12" D.Fir S.87 $\frac{1}{2}$ °W. 98.0 ft. Mkd: T21S R6W S8 CS BT.
 25" D.Fir N. 1°W. 64.3 ft. Mkd: T21S R6W S5 CS BT.

*Fd. 4/87
D. MARY
#105-46*

RE-RENEWED SEE CORNER NO. #139

Milo E. Godfrey, Deputy County Surveyor
 Vernon Tracy and Clete Putnam
 April 1962
 C. S. File No. 49/143

101
 $\frac{1}{4}$ Corner to Sections 15 and 14. #131-17 1-1989 H. Christensen
 Found - Badly rotted Hemlock Stump S.53°E. 11.9 ft., scribing visible
 on old face " $\frac{1}{4}$ S".
 Badly rotted Hemlock Stump S.57°W. 16.5 ft., fd. fragment
 of scribing, part of "B".
 Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962
 T21S R6W $\frac{1}{4}$ S15/S14
 New BT's: 5" Hemlock S.41°W. 10.8 ft. Mkd: $\frac{1}{4}$ S15 CS BT.
 5" Hemlock N.30°E. 6.0 ft. Mkd: $\frac{1}{4}$ S14 CS BT.
 Corner lies on steep N.W. slope approx. 100 ft. South of small stream.

102
 Section Corner to Sections 10 - 11 - 14 - 15. *Fd. OK JUNE 2002 BY R. WARD - M140-36*
 Found - Haines "T" Iron & Cap at Cor. & Cedar Snag, now 33", N.56°W.
 5.9 ft. chopped open & fd. good scribing. - ~~SEE COR #97~~
 R. Cedar S.29°E. 21.1 ft., now 28", shows good scar.
 Blaze & Rescribe this Tree, "T21S R6W S14 CS BT".
 Fir, now 53", N.34°E. (not N.45°E.) 38.9 ft. Old bark sluffing off.
 No scribing found, blaze & rescribe (one blaze) T21SR6WS11CS BT.
 Fir to S.W. is uprooted & down. Bark all gone, no scribing.
DID NOT SET BRASS CAP.
 New BT's: 12" Hemlock N.54°W. 42.6 ft. Mkd: T21S R6W S10 CS BT.
 8" Hemlock S. 4°W. 7.2 ft. Mkd: T21S R6W S15 CS BT.