

Douglas County Surveyor's Record of  
Government Corners Renewed

21

T. S.

8

R. W. W. M.

ROCKY MOUNTAIN CO., EUGENE, ORE. 97185

Wm. J. Brayton  
Reg. Eng. #2793

Filed Oct. 1, 1949  
C.S. 40/205

John M. Phillips  
For Snellstrom Lumber  
August 20, 1959  
C.S. File No. 51/37

Milo E. Godfrey, Deputy County Surveyor  
Wm. Stoffel and Mike Stone  
September 1963  
C.S. File No. 52/14

$\frac{1}{4}$  COR. BET. 3-10

Set a four inch square cedar post as the quarter corner bet. secs. 3-10, with the following B. T's.

32" Fir, North 3\* W 21.4 ft.

12" Fir, S 75\* W 19.6 ft.

9" Hemlock, S 73\* E 17.2 ft.

1

$\frac{1}{4}$  Section Corner to Sections 27 and 34.

Done at the request of B.L.M.

Found - Brass Capped Iron Pipe markd  $\frac{1}{4}$  S27 at approximately S34

the location it was before being disturbed by tractor operations. It was pulled loose from the ground & the pipe was bent.

I obtained resurvey notes from B.L.M. as follows:

56" Fir bears N.65°45'E. 307 lks. dist. mkd.  $\frac{1}{4}$  S27 B.T.

62" Fir bears S.54 $\frac{1}{4}$ °E. 410 lks. dist. mkd.  $\frac{1}{4}$  S34 B.T.

I found the 56" Fir and a hole on the edge of the road where the 62" Fir apparently used to be. It is now a windfall and has been bucked. I reset the pipe from the 56" Fir. This location tallies with the original location I remember before the logging commenced.

Note - See sketch of Corner location in file.

2

South  $\frac{1}{4}$  Corner for Section 31, only.

(on N. Line of Sec. 6, T22-8W.)

Found - Brass Cap set by Cadastral survey in 1945. - See Gov't Notes Vol. 33 Pg. 13731

Stump of 38" Fir N.30°E. 149.8 ft.

34" Fir N.77 $\frac{1}{2}$ °E. 25.1 ft., no scribing visible. Old face badly burned, Blaze & Rescribe,  $\frac{1}{4}$  S31 CS BT".

60" Fir N.72°W. 134.0 ft., recently blazed & scribed  $\frac{1}{4}$  S31 BT".

3

Wit. Cor.  $\frac{1}{4}$  Cor. Section 6, T22S R8W.

(on S. Line of T21S R8W)

Found - Brass Cap set in 1945.

Both BT's. mkd. in 1945, uprooted stumps only, both show good scars.

$\frac{1}{4}$  Corner, W. Fir Tree, uprooted & down.

New BT's: 9" W. Fir S.25 $\frac{1}{2}$ °W. 36.0 ft. Mkd: W C  $\frac{1}{4}$  S6 CS BT.

7" W. Fir S.18°W. 43.2 ft. Mkd: W.C  $\frac{1}{4}$  S6 CS BT.

4

Closing Corner Sections 2 and 1, T22S R8W.

(on S. Line Sec. 35, T21S R8W)

Found - Brass Cap set in 1952.

All BT's. called for in gov't. notes(1952), but all are uprooted & down, fairly recent.

New BT's: 11" D. Fir S.83°W. 63.7 ft. Mkd: T22S R8W CC S2 CS BT.

22" Madrone N.36°W. 94.0 ft. Mkd: CC S1 S2 CS BT.

No trees available in Section 1.

Note - Bottom of blaze on Madrone 4 feet above ground.

5

North  $\frac{1}{4}$  Corner to Section 1, only.

(on S. Line Sec. 36, T21S R8W)

Found - Brass Cap set in 1952.

42" D. Fir S.26 $\frac{1}{2}$ °E. 36.3 ft., very plain axe blaze visible.

55" Fir S.49 $\frac{1}{2}$ °W. 37.0 ft., uprooted & down.

New BT: 38" Doug. Fir N.52°E. 22.5 ft. Mkd:  $\frac{1}{4}$  S1 CS BT.

No other tree available south of line.

6

South  $\frac{1}{4}$  Corner to Section 36, only.

(on N. Line Sec. 1, T22S R8W)

Found - Brass Cap set in 1952.

Sawed Stump of 52" Fir N.7°E. 30.4 ft., shows good scar.

(continued over)

7