

Douglas County Surveyor's Record of
Government Corners Renewed

T. 21 S. T. S. R. 8 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97196

(S. $\frac{1}{4}$ Section 36, only, continued)

Found - Burned Shell of 70" Fir N.40°E. 16.5 ft., no mks. remain.
No trace of 7" Hemlock mkd. in 1952.
New BT: 9" Maple N.37°E. 78.2 ft. Mkd: $\frac{1}{4}$ S36 CS BT.
No other trees available.

Section Corner to Sections 34 and 35, only. 8
(on N. Line of Sec. 2, T22S R8W)

Found - Brass Cap set in 1952 (under uprooted Fir 36" diam.)
7" Hemlock, now 10" N.78 $\frac{1}{2}$ °W. 23.1 ft. Tree alive & good cond.
55" Fir N.30°E. 29.7 ft., now stump, sawed off 2' abv. grd.
47" Fir N.35 $\frac{1}{2}$ °E. 60.7 ft., now a shattered snag.
New BT: 10" Hemlock N.7 $\frac{1}{2}$ °W. 68.0 ft. Mkd: T21S R8W S34 CS BT.
No trees available in Section 35.

Wit. Cor. to South $\frac{1}{4}$ Cor. to Sec. 34, only. 9
(on N. Line Sec. 3, T22S R8W)

Found - Brass Cap set in 1952.
Sawed Stump of 27" Fir N.54 $\frac{1}{2}$ °E. 25.7 ft., shows good scar.
No trace of N. W. Bearing Tree.
Fir Tree at $\frac{1}{4}$ cor., 2 ft. W. of Wit. Cor., alive & in good condition, shows good scars.
50" Fir S.21 $\frac{1}{2}$ °W. 27.1 ft., alive & in good condition, traces of bark scribing visible.
Stump of 35" Fir N.27 $\frac{1}{4}$ °E. 11.2 ft., bark scribing visible.
New BT: 12" Hemlock S.17°E. 15.2 ft., from Brass Cap, Mkd: $\frac{1}{4}$ S34 CS BT.
No live trees available north of line.
Corner lies on top of ridge, just south of S. edge of logging road.

Closing Corner Sections 4 and 3, T22-8W. #38
(on S. Line Sec. 33, T21S R8W)

Found - Brass Cap, 1945 survey, in ground - had obviously been recently reset, did not fit bear. or dist. to old BT's.
Reset Brass Cap in proper position from 2 old BT's.
54" Fir S.62°W. 25.1 ft., portion of old scribing visible on badly burned face.
32" Fir Stump, cut off approx. 8' above gr., S.11 $\frac{1}{4}$ °E. 17.2 ft., cut open & find good scribing "W" on old face.
Reblaze & Scribe 54" D. Fir S.62°W. 25.1 ft. Mkd: T22S R8W CC S4 CS BT.
New BT's: 48" Fir Stump N.32°E. 78.2 ft. Mkd: T22S R8W CC S3 S4 CSBT.
No live trees available.
Note - from corner as reset by Godfrey, the position where brass cap was found bears N.38 $\frac{1}{2}$ °W. 14.5 ft.

Township Corner

T21S
R9W $\frac{S36}{S11S6}$ R8W
T22S

FD OK V. McLind 10/97 M127-77 11

Found - Brass Cap set by Cadastral Survey of 1945, bulldozed out & buried in ground, lying across corner position.
38" Fir Stump N.12 $\frac{1}{2}$ °W. 12.5 ft.
48" Fir Stump S.18 $\frac{1}{2}$ °E. 18.5 ft.
38" Fir Stump N.36°E. 107.6 ft.
36" Fir Stump N.37°E. 34.3 ft., no scribe marks found.
No trace of other old Bearing Trees.
Reset - Gov't Brass Cap in proper position.
Rescribe: 38" Fir Stump N.12 $\frac{1}{2}$ °W. 12.5 ft. "T21S R9W S36"
No live trees available.

Milo E. Godfrey, Deputy County Surveyor
 Wm. Stoffel and Mike Stone
 September 1963
 C. S. File No. 52/14