

Douglas County Surveyor's Record of
Government Corners Renewed

T. 21 S. T. S. R. 8 W. R. W. W. M.

KOKE-CHAFFMAN CO., EUGENE, ORE. 97101

Vernon "Ray" Tracy
Jack Heritage & E. West
July 31, 1967
C. S. File No. 54/67

Witness Corner to Secs. 3 & 2, T21-SW. & Secs. 34 & 35, T20-SW. 12
Found - 1950 Cadastral Brass Cap, firmly set with steel fence post alongside & burned stumps of BT's.
We go 75 ft. south for witness corner & reset Cadastral Brass Cap and steel fence post alongside, now marked:
W.C. 75 ft. N. to Cor. T20S R&W $\frac{S}{S} \frac{34}{3} \frac{S}{S} \frac{35}{2}$
T21S R&W $\frac{S}{S} \frac{3}{3} \frac{S}{S} \frac{2}{2}$
New BT's: 54" D. Fir Stump N. 30° E. 7.5 ft. mkd. W.C. T20S R&W S35 CS BT.
48" D. Fir Stump S. 47° E. 28.4 ft. mkd. W.C. T21S R&W S2 CS BT.
60" D. Fir Stump N. 51° W. 27.6 ft. mkd. W.C. T20S R&W S34 CS BT.
Note - The old position of this corner was near centerline of new logging access road to be constructed. This witness corner lies on S.W. slope of ridge S.W. of proposed road junction. Sec #13

MICROFILM TO HERE 10/67

New - Witness Corner to Sections 3 & 2, T21-SW. and Secs. 34 & 35, T20-SW. 13
Move Witness Corner set in July, 1967, See-~~Ren.~~ #12, above, from its location 75 ft. south of true corner, 20 ft. N., or 55 ft. S. of true corner location.
New BT's: 12" Hemlock Stump N. 38° W. 6.7 ft. mkd. W.C. T20SR&W S34 CS BT.
18" Hemlock Stump N. 12° E. 10.5 ft. mkd. W.C. T20SR&W S35 CS BT.
14" Hemlock Stump S. 88° E. 6.4 ft. mkd. W.C. T21SR&WS 2 CS BT.
Nothing available in Section 3.
Reset - Steel Fence post alongside Brass Cap.
Note - This Witness Corner lies in "Y" of new logging roads on top of ridge. We obliterate scribe on BT. stumps mkd. in July, 1967. 10/31/67

Vernon "Ray" Tracy
Jack Heritage & V. Perron
April & May, 1968
C. S. File No. 54/67

$\frac{1}{4}$ Corner to Sections 24 and 25. 14
Found - 1952 GLO Brass Cap, properly marked.
40" Fir, now burned out shell of stump, N. 58 $\frac{1}{2}$ ° E. 37.0 ft.
41" Fir, now stump, tipped out, S. 28 $\frac{1}{2}$ ° E. 31.7 ft., shows good scar.
New BT's: 9" Hemlock N. 72° W. 37.4 ft. mkd. " $\frac{1}{4}$ S24 CS BT".
7" Hemlock S. 12° E. 54.1 ft. mkd. " $\frac{1}{4}$ S25 CS BT".

$\frac{1}{4}$ Corner to Sections 25 and 36. 15
Found - No trace of 1952 GLO Brass Cap, apparently destroyed by road construction.
35" W. Fir, now stump, S. 64° E. 48.8 ft., scribe visible on burned blaze. Rescribed " $\frac{1}{4}$ S36 CS BT".
Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1968 T 21 S R 8 W $\frac{1}{4} \frac{S}{S} \frac{25}{36}$
No trees close. Steel Fence Post with yellow line tag bears west 44.0 ft. Corner lies on east side of road at foot of fill & west edge of creek, course S. 30° W. 4/23/68

$\frac{1}{4}$ Corner to Section 13 and 24. 16
Found - 1954 GLO Brass Cap, bent over. Straighten & Reset.
Orig. 33" Cedar, now burned out stump, S. 18° W. 27.7 ft.
1954- 23" Cedar, now burned snag, S. 34 $\frac{1}{4}$ ° W. 14.5 ft., scribe visible on burned blaze. Rescribed " $\frac{1}{4}$ S24 CS BT".
New BT's: 7" Hemlock N. 29° W. 78.3 ft. mkd. " $\frac{1}{4}$ S13 CS BT".
No live trees S. of corner which lies on gentle south slope in logged area.

Section Corner to Sections 13 - 14 - 23 - 24. 17
Found - 1954 GLO Brass Cap, properly mkd.
Orig. 55", now 60" Fir, almost dead, N. 30° W. 17.8 ft., shows good scar.
Orig. 60" Fir Stump, burned, S. 75° W. 17.8 ft., no scribe found.
All other BT's. destroyed by logging.
New BT's: 26" Fir Stump S. 33° E. 34.7 ft. mkd. "T21S R&W S24 CS BT".
48" Fir Stump S. 26° W. 35.3 ft. mkd. "T21S R&W S23 CS BT".
Note - Set 6 ft. Steel Fence Post alongside Brass Cap. This corner lies approx. 450 ft. N. of Paradise Creek Access Road in reproduction of D. Fir & Hemlock. 5/6/68