

Douglas County Surveyor's Record of  
Government Corners Renewed

21 T.S. 8

R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 31881

L.E. Monrean  
P.L. Earle  
C.S. 57/36  
10/29/75

JAN 76  
JAN 78  
1-79

Stephen J. Flause  
Deputy, Doug. Co.  
Surveyors Office  
Karen Mosely  
April 13, 1981  
C.S. 61/19

Section Corner for Section 12 & 13 T 21,R8. and Sec.7 & 18 T 21,R7 24  
Found: G.L.O. 1954 Brass Cap properly Marked.  
13" now 15" Dia. Hemlock stump, bears N48°E., 19.0 ft. (Record 19.8 ft.)  
has good blaze.  
10" now 11" dia. Hemlock stump, bears S58°E., 24.2 ft. (Record 25.1 ft.)  
has good blaze.  
38" Fir stump bears S 56 1/2°W., 13.9 ft. Has good blaze.  
8" now 12" Hemlock stump bears N 59 1/2°W., 19.7 Ft. (Record 19.4 ft.)  
I open portion of blaze and find good scribing "S 12 BT"  
Note: Bark has been removed from all bearing tree stumps and a preservative  
has been applied. Stumps have been capped with aluminium sheet metal and  
are tagged.  
Renewal: A cedar, 7 1/2" dia. bears S 27 1/2°W., 45.6 ft. Scribed "T 21 S R8W  
S 13 CS BT" Tree is growing out from the N NE side of 52" dia. fir  
stump. Large blaze is 5 ft. above ground, bearing and distance were  
recorded from the height described. No other B.T.'s were scribed as cor.  
lies in clear cut area 10/29/75

1/4 Corner for Sections 4 and 9 25  
Found - A 1945 GLO brass cap properly mkd. on a 1"x30" I.P. lying loose on  
ground surface. A red painted steel fence post nearby protrudes  
42" from ground; a check of the bearing & distance to orig.  
southwest bearing tree reveals that fencepost does not mark corner  
position.  
Accessories bearings and distances are check from corner position as  
determined from southwest bearing tree.  
An orig. fir, 16" now a 42" DBH D. fir bears S.10°W., 12.5 ft. Tree  
is opened to search for 1945 rescribing. Blaze found is opened to  
see scribing 1/4.  
An orig. Cedar, 28" is now a downed cedar 50". Center of uproot  
hole agrees reasonably well with record bearing & distance. This  
cedar has fallen with blaze marks hidden.  
A 22" fir, now a 32" 8 ft. long tipped out stump has uproot hole  
which agrees reasonable well with record bearing and distance.  
This fir stump also has tipped over on its face and no blaze  
marks are found. (1945 dependent resurvey)  
Set - Because of good condition of orig. southwest bearing tree, the GLO  
brass cap monument is set the record bearing and distance from  
this tree. WE ADD reset marks to cap: US General Land Office  
Survey RESET 1/4 S4 S9 DCSO 1981 1945" Cap protrudes 1"  
from ground. Red fence post is set on south side of cap and  
protrudes 44" from ground.  
New BT's- A 12" DBH D. fir bears N.53°W., 38.1 ft. and is scribed 1/4 S4  
CS BT on a double blaze.  
A7" DBH Hemlock bears N.24 1/4°W., 13.9 ft. & is scribed 1/4 S4 CS  
BT as a bark scribe.  
The new bearing trees and the orig. southwest bearing tree are tagged with  
DCSO BT tags.

4/13/81

Sec. corner for Sec's. 1, 2, 11, & 12. 26  
Found - Brass Cap (GLO) 1954 - 1960 RESURVEY.  
BT's - 26" Cedar bears S.72°W., 61.4-ft. (scribe visible). 1883 BT  
11" Fir bears N.1°E., 5.0-ft. (scar visible). 1954 BT  
22" Hemlock bears S.9°E., 23.4-ft. (scar visible) 1954 BT  
30" Fir bears N. 44° E., 42.5-ft. (scar visible) 1954 BT  
6/26/81

Sec. corner for Sec's. 11, 12, 13, & 14. 27  
Found - Brass Cap (GLO) 1954 - 1960 RESURVEY.  
BT's - 12" Maple bears South, 35.0-ft. (no scar) 1883 BT  
20" Maple bears N.48°E., 20.4-ft. (scar visible) 1883 BT  
68" Fir stump bears N.76 1/2 °W., 22.2-ft. (scar vis.) 1883 BT  
24" Fir bears S.13°W., 56.7-ft. (scar visible) 1954 BT  
29" Hemlock bears S.38°E., 75.0-ft. (scribe vis.) 1954 BT  
46" Cedar bears N.28 1/2 °W., 62.0-ft. (scribe vis.) 1954 BT  
6/26/81

Les Roberts  
For: International Paper Co.  
June 26, 1981  
M 88 - 22