

Douglas County Surveyor's Record of
Government Corners Renewed

T.21S. T. S. R.8W. R.W.W.M.

KORE-CHAPMAN CO., EUGENE, ORE. 21991

LES ROBERT
Feb. 10, 1997
M 124- 44 &
C.S. 65/12-5 A&B

North $\frac{1}{4}$ cor. sec. 4 only 51
Mon. Set- 3/4" X 24" Alum. rod with 3" Alum. cap
New Bt's- 6" Fir, N.17°E., 10.7' (scribed/painted yellow)
12" Fir, S.53°E., 8.5' (scribed/painted yellow)
12" Fir, S.06°W., 10.8' (scribed/painted yellow)
18" Alder, N.45°W., 36.7' (bark scribed/painted yellow)
(1" Iron Pipe, bears S.79°19'E., 89.34 - No Record)

Standard sec. corner to secs. 32 & 34 52
Mon. Set - "PK" Nail in steep rock face using data of record from
1975 Dougals Co. survey see C.S. 57/34.
Bt's Fd. - 12" Alder, N.55°W., 34.7' (scribe visible) 1975 B.T.
16" Fir, N.51°E., 23.6' (scar vis.), 1975 B.T.
see previous ren. # 23

RE-RENEWED CORNER NO. # 56

CLOSING COR. SECS. 3 & 4 53
Mon. Fd. - 1945 GLO Iron pipe and Brass cap
Bt's Fd. - 48" Fir, S.62°W., 24' (scar vis.), 1881 B.T.
6" Fir, N.9°W., 29.1' (scar vis.), No record
10" Fir, S.51°E., 18.4' (scar vis.), no record
Mon. Set - 3/4" X 36" Alum. rod with 3" Alum cap at true point of
intersection, 1945 BLM Brass cap bears S.1°28'15" W.,
8.45'. see previous ren. # 38

South Sec. Cor. to 32 & 33 only 54
Mon. Fd.- 2 $\frac{1}{2}$ " dia. Brass cap on a 2" O.D. Iron pipe, protrudes 12"
above ground. (1945).
Bt's Fd.- No OBT's Found
36" dia. now 38" dia. down D.Fir, bears N.45 $\frac{1}{2}$ °E., 35'
(agrees with 1965 renewal).
6" now 18" dia. 2 $\frac{1}{2}$ " High Cedar stump with a healed blaze,
bears N.70°W., 36.3' (agrees with 1965 renewal).
23" now 30" dia. D.Fir with a fully healed single blaze,
bears N.53°E., 43.6' (rec. N.47°E., 43.6' possible
compass reading error) 1965.
New Bt's- 20" dia. W.Fir double blazed and scribed "T21S R8W S32 CS
BT", bears N.47°W., 14.6'.
10" dia. Maple double blazed and scribed "T21S R8W S33 CS
BT", bears N.60°E., 20.2'.
16" dia. W.Fir double blazed and scribed "T21S R8W S33 CS
BT", bears N.80°E., 69.3'.
Corner lies on a steep southerly slope in a slide area.

South $\frac{1}{4}$ Sec. 33 Only 55
Mon. Fd.- 2 $\frac{1}{2}$ " dia. Brass cap on a 1" O.D. iron pipe protrudes 9"
above ground. (1945)
Bt's Fd.- 20" now 62" dia. D.Fir with a healed double blaze, bears
N.80°W., 160.5' (Rec. N.80°W., 158.4' dist. is a good
face measurement) OBT.
16" now 28" dia. D.fir with a healed double blaze, bears
N.65 $\frac{1}{2}$ °W., 170.9' (agrees 1945 rec.)
New Bt's- 14" dia. D.Fir double blazed and scribed " $\frac{1}{4}$ S33 CS BT",
bears N.72 $\frac{1}{2}$ °E., 13'.
21" dia. D.Fir double blazed and scribed " $\frac{1}{4}$ S33 CS BT",
bears N.16°W., 5.2'.

Douglas County Surveyors Office
Randall Smith & Stephen Flause
Mar. 13, 1997
C.S. 64/71-20 & 21