

Douglas County Surveyor's Record of
Government Corners Renewed

T. 21 S. T. S. R. 9 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Center 1/4 Corner Section 10.

Set - 5/8" Iron Rod

Location Sign on 20" Hemlock which bears

N.22°W. 7.6 feet

8/30/72

Hintz, R. J.
For: B.L.M.
Map File
M 46-58

RE-RENEWED SEE CORNER NO. 57 18

1/4 Corner Sections 28 & 33.

Found - 8" Orig. D. Fir, now snag, S.67 1/2°E., 11.9 ft. Opened Scribe visible "1/2"s".

12" D. Fir, now 14", S.39°E., 24.0 ft. Shows good scribe. Ren. # 1

14" Hemlock, now 18", N.23 1/2°E., 18.0 ft. scribe visible

Set - Brass Cap at 1/4 cor. mkd: County Surveyors T 21 S R 9 W

Office

1972

1/4 S 28

S 33

John Powell
J. Heritage
C.S. 53/66
10/3/72

All bearing trees OK; Tagged same.

10/3/72

EAST 1/4 Corner, Section 25 only, T21-10.

Found - 1919 GLO Brass cap at 1/4 Corner.

16" Hemlock, now down, S.20°W., 35.0 ft.

12" D. Fir, now 39", N.65°W., 33.0 ft. Shows good scar.

New BT - 8" Hemlock, N.44°W., 34.8 ft. scribed 1/4 S25 CS BT.

3/28/73 R

WEST 1/4 Corner, Section 30 only.

Found - 1919 GLO Brass cap, broken off.

34" D. Fir, now stump, N.75 1/2°E., 21.8 ft. Shows good scar.

58" D. Fir, now down, S.20°E., 17.8 ft. Shows scar.

Set - Brass cap along side old pipe mkd. County Surveyors T 21 S

Office

1973

R

R

10 1/4 S30

W

9

W

New BT's - 7" D. Fir, N.60°E., 5.0 ft. Scribed 1/4 S30 CS BT.

22" Hemlock, S.62°W., 25.0 ft. scribed 1/4 CS BT.

Note - There were no other good trees to the east for BT's. Old logged unit. BT tag mkd. for 1/4 S30 only on SW BT.

3/28/73 R

John M. Powell
J. Heritage
C. S. File 56/25
March 28, 1973

Fd. 12/89
L. Roberts
M 109-42

Sec. Corner, Sections 19 and 30 only, T21-8.

Found - 1945 GLO Brass cap properly mkd.

52" Fir stump, burnt, S.20°E., 89.1 ft. Shows part of face.

54" Fir stump, burnt, N.17 1/2°E., 237.6 ft.

New BT's - 5" D. Fir, N.54°E., 7.3 ft. Scribed S19 CS BT.

5" D. Fir, S.59°E., 19.1 ft. Scribed S30 CS BT.

Note - This corner lies in old clear cut very brushy. Also lies on westerly slope.

5/11/73 R

Sec. corner, Sections 24 and 25 only.

Found - 1945 GLO Brass Cap C.C. properly mkd.

26" Fir stump, N.80°E., 63.4 ft. Open for scribing B.T.

48" Fir stump, N.33°W., 143.9ft.

1" Iron pipe along side of Brass cap.

New BT's - 6" D. Fir, N.31°W., 11.3 ft. Scribed S24 CS BT.

8" D. Fir, South, 29.9 ft. Scribed S25 CC CS BT.

Note - This corner lies in old clear cut, very brushy. A lot of new growth. It lies on westerly slope approx. 60 ft. westerly of ridge top.

5/11/73 R

1/4 Corner for Sec. 6 only. South line.

Found - 1966 U.S. BLM Cadastral brass cap properly mkd. with a sandstone alongside with a "1/4" chiseled on the north face. Both monuments were buried under road excavation material.

BT's - 25" now 30" D. Fir bears N.52°E., 117.5 ft. with a well healed blaze.

The NW BT, a hemlock marked in 1966, has since fallen and slid approx. 30 ft. downhill.

New BT - A 14" D. Fir bears N.72°W., 47.4 ft. scribed "1/4 S6 CS BT.

Note - This corner lies on very steep slope, approx 100' north of and 50 ft. lower than a gravel surfaced logging road.

Gary Langlitz
Pete Earle
C.S. 56/49
March 14, 1974

John M. Powell, County Surveyors Office
G. Commons
May 11, 1973
C.S. 56/25